

## CHICKAMIN BARGE




Starboard Side




Port Side





Aluminum Staircase - Fix bent outside rib on bottom stair




Forward Deck



Forward – Visible 1000 lb anchor, zodiac liferafts, two winches, crane/boom and mast





Aft – Bent handrail to be corrected. Also shown is a capstan and two winches.




Forward rotting plywood deck



Example: A similar barge with desired aluminum decking (minus the vegetation)





Aft Upper Exterior Deck to be replaced with aluminum decking.



Aft side of barge







Main Hatch has rust around lip observed



Hatch lid to be repainted and seal replaced



## First Zodiac Liferaft



## Second Zodiac Liferaft





Main Hatch



Spot paint areas of rust in main compartment





Spot paint areas of rust in main compartment



Forward compartment



Areas of rust in generator/aft compartment