



052738

OF

INSPECTORS: FRANCIS BOSSARD

LOCATION: 3355 La Jolla Village Drive San Diego CA

Below

ENR 08P Literary Services 19700 Valley View Avenue Suite 100 La Mirada California 90638

Office 714 523-9811 • Fax 714 523-9810

Z:\Public\FORAN\Feld Forms\Bulk Sample Forms

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052731 Project Number: P14320 . V11  
Sampled Date: 11/12/2014 Date Received: 11/18/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 11/18/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION			Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color	Material			
407071	1	5TH FLOOR	WHITE / BEIGE	2' x 2' FISHER CEILING TILES	FR	NONE DETECTED	50% CELLULOSE 10% GLASS WOOL 40% MATRIX
407072	2	5TH FLOOR	WHITE / BEIGE	2' x 2' FISHER CEILING TILES	FR	NONE DETECTED	50% CELLULOSE 10% GLASS WOOL 40% MATRIX
407073	3	5TH FLOOR	WHITE / BEIGE	2' x 2' FISHER CEILING TILES	FR	NONE DETECTED	50% CELLULOSE 10% GLASS WOOL 40% MATRIX
407074	4	5TH FLOOR	GREEN / WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
407075A	5	5TH FLOOR	GREEN / WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
407075B	5	5TH FLOOR	BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407076A	6	5TH FLOOR	WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
407076B	6	5TH FLOOR	BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407077A	7	5TH FLOOR	WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE, STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052731  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407077B	7	5TH FLOOR		BEIGE	JOINT COMPOUND	NF	2% CHRYSOTILE	98% MATRIX
407078A	8	5TH FLOOR		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX
407078B	8	5TH FLOOR			JOINT COMPOUND	NF	SFP	
407079A	9	5TH FLOOR		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX
407079B	9	5TH FLOOR			JOINT COMPOUND	NF	SFP	
407080A	10	5TH FLOOR		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
407080B	10	5TH FLOOR		YELLOW / BROWN	GLUE	NF	NONE DETECTED	100% MATRIX
407081A	11	5TH FLOOR		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
407081B	11	5TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200879-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 · FAX (714) 523-9810 · MAIN@ENCORP.NET · WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052731  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 · V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

**BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples**

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407082A	12	5TH FLOOR		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
407082B	12	5TH FLOOR		YELLOW / BROWN	GLUE	NF	2% CHRYSOTILE	98% MATRIX
407083A	13	5TH FLOOR		TAN	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
407083B	13	5TH FLOOR		CLEAR	GLUE	NF	NONE DETECTED	100% MATRIX
407084A	14	5TH FLOOR		TAN	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
407084B	14	5TH FLOOR		CLEAR	GLUE	NF	NONE DETECTED	100% MATRIX
407085A	15	5TH FLOOR		TAN	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
407085B	15	5TH FLOOR		CLEAR	GLUE	NF	NONE DETECTED	100% MATRIX
407086A	16	5TH FLOOR		WHITE	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878.0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052731  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION			Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color	Material			
407086B	16	5TH FLOOR	YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407087A	17	5TH FLOOR	WHITE	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
407087B	17	5TH FLOOR	WHITE	GLUE	NF	NONE DETECTED	100% MATRIX
407088A	18	5TH FLOOR	WHITE	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
407088B	18	5TH FLOOR	WHITE	GLUE	NF	NONE DETECTED	100% MATRIX
407089A	19	5TH FLOOR	BLUE	12" x 12" VCT	NF	NONE DETECTED	100% MATRIX
407089B	19	5TH FLOOR	BLACK	GLUE	NF	3% CHRYSOTILE	97% MATRIX
407090A	20	5TH FLOOR	WHITE	12" x 12" VCT	NF	3% CHRYSOTILE	97% MATRIX
407090B	20	5TH FLOOR	GLUE	SFP			

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052731 Project Number: P14320 V11  
Sampled Date: 11/12/2014 Date Received: 11/18/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 11/18/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non- Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407091A	21	5TH FLOOR		YELLOW	12" x 12" VCT	NF	NONE DETECTED	100% MATRIX
407091B	21	5TH FLOOR			GLUE		SFP	
407092	22	5TH FLOOR		BROWN	WOOD DESIGN LINOLEUM	NF	NONE DETECTED	100% MATRIX
407093	23	5TH FLOOR		BROWN	WOOD DESIGN LINOLEUM	NF	NONE DETECTED	100% MATRIX
407094A	24	5TH FLOOR		BROWN	WOOD DESIGN LINOLEUM	NF	NONE DETECTED	100% MATRIX
407094B	24	5TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407095A	25	5TH FLOOR		WHITE	12" x 12" SPECKLES	NF	NONE DETECTED	100% MATRIX
407095B	25	5TH FLOOR		BLACK / YELLOW	GLUE	NF	2% CHRYSOTILE	98% MATRIX
407096A	26	5TH FLOOR		WHITE	12" x 12" SPECKLES	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052731  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407096B	26	5TH FLOOR			GLUE	SFP		
407097A	27	5TH FLOOR	WHITE	12" x 12" SPECKLES	NF	NONE DETECTED	100% MATRIX	
407097B	27	5TH FLOOR			GLUE	SFP		
407098A	28	5TH FLOOR	GREEN	LINOLEUM	NF	NONE DETECTED	3% CELLULOSE 3% FIBROUS GLASS 3% SYNTHETIC FIBERS 91% MATRIX	
407098B	28	5TH FLOOR	YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX	
407099A	29	5TH FLOOR	GREEN	LINOLEUM	NF	NONE DETECTED	3% CELLULOSE 3% FIBROUS GLASS 3% SYNTHETIC FIBERS 91% MATRIX	
407099B	29	5TH FLOOR	YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX	
407100A	30	5TH FLOOR	GREEN	LINOLEUM	NF	NONE DETECTED	3% CELLULOSE 3% FIBROUS GLASS 3% SYNTHETIC FIBERS 91% MATRIX	
407100B	30	5TH FLOOR	YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052731  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

### SAMPLE DESCRIPTION

Sample Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
---------------	----------------------	--------------------------	-------	----------	------------------------	------------------	------------------

APPROVED SIGNATURE:

Elaine Espique 11/18/14  
Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

05273!

CLIENT: Department of Veterans Affairs

DATE: 11-12-14

PAGE: 1

OF 3

JOB NO: P14320-VAF

INSPECTORS: Francisco Barrera

LOCATION: 5th Floor

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407071	5th Floor	2x2 Fiber Ceiling Tiles	g	1	40% beige- 50% (2) 10% Moss (6/21)
2.	407072	↓	↓	↓	↓	ND
3.	407073	↓	↓	↓	↓	ND
4.	407074	↓	Paste	g	1	exp. calc Green white ND
5.	407075	↓	↓	↓	↓	A Green white B Plaster Pink ND
6.	407076	↓	↓	↓	↓	A White ND B Plaster-Purple ND
7.	407077	↓	Drywall	g	1	A Drywall 1/2" Fiberglass ND B Blue 2" Fiberglass ND
8.	407078	↓	↓	↓	↓	A Drywall 1/2" Fiberglass ND B SP12 ND
9.	407079	↓	↓	↓	↓	A Drywall 1/2" Fiberglass ND B SP12 ND
10.	407080	tan basecoat 5th floor	tan basecoat Floor	g	1	A basecoat tan ND B blue-yellow brown ND

CHAIN OF CUSTODY

Sampled By: Francisco Barrera 11-12-14

Relinquished/Received By: Francisco Barrera 11-12-14

Relinquished/Received By: Francisco Barrera 11-12-14

Received: 11-12-14 1000

Received: 11-18-14 0910

ABBREVIATIONS:

OTHER: S.F. = Square Feet, L.F. = Linear Feet

CONDITION: G = Good, D = Damaged, SD = Significantly Damaged

TYPES OF MATERIALS: S = Surface Material, TS = Thermal Systems Insulation, M = Miscellaneous Material

Comments/Special Instructions:



# ENCORP FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT 052731

CLIENT: Department of Veterans Affairs DATE: 11-12-14 PAGE: 2 OF 3

JOB NO: P1430011 INSPECTORS: Francisco Barroza

LOCATION: 5th Floor

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407081	↓	↓	↓	1	A) Positive tan ND
2.	407082	↓	↓	↓	1	B) Blue-Yellow ND
3.	407083	5th Floor	tan 12x12 vt/green brown speckles	g	1	A) Positive tan ND
4.	407084	↓	↓	↓	1	A) Positive tan ND
5.	407085	↓	↓	↓	1	A) Positive tan ND
6.	407086	5th Floor	white 12x12 vt/yellow brown speckles	g	1	A) Positive tan ND
7.	407087	↓	↓	↓	1	A) Positive tan ND
8.	407088	↓	↓	↓	1	A) Positive tan ND
9.	407089	5th Floor	Blue/Yellow 12x12 vt/gre	g	1	A) Positive tan ND
20.	407090	↓	↓	↓	1	A) Positive tan ND

ABBREVIATIONS:

Types of Materials:

3 = Surface Material  
TSI = Thermal Systems Insulation  
M = Miscellaneous Material

Condition:

G = Good  
D = Damaged  
SD = Significantly Damaged

Other:

S.F. = Square Feet  
L.F. = Linear Feet

Comments/Spec. Instructions:

Chain of Custody:

Sampled By: Francisco Barroza Date/Time: 11-12-14

Relinquished/Received By: Francisco Barroza Date/Time: 11-12-14

Relinquished/Received By: Received Date/Time: 11/17/14 1600

Office (714) 523-9811 Fax (714) 523-9810

ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 - La Mirada, California 90638

ZAPUBKFORMANField Form/Current Field Forms/Blank Sample Forms

CLIENT: Department of veterans affairs

DATE: 1-2-14

**PAGE:**

9



30

JOB NO: 0430111

INSPECTORS: FRANCO

LOCATION: STAFFORD

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	407991	I	I	I	I	A) VCT-Yellow - ND B) SFP
2.	407992	5th Floor	Brown wood Design Unbleum	D	I	Brown ND
3.	407993	I	I	I	I	NN
4.	407994	I	I	I	I	A) Pine-Brown ND B) Pine Yellow ND C) PZ-White
5.	407995	5th Floor	white PZ12 light Blue/Dark blue speckles	G	I	C) Pine-Black Yellow 21(ND) D) White ND
6.	407996	I	I	I	I	D) SFP ND
7.	407997	I	I	I	I	A) White ND D) SFP
8.	407998	5th Floor	green unbleum	G	I	A) Green 31(ND) 51(Sy) 16(ND) B) Pine-Yellow ND
9.	407999	I	I	I	I	A) ND B) ND C) ND
30.	407100	I	I	I	I	A) ND B) ND C) ND

ABERRATIONS:			CHAIN OF CUSTODY	
TYPES OF MATERIALS:	CONDITION	OTHER:	Sampled By:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	SF = Square Feet LF = Linear Feet	Francisco Baraza	11-12-14
			Francisco Baraza	11-17-14
			Received By: 	11-17-14 1600
			Received: 	11-18-14 0710
Comments/special Instructions:				

ENCORP Laboratory Services 16700 Valley View Avenue, Suite 100 La Mirada California 90638

Office (714) 523-9811 Fax (714) 523-9810

Z:\Public\FORMA\Feld Form\Current Field Forms\Bulk Sample Form



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 · FAX (714) 523-9810 · MAIN@ENCORP.NET · WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052774  
Sampled Date: 12/3/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 · V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407530	1	6TH FLOOR		WHITE / BEIGE	2' x 4' CEILING TILES	FR	NONE DETECTED	50% CELLULOSE 20% GLASS WOOL 30% MATRIX
407531	2	6TH FLOOR		WHITE / BEIGE	2' x 4' CEILING TILES	FR	NONE DETECTED	50% CELLULOSE 20% GLASS WOOL 30% MATRIX
407532	3	6TH FLOOR		WHITE / BEIGE	2' x 4' CEILING TILES	FR	NONE DETECTED	50% CELLULOSE 20% GLASS WOOL 30% MATRIX
407533	4	6TH FLOOR		WHITE	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
407534	5	6TH FLOOR		WHITE	MUD / TAPE	NF	2% CHRYSOTILE	98% MATRIX
407535A	6	6TH FLOOR		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 94% MATRIX
407535B	6	6TH FLOOR			MUD / TAPE		SFP	
407536	7	6TH FLOOR		WHITE	PLASTER	NF	NONE DETECTED	100% MATRIX
407537A	8	6TH FLOOR		WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052774  
Sampled Date: 12/3/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407546B	17	CORRIDORS		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407547A	18	CORRIDORS		BEIGE	VCT 12" X 12" SPECKLES	NF	NONE DETECTED	100% MATRIX
407547B	18	CORRIDORS		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407548A	19	ROOM 6014		WHITE / BLUE	12" x 12" SPECKLES	NF	NONE DETECTED	100% MATRIX
407548B	19	ROOM 6014		BLACK	MASTIC	NF	3% CHRYSOTILE	97% MATRIX
407549A	20	ROOM 6014		WHITE / BLUE	12" x 12" SPECKLES	NF	NONE DETECTED	100% MATRIX
407549B	20	ROOM 6014			MASTIC		SFP	
407550A	21	ROOM 6014		WHITE / BLUE	12" x 12" SPECKLES	NF	NONE DETECTED	100% MATRIX
407550B	21	ROOM 6014			MASTIC		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052774 Project Number: P14320 . V11  
Sampled Date: 12/3/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non- Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407551A	22	6TH FLOOR		TAN	6" BASECOVE	NF	NONE DETECTED	100% MATRIX
407551B	22	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407552A	23	6TH FLOOR		TAN	6" BASECOVE	NF	NONE DETECTED	100% MATRIX
407552B	23	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407553A	24	6TH FLOOR		TAN	6" BASECOVE	NF	NONE DETECTED	100% MATRIX
407553B	24	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407554A	25	6TH FLOOR		GRAY / PINK / RED	CARPET	NF	NONE DETECTED	60% SYNTHETIC FIBERS 40% MATRIX
407554B	25	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407555A	26	6TH FLOOR		GRAY / PINK / RED	CARPET	NF	NONE DETECTED	60% SYNTHETIC FIBERS 40% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052774  
Sampled Date: 12/3/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						

407555B	26	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407556A	27	6TH FLOOR		GRAY / PINK / RED	CARPET	NF	NONE DETECTED	60% SYNTHETIC FIBERS 40% MATRIX
407556B	27	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX

APPROVED SIGNATURE:

  
Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

CLIENT: Veterans Administration SA DATE: 12/3/14 PAGE: 1 OF 3  
 JOB NO: P14320-VI1 INSPECTORS: Francisco Barrera cost 07-442  
 LOCATION: 3250 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407530	6th Floor	2x2 ceiling tiles	G		white beige 50% cell 20% fiberglass/
2.	407531					ND
3.	407532					ND
4.	407533		Drywall / tape			white and tape ND
5.	407534					white 2/4 dry tape
6.	407535					A Drywall - white ND B GYP
7.	407536		Plaster			white ND
8.	407537					A top coat white ND B plaster beige ND
9.	407538					white ND
10.	407539		white/black speckles yellow blue vet 12x12			A VCT-Brown ND B Mastic-Black s/GHP

## CHAIN OF CUSTODY

Sampled by: Francisco Barrera 12/4/14 Date/Time:  
 Relinquished/Received By: Francisco Barrera 12/4/14 Date/Time:  
 Relinquished/Received By: Francisco Barrera 12-4-14 0715 Date/Time:

## ABBREVIATIONS

OTHER: S.F. = Square Feet  
L.F. = Linear Feet

CONDITION: G = Good  
D = Damaged  
SD = Significantly Damaged

S = Surface Material  
TSI = Thermal Systems Insulation  
M = Miscellaneous Material

Comments/Special Instructions:



# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052774

CLIENT: Veterans Administration SA DATE: 12/3/14 PAGE: 2 OF 3  
 JOB NO: P14320.VII INSPECTORS: Francisco Barrera cost 07-14-14  
 LOCATION: 3350 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407540	6th Floor	L	1	1	4) VCT-unzue - NO 5) SFP
2.	407541					4) VCT-yellow - NO 5) SFP
3.	407542		4" Basecoat + glue	9		4) Tan NO 5) Gtue-yellow - NO
4.	407543					4) NO 5) NO
5.	407544					4) NO 5) NP
6.	407545	cardos	tan vct 12x12 brown/green speckles	9	1	4) Blue Brown - NP 5) Range - NO 6) Blue-yellow - NO
7.	407546				1	4) NO 5) NO
8.	407547				1	4) NO 5) NO
9.	407548	Room 6014	white 12x12 light blue speckles/mastic	9		4) White Blue - NO 5) Mastic-Black 3/16" NO 6) White Blue - NO 7) SFP
20.	407549				1	

CHAIN OF CUSTODY

Abbreviations: COND: CONDITION OTHER: OTHER S.F. = Square Feet L.F. = Linear Feet G = Good D = Damaged SD = Significantly Damaged

Types of Materials: SI = Surface Material TI = Thermal Systems Insulation M = Miscellaneous Material

Sampled By: Francisco Barrera Date/Time: 12/4/14  
 Rechecked/Received By: Francisco Barrera Date/Time: 12/4/14  
 Rechecked/Received By: Francisco Barrera Date/Time: 12/4/14

# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052774

CLIENT: Veterans Administration SA DATE: 12/3/14 PAGE: 3 OF 3  
 JOB NO: P14320.VII INSPECTORS: Francisco Barrera cost 07-414  
 LOCATION: 3350 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	407550	L	L	L	L	ND
2.	407551	6th floor	6" grain Basecoat + glue	g		ND
3.	407552	L	L	L	L	ND
4.	407553	L	L	L	L	ND
5.	407554	L	car pet / glue	g		ND
6.	407555	L	L	L	L	ND
7.	407556	L	L	L	L	ND
8.						
9.						
30.						

ABREVIATIONS: S = Surface Material, TS = Thermal Systems Insulation, M = Miscellaneous Material, C = Concrete, S.F. = Square Feet, L.F. = Linear Feet, SD = Significantly Damaged, Comments/Special Instructions:

CHART OF CUSTODY: Sampled by: Francisco Barrera Date/Time: 12/4/14  
 Relinquished/Received By: Francisco Barrera Date/Time: 12/4/14  
 Relinquished/Received By: Francisco Barrera Date/Time: 12-4-14 0715

ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 - La Mirada - California 90638  
 Office (714) 523-9811 - Fax (714) 523-9810  
 7 Alhambra-Huntington Road, Suite 100, La Brea, CA 90038



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052834

Sampled Date: 12/19/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11

Date Received: 12/24/2014

Date Analyzed: 12/24/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408207	1	6TH FLOOR 6085		BLACK	FLOORING (CONCRETE)	NF	NONE DETECTED	100% MATRIX
408208	2	6TH FLOOR 6085		BLACK	FLOORING (CONCRETE)	NF	NONE DETECTED	100% MATRIX
408209	3	6TH FLOOR 6085		BLACK	FLOORING (CONCRETE)	NF	NONE DETECTED	100% MATRIX
408210	4	6TH FLOOR		WHITE / BROWN	2' x 4' FISHER CEILING TILE	FR	NONE DETECTED	50% CELLULOSE 10% GLASS WOOL 40% MATRIX
408211	5	6TH FLOOR		WHITE / BROWN	2' x 4' FISHER CEILING TILE	FR	NONE DETECTED	50% CELLULOSE 10% GLASS WOOL 40% MATRIX
408212	6	6TH FLOOR		WHITE / BROWN	2' x 4' FISHER CEILING TILE	FR	NONE DETECTED	50% CELLULOSE 10% GLASS WOOL 40% MATRIX
408213A	7	WOMENS ROOM (6040)		TAN	LINOLEUM	NF	NONE DETECTED	100% MATRIX
408213B	7	WOMENS ROOM (6040)		BLACK / YELLOW	MASTIC	NF	3% CHRYSOTILE	97% MATRIX
408214A	8	WOMENS ROOM (6040)		TAN	LINOLEUM	NF	NONE DETECTED	100% MATRIX

**NOTES:** ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 - FAX (714) 523-9810 - MAIN@ENCORP.NET - WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052834 Project Number: P14320 . V11  
Sampled Date: 12/19/2014 Date Received: 12/24/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/24/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non- Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408214B	8	WOMENS ROOM (6040)			MASTIC		SFP	
408215A	9	WOMENS ROOM (6040)		TAN	LINOLEUM	NF	NONE DETECTED	100% MATRIX
408215B	9	WOMENS ROOM (6040)			MASTIC		SFP	
408216A	10	WOMENS ROOM 6040		GREEN	4" BASECOVE	NF	NONE DETECTED	100% MATRIX
408216B	10	WOMENS ROOM 6040		BROWN / YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408217A	11	WOMENS ROOM 6040		GREEN	4" BASECOVE	NF	NONE DETECTED	100% MATRIX
408217B	11	WOMENS ROOM 6040		BROWN / YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408218A	12	WOMENS ROOM 6040		GREEN	4" BASECOVE	NF	NONE DETECTED	100% MATRIX
408218B	12	WOMENS ROOM 6040		BROWN / YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=Non Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 - FAX (714) 523-9810 - MAIN@ENCORP.NET - WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052834

Sampled Date: 12/19/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 - V11

Date Received: 12/24/2014

Date Analyzed: 12/24/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			
408219A	13	LAB 6045	WHITE	NF	2% CHRYSOTILE	98% MATRIX
408219B	13	LAB 6045	BLACK / YELLOW	NF	3% CHRYSOTILE	97% MATRIX
408220A	14	LAB 6045			SFP	
408220B	14	LAB 6045			SFP	
408221A	15	LAB 6044			SFP	
408221B	15	LAB 6044			SFP	
408222A	16	WEST WING	WHITE	NF	NONE DETECTED	7% CELLULOSE 93% MATRIX
408222B	16	WEST WING	WHITE	NF	3% CHRYSOTILE	97% MATRIX
408223A	17	6032 6TH FLOOR	GRAY	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052834  
Sampled Date: 12/19/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 12/24/2014  
Date Analyzed: 12/24/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408223B	17	6032 6TH FLOOR		BLACK / BROWN	MASTIC	NF	3% CHRYSOTILE	97% MATRIX
408224A	18	6032 6TH FLOOR		GRAY	EPOXY FLOORING	NF	NONE DETECTED	100% MATRIX
408224B	18	6032 6TH FLOOR			MASTIC		SFP	
408225A	19	6032 6TH FLOOR		GRAY	EPOXY FLOORING	NF	NONE DETECTED	100% MATRIX
408225B	19	6032 6TH FLOOR			MASTIC		SFP	
408226A	20	6076 6TH FLOOR		GRAY / BLACK	LINOLEUM	NF	NONE DETECTED	100% MATRIX
408226B	20	6076 6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408227A	21	6076 6TH FLOOR		GRAY / BLACK	LINOLEUM	NF	NONE DETECTED	100% MATRIX
408227B	21	6076 6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052834  
Sampled Date: 12/19/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 12/24/2014  
Date Analyzed: 12/24/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non- Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408228A	22	6076 6TH FLOOR		GRAY / BLACK	LINOLEUM	NF	NONE DETECTED	100% MATRIX
408228B	22	6076 6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408229	23	6170 EAST WING		BLUE / BEIGE	FLOORING	NF	NONE DETECTED	100% MATRIX
408230	24	6170 EAST WING		BLUE / BEIGE	FLOORING	NF	NONE DETECTED	100% MATRIX
408231	25	6170 EAST WING		BLUE / BEIGE	FLOORING	NF	NONE DETECTED	100% MATRIX
408232A	26	NORTH WING CORRIDOR		GREEN	12" x 12"	NF	NONE DETECTED	100% MATRIX
408232B	26	NORTH WING CORRIDOR		BLACK	MASTIC	FR	NONE DETECTED	3% SYNTHETIC FIBERS 97% MATRIX
408233A	27	NORTH WING CORRIDOR		GREEN	12" x 12"	NF	NONE DETECTED	100% MATRIX
408233B	27	NORTH WING CORRIDOR		BLACK	MASTIC	FR	NONE DETECTED	3% SYNTHETIC FIBERS 97% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

Client Name: Department of Veterans AffairsClient Address: 4811 Airport Plaza DriveLong Beach, CA 90815Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICALFacility Address: 3350 LA JOLLA VILLAGE DRIVESAN DIEGO, CALIFORNIA 92161Reference Batch Number: 052834Sampled Date: 12/19/2014Sampled By: FRANCISCO BARRAZAAnalyzed By: ELAINE ESPIQUEProject Number: P14320 . V11Date Received: 12/24/2014Date Analyzed: 12/24/2014

## LABORATORY TEST REPORT

## BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408234A	28	NORTH WING CORRIDOR		GREEN	12" x 12"	NF	NONE DETECTED	100% MATRIX
408234B	28	NORTH WING CORRIDOR		YELLOW	MASTIC	NF	NONE DETECTED	100% MATRIX
408235A	29	NORTH WING		TAN	12" x 12" SMALL SPECKLES	NF	NONE DETECTED	100% MATRIX
408235B	29	NORTH WING		BLACK	GLUE / MASTIC	NF	NONE DETECTED	100% MATRIX
408236A	30	NORTH WING		TAN	12" x 12" SMALL SPECKLES	NF	NONE DETECTED	100% MATRIX
408236B	30	NORTH WING		YELLOW	GLUE / MASTIC	NF	NONE DETECTED	100% MATRIX
408237A	31	NORTH WING		TAN	12" x 12" SMALL SPECKLES	NF	NONE DETECTED	100% MATRIX
408237B	31	NORTH WING		YELLOW	GLUE / MASTIC	NF	NONE DETECTED	100% MATRIX
408238	32	NORTH WING		CLEAR / RED	EPOXY FLOORING	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052834  
Sampled Date: 12/19/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 12/24/2014  
Date Analyzed: 12/24/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408239	33	NORTH WING		CLEAR / RED	EPOXY FLOORING	NF	NONE DETECTED	100% MATRIX
408240	34	NORTH WING		CLEAR / RED	EPOXY FLOORING	NF	NONE DETECTED	100% MATRIX
408241A	35	6TH FLOOR		GRAY	LINOLEUM FLOORING	NF	NONE DETECTED	100% MATRIX
408241B	35	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408242A	36	6TH FLOOR		TAN	LINOLEUM FLOORING	NF	NONE DETECTED	10% CELLULOSE 2% FIBROUS GLASS 88% MATRIX
408242B	36	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408243A	37	6TH FLOOR		GRAY	LINOLEUM FLOORING	NF	NONE DETECTED	100% MATRIX
408243B	37	6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408244A	38	6081 6TH FLOOR		WHITE	LINOLEUM	NF	NONE DETECTED	3% SYNTHETIC FIBERS 97% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052834 Project Number: P14320 • V11  
Sampled Date: 12/19/2014 Date Received: 12/24/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/24/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non- Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408244B	38	6081 6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408245A	39	6081 6TH FLOOR		WHITE	LINOLEUM	NF	NONE DETECTED	3% SYNTHETIC FIBERS 97% MATRIX
408245B	39	6081 6TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408246A	40	6081 6TH FLOOR		WHITE	LINOLEUM	NF	NONE DETECTED	3% SYNTHETIC FIBERS 97% MATRIX
408246B	40	6081 6TH FLOOR		YELLOW / BLACK	GLUE	NF	2% CHRYSOTILE	98% MATRIX

APPROVED SIGNATURE:

  
Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

052834

# ENCORP FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

 CLIENT: Veterans Administration DATE: 12-19-14 PAGE: 4 OF 4

 OB NO: PLUSO.VII INSPECTORS: Francisco Baraza

 LOCATION: 6th Floor

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
31.	408237	L	L	L	↓	A) ND B) ND
2.	408238	Wth wing	Red epoxy flooring	g	↓	Clear Red ND
3.	408239	↓	↓	↓	↓	ND
4.	408240	↓	↓	↓	↓	ND
5.	408241	6th floor	Unleam Flooring g	g	↓	A) NO - Gray ND B) Blue - Yellow - ND
6.	408242	↓	↓	↓	↓	A) NO - Tan ND B) Blue - Yellow - ND
7.	408243	↓	↓	↓	↓	A) Gray - NO B) Blue - Yellow - ND
8.	408244	6001 6th floor	White urea	g	↓	A) NO - Tan ND B) Blue - Yellow - ND
9.	408245	↓	↓	↓	↓	A) NO B) NO
40.	408246	↓	↓	↓	↓	A) NO B) NO

## CHAIN OF CUSTODY

Date/Time:

Sampled By:

OTHER:

Relinquished/Received By:

 S.F. = Square Feet  
L.F. = Linear Feet

 G = Good  
D = Damaged  
SD = Significantly Damaged

Consultant Special Instructions:

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052730  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407035A	1	BLDG 1 8TH FLOOR		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 94% MATRIX
407035B	1	BLDG 1 8TH FLOOR		BLUE	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
407036	2	BLDG 1 8TH FLOOR		BLUE	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
407037A	3	BLDG 1 8TH FLOOR		WHITE	DRYWALL	NF	NONE DETECTED	5% CELLULOSE 95% MATRIX
407037B	3	BLDG 1 8TH FLOOR		GREEN	MUD / TAPE	NF	2% CHRYSOTILE	98% MATRIX
407038A	4	BLDG 1 8TH FLOOR		GREEN / WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
407038B	4	BLDG 1 8TH FLOOR		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407039	5	BLDG 1 8TH FLOOR		BLUE / WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
407040A	6	BLDG 1 8TH FLOOR		BLUE / WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052730 Project Number: P14320 . V11  
Sampled Date: 11/12/2014 Date Received: 11/18/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 11/18/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407040B	6	BLDG 1 8TH FLOOR		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407041A	7	BLDG 1 8TH FLOOR		TAN / GREEN	6 INCH BASECOVE	NF	NONE DETECTED	100% MATRIX
407041B	7	BLDG 1 8TH FLOOR		BROWN	GLUE	NF	NONE DETECTED	100% MATRIX
407042A	8	BLDG 1 8TH FLOOR		TAN / GREEN	6 INCH BASECOVE	NF	NONE DETECTED	100% MATRIX
407042B	8	BLDG 1 8TH FLOOR		BROWN	GLUE	NF	NONE DETECTED	100% MATRIX
407043A	9	BLDG 1 8TH FLOOR		TAN / GREEN	6 INCH BASECOVE	NF	NONE DETECTED	100% MATRIX
407043B	9	BLDG 1 8TH FLOOR		BROWN	GLUE	NF	NONE DETECTED	100% MATRIX
407044A	10	BLDG 1 8TH FLOOR		GRAY	6 INCH BASECOVE	NF	NONE DETECTED	100% MATRIX
407044B	10	BLDG 1 8TH FLOOR		CLEAR	GLUE	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

Client Name: Department of Veterans AffairsClient Address: 4811 Airport Plaza DriveLong Beach, CA 90815Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICALFacility Address: 3350 LA JOLLA VILLAGE DRIVESAN DIEGO, CALIFORNIA 92161Reference Batch Number: 052730Sampled Date: 11/12/2014Sampled By: FRANCISCO BARRAZAAnalyzed By: ELAINE ESPIQUEProject Number: P14320 . V11Date Received: 11/18/2014Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

## BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407045A	11	BLDG 1 8TH FLOOR		GRAY	6 INCH BASECOVE	NF	NONE DETECTED	100% MATRIX
407045B	11	BLDG 1 8TH FLOOR		CLEAR	GLUE	NF	NONE DETECTED	100% MATRIX
407046A	12	BLDG 1 8TH FLOOR		GRAY	6 INCH BASECOVE	NF	NONE DETECTED	100% MATRIX
407046B	12	BLDG 1 8TH FLOOR		CLEAR	GLUE	NF	NONE DETECTED	100% MATRIX
407047	13	7TH FLOOR		GRAY	FIREPROOFING	FR	NONE DETECTED	95% GLASS WOOL 5% MATRIX
407048	14	7TH FLOOR		GRAY	FIREPROOFING	FR	NONE DETECTED	95% GLASS WOOL 5% MATRIX
407049	15	7TH FLOOR		GRAY	FIREPROOFING	FR	NONE DETECTED	95% GLASS WOOL 5% MATRIX
407050	16	7TH FLOOR		WHITE	TSI ELBOWS	FR	NONE DETECTED	2% FIBROUS GLASS 98% MATRIX
407051	17	7TH FLOOR		WHITE	TSI ELBOWS	FR	2% CHRYSOTILE	2% FIBROUS GLASS 96% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052730 Project Number: P14320 . V11  
Sampled Date: 11/12/2014 Date Received: 11/18/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 11/18/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407052	18	7TH FLOOR			TSI ELBOWS	SFP		
407053A	19	7TH FLOOR		GREEN	TOP COAT	NF	NONE DETECTED	100% MATRIX
407053B	19	7TH FLOOR		BEIGE	PLASTER WALLS	NF	NONE DETECTED	100% MATRIX
407054A	20	7TH FLOOR		GREEN	TOP COAT	NF	NONE DETECTED	100% MATRIX
407054B	20	7TH FLOOR		BEIGE	PLASTER WALLS	NF	NONE DETECTED	100% MATRIX
407055A	21	7TH FLOOR		GRAY / WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
407055B	21	7TH FLOOR		BEIGE	PLASTER WALLS	NF	NONE DETECTED	100% MATRIX
407056	22	7TH FLOOR		GREEN / WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX
407057A	23	7TH FLOOR		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052730  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407057B	23	7TH FLOOR		GREEN / WHITE	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
407058A	24	7TH FLOOR		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX
407058B	24	7TH FLOOR		GRAY / WHITE	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
407059	25	7TH FLOOR		BEIGE / YELLOW / WHITE	FIBERGLASS PIPE INSULATION	FR	NONE DETECTED	20% FIBROUS GLASS 80% MATRIX
407060	26	7TH FLOOR		BEIGE / YELLOW / WHITE	FIBERGLASS PIPE INSULATION	FR	NONE DETECTED	20% FIBROUS GLASS 80% MATRIX
407061	27	7TH FLOOR		BEIGE / YELLOW / WHITE	FIBERGLASS PIPE INSULATION	FR	NONE DETECTED	20% FIBROUS GLASS 80% MATRIX
407062	28	7TH FLOOR		GREEN / BROWN	DUCT SEAM MASTIC	NF	3% CHRYSOTILE	97% MATRIX
407063	29	7TH FLOOR			DUCT SEAM MASTIC		SFP	
407064	30	7TH FLOOR			DUCT SEAM MASTIC		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 · FAX (714) 523-9810 · MAIN@ENCORP.NET · WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052730  
Sampled Date: 11/12/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 · V11  
Date Received: 11/18/2014  
Date Analyzed: 11/18/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407065	31	7TH FLOOR		BEIGE	CLOTH BOILER WRAP	NF	NONE DETECTED	5% CELLULOSE 3% FIBROUS GLASS 92% MATRIX
407066	32	7TH FLOOR		BEIGE	CLOTH BOILER WRAP	NF	NONE DETECTED	5% CELLULOSE 3% FIBROUS GLASS 92% MATRIX
407067	33	7TH FLOOR		BEIGE	CLOTH BOILER WRAP	NF	NONE DETECTED	5% CELLULOSE 3% FIBROUS GLASS 92% MATRIX
407068A	34	7TH FLOOR		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
407068B	34	7TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407069A	35	7TH FLOOR		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
407069B	35	7TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
407070A	36	7TH FLOOR		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
407070B	36	7TH FLOOR		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

Client Name: Department of Veterans Affairs  
 Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
 Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
 Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052730 Project Number: P14320 V11  
 Sampled Date: 11/12/2014 Date Received: 11/18/2014  
 Sampled By: FRANCISCO BARRAZA Date Analyzed: 11/18/2014  
 Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

SAMPLE DESCRIPTION			Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
Sample Number	Field/ Client Number	Sample Location/Activity			

 11/18/14

APPROVED SIGNATURE:

Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

CLIENT: Department of Veterans AffairsDATE: 11-12-14PAGE: 1OF 4JOB NO: P4230.V.11INSPECTORS: Francisco BararazaLOCATION: Building 1 3th Floor

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407035	BLDG 1 3th Floor	Drywall	9		A) Drywall - white B) Blue - ND
2.	407036					JC - Blue ND
3.	407037					A) Drywall 5' x 11' 2' x 1/2" ND B) Blue ND
4.	407038		Plaster	9		A) pop loc (green white) ND B) plaster - beige ND
5.	407039					Pop loc Blue White ND
6.	407040					A) Blue White ND B) Plaster - beige ND
7.	407041		6" - 6" tan/green plaster	9		A) tan (green) ND B) Blue - Brown - ND
8.	407042					A) Blue - Brown - ND B) Blue - Brown - ND
9.	407043					A) Blue - Brown - ND B) Blue - Brown - ND
10.	407044		6" plaster	9		A) Blue - Brown - ND B) Blue - Brown - ND

## ABBREVIATIONS:

## CHAIN OF CUSTODY

TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled by:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	SF = Square Feet LF = Linear Feet	Francisco Bararaza	11-12-14
Comments/special instructions:			Francisco Bararaza	11-12-14
			Received: <u>[Signature]</u>	11-17-14 1600
				11-18-14 0710

CLIENT: Department of Veterans Affairs

DATE: 11-12-14

PAGE: 2 OF 4

JOB NO: PWSB-V11

INSPECTORS: Francisco Barrera

LOCATION: Bldg 1 8th Floor

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407045	↑	↑	↑	↑	ND
2.	407046	↑	↑	↑	↑	ND
3.	407047	7th floor	Fire proofing	g	↑	ND
4.	407048	↑	↑	↑	↑	ND
5.	407049	↑	↑	↑	↑	ND
6.	407050	7th floor	TSI elbows	g	↑	ND
7.	407051	↑	↑	↑	↑	ND
8.	407052	↑	↑	↑	↑	ND
9.	407053	↑	Plaster walls	g	↑	ND
20.	407054	↑	↑	↑	↑	ND

ABBREVIATIONS:			
TYPES OF MATERIALS:	CONDITION:	OTHER:	
S = Surface Material	G = Good	S.F. = Square Feet	
TSI = Thermal Systems Insulation	D = Damaged	L.F. = Linear Feet	
M = Miscellaneous Material	SD = Significantly Damaged		
Comments/Special Instructions:			

CHAIN OF CUSTODY	
Sampled by:	Date/Time:
Francisco Barrera	11-12-14
Retained by:	Date/Time:
Francisco Barrera	11-12-14
Relinquished to:	Date/Time:
Revised: <u>[Signature]</u>	11/18/14 0710



CLIENT: Department of Veterans Affairs

DATE: 11-12-14

INSPECTORS: Francisco Barrera

JOB NO: DVS-03-VI-1

LOCATION: Bldg 1 9th Flr

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
2 1.	407055	↓	↓	↓	↓	gray knr NO
2.	407056	7th Floor	Drywall/mud tape	g	↓	3 ply glass / base NO green vinyl 2. NO cellulose NO
3.	407057	↓	↓	↓	↓	A) Drywall - white NO B) Cell 12. 1-12-14 NO C) Green white NO
4.	407058	↓	↓	↓	↓	A) Drywall - white NO B) Cell 2. 1-12-14 NO C) Gray white NO
5.	407059	↓	Fiberglass pipe insulation	g	↓	Beige / Yellow / black 20% Fiberglass NO
6.	407060	↓	↓	↓	↓	ND
7.	407061	↓	↓	↓	↓	ND
8.	407062	↓	Duct seam mastic	g	↓	green brown 3% ch HCN
9.	407063	↓	↓	↓	↓	SF
30.	407064	↓	↓	↓	↓	SF

## CHAIN OF CUSTODY

Date/Time:

Sampled By:

Francisco Barrera 11-12-14

Relinquished/Received By:

Francisco Barrera 11-12-14

Relinquished/Received By:

11-17-14 1600  
11-18-14 0710

## ABBREVIATIONS:

## CONDITION:

S = Surface Material  
TSI = Thermal Systems Insulation  
M = Miscellaneous MaterialG = Good  
D = Damaged  
SD = Significantly Damaged

## OTHER:

SF = Square Feet  
LF = Linear Feet

Comments/Special Instructions:

CLIENT: Department of Veterans AffairsDATE: 11-12-14PAGE: 4 OF 4JOB NO: P423.V.I.IINSPECTORS: Francisco BarreraLOCATION: Building 1 8th Floor

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
3 1.	457 65	7th Floor	Cloth Boiler wrap	g	↓	Boiler 34% class NO
2.	457 66	↓	↓	↓	↓	NO
3.	457 67	↓	↓	↓	↓	NO
4.	457 68	↓	tan Basecoat	g	↓	A) Basecoat tan - NO B) Glue Yellow - NO
5.	457 63	↓	↓	↓	↓	A) NO B) NO
6.	457 79	↓	↓	↓	↓	A) NO B) NO
7.						
8.						
9.						
0.						

## ABBREVIATIONS:

## CHAIN OF CUSTODY

TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled by:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material Comments/Special Instructions:	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet	Francisco Barrera	11-12-14
			Francisco Barrera	11-12-14
			Retrieved/Received By:	Date/Time:
			Retrieved: <u>11/17/14 1600</u>	<u>11/18/14 0710</u>

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052781  
Sampled Date: 12/2/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407713	1	BASEMENT INTERSTITIAL		WHITE	OVERSPRAY FIREPROOFING	FR	8% CHRYSOTILE	92% MATRIX
407714	2	BASEMENT INTERSTITIAL			OVERSPRAY FIREPROOFING		SFP	
407715	3	BASEMENT INTERSTITIAL			OVERSPRAY FIREPROOFING		SFP	
407716	4	BASEMENT INTERSTITIAL		BEIGE	BEAM FIREPROOFING	FR	8% CHRYSOTILE	92% MATRIX
407717	5	BASEMENT INTERSTITIAL			BEAM FIREPROOFING		SFP	
407718	6	BASEMENT INTERSTITIAL			BEAM FIREPROOFING		SFP	
407719	7	BASEMENT INTERSTITIAL		BEIGE	COLUMN FIREPROOFING	FR	8% CHRYSOTILE	92% MATRIX
407720	8	BASEMENT INTERSTITIAL			COLUMN FIREPROOFING		SFP	
407721	9	BASEMENT INTERSTITIAL			COLUMN FIREPROOFING		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052781  
Sampled Date: 12/2/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407722	10	BASEMENT INTERSTITIAL		WHITE	TSI ELBOWS	FR	3% AMOSITE	4% FIBROUS GLASS 93% MATRIX
407723	11	BASEMENT INTERSTITIAL			TSI ELBOWS		SFP	
407724	12	BASEMENT INTERSTITIAL			TSI ELBOWS		SFP	
407725	13	BASEMENT INTERSTITIAL		YELLOW	PIPE WRAP (FIBERGLASS)	FR	NONE DETECTED	70% SYNTHETIC FIBERS 10% CELLULOSE 20% MATRIX
407726	14	BASEMENT INTERSTITIAL		YELLOW	PIPE WRAP (FIBERGLASS)	FR	NONE DETECTED	70% SYNTHETIC FIBERS 10% CELLULOSE 20% MATRIX
407727	15	BASEMENT INTERSTITIAL		YELLOW	PIPE WRAP (FIBERGLASS)	FR	NONE DETECTED	70% SYNTHETIC FIBERS 10% CELLULOSE 20% MATRIX
407728	16	BASEMENT INTERSTITIAL		BROWN	DUCT SEAM CAULKING	NF	5% CHRYSOTILE	95% MATRIX
407729	17	BASEMENT INTERSTITIAL			DUCT SEAM CAULKING		SFP	
407730	18	BASEMENT INTERSTITIAL			DUCT SEAM CAULKING		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052781 Project Number: P14320 V11  
Sampled Date: 12/2/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

### SAMPLE DESCRIPTION

Sample Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
---------------	----------------------	--------------------------	-------	----------	------------------------	------------------	------------------

APPROVED SIGNATURE:

Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT 052781

CLIENT: Veterans Administration SA DATE: 12-2-14 PAGE: 1 OF 2  
 JOB NO: D4320-VIA INSPECTORS: Francisco Barrera CSST 07-4412  
 LOCATION: Basement Interstitial / 3350 La Jolla Village Dr San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407713	Basement Interstitial	aerspray Fire Proofing	g	8	White 8/CHRY
2.	407714				1	SFP
3.	407715				1	SFP
4.	407716		Beam Fire Proofing	g		Bugs 8/CHRY
5.	407717				1	SFP
6.	407718				1	SFP
7.	407719		Column Fire Proofing	g		Bugs 8/CHRY
8.	407720				1	SFP
9.	407721				1	SFP
10	407722		TSI elbows	g	1	White 8/CHRY

ABBREVIATIONS:		CHAIN OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	Sampled by:	Date/Time:
S = Surface Material	G = Good	Francisco Barrera	12-3-14
TSI = Thermal Systems Insulation	D = Damaged	Relinquished/Received By:	Date/Time:
M = Miscellaneous Material	SD = Significantly Damaged	Francisco Barrera	12-3-14
Comments - special instructions:		Relinquished/Received By:	Date/Time:
		Received: [Signature]	12/3/14 9:15
			12/4/14 0930
ENCORP Laboratory Services 16700 Valley View Avenue, Suite 100 La Mirada California 90638			
Office (714) 523-9811 Fax (714) 523-9810			

# ENCORP FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT 052781

CLIENT: Vibracore Administration SA DATE: 12-2-14 PAGE: 2 OF 2  
 JOB NO: 04320-VII INSPECTORS: Francisco Barrera  
 LOCATION: Basement Interstitial / 3350 La Billa Village Drive San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407723	Basement interstitial	↓	I	I	SFP
2.	407724			I	I	SFP
3.	407725		Pipe wrap (fiberglass)	G		Yellow 90/10 synth 10% cell NO
4.	407726		↓	I	I	NO
5.	407727		↓	I	I	NO
6.	407728		Duct seam caulking (brown)	G		Brown S/Ctray
7.	407729		↓	I	I	SFP
8.	407730		↓	I	I	SFP
9.						
20.						

ABBREVIATIONS:

TYPES OF MATERIALS:	CONDITION:	OTHER:
S = Surface Material TS = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	SF = Square Feet LF = Linear Feet

Comments: Special Insulation.

CHAIN OF CUSTODY

Sampled by:	Date/Time:
Francisco Barrera	12-3-14
Relinquished/Received By:	Date/Time:
Francisco Barrera	12-3-14
Relinquished/Received By:	Date/Time:
Rcd	12/4/14 915 12/4/17 0930

ENCORP Laboratory Services 16700 Valley View Avenue, Suite 100 La Mirada California 90638 Office (714) 523-9811 Fax (714) 523-9810

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052778

Sampled Date: 12/2/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			
407638	1	1ST FLOOR INTERSTITIAL	WHITE / BEIGE	FIREPROOFING OVERSPRAY	FR 8% CHRYSOTILE	92% MATRIX
407639	2	1ST FLOOR INTERSTITIAL		FIREPROOFING OVERSPRAY	SFP	
407640	3	1ST FLOOR INTERSTITIAL		FIREPROOFING OVERSPRAY	SFP	
407641	4	1ST FLOOR INTERSTITIAL	BEIGE	FIREPROOFING (BEAMS)	FR 8% CHRYSOTILE	92% MATRIX
407642	5	1ST FLOOR INTERSTITIAL		FIREPROOFING (BEAMS)	SFP	
407643	6	1ST FLOOR INTERSTITIAL		FIREPROOFING (BEAMS)	SFP	
407644	7	1ST FLOOR INTERSTITIAL	BEIGE	FIREPROOFING COLUMN	FR 8% CHRYSOTILE	92% MATRIX
407645	8	1ST FLOOR INTERSTITIAL		FIREPROOFING COLUMN	SFP	
407646	9	1ST FLOOR INTERSTITIAL		FIREPROOFING COLUMN	SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affair  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052778 Project Number: P14320 . V11  
Sampled Date: 12/2/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407647	10	1ST FLOOR INTERSTITIAL		GRAY	TSI ELBOWS	FR	3% CHRYSOTILE	5% FIBROUS GLASS 92% MATRIX
407648	11	1ST FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407649	12	1ST FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407650	13	1ST FLOOR INTERSTITIAL		YELLOW	PIPE WRAP INSULATION	FR	NONE DETECTED	70% CELLULOSE 8% FIBROUS GLASS 22% MATRIX
407651	14	1ST FLOOR INTERSTITIAL		YELLOW	PIPE WRAP INSULATION	FR	NONE DETECTED	70% CELLULOSE 8% FIBROUS GLASS 22% MATRIX
407652	15	1ST FLOOR INTERSTITIAL		YELLOW	PIPE WRAP INSULATION	FR	NONE DETECTED	70% CELLULOSE 8% FIBROUS GLASS 22% MATRIX
407653	16	1ST FLOOR INTERSTITIAL		BROWN	DUCT SEAM CAULKING	NF	5% CHRYSOTILE	95% MATRIX
407654	17	1ST FLOOR INTERSTITIAL			DUCT SEAM CAULKING		SFP	
407655	18	1ST FLOOR INTERSTITIAL			DUCT SEAM CAULKING		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052778 Project Number: P14320 V11  
Sampled Date: 12/2/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407656	19	1ST FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407657	20	1ST FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407658	21	1ST FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407659	22	1ST FLOOR INTERSTITIAL		WHITE	CLOTH / PIPE (WRAP)	FR	80% CHRYSOTILE 5% FIBROUS GLASS 3% CELLULOSE 12% MATRIX	
407660	23	1ST FLOOR INTERSTITIAL			CLOTH / PIPE (WRAP)		SFP	
407661	24	1ST FLOOR INTERSTITIAL			CLOTH / PIPE (WRAP)		SFP	

APPROVED SIGNATURE:

*Elaine Espique* 12/4/14

Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052778

CLIENT: Department of Veterans Affairs DATE: 11-13-14 12/2/14 PAGE: 1 OF 3  
 JOB NO: P14320.V11 INSPECTORS: Francisco Barata  
 LOCATION: Veterans Administration SA - 4th Floor 1st Floor Interstitial

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407638	1st Floor Interstitial	Fire proofing aerospray	g		WATER BEIGE 8/10/14
2.	407639					SFP
3.	407640					SFP
4.	407641		Fire proofing (Beams)			Beige 8/10/14
5.	407642					SFP
6.	407643					SFP
7.	407644		Fire proofing column			Beige 8/10/14
8.	407645					SFP
9.	407646					SFP
10.	407647		TSI elbows			Gray 8/10/14

CHAIN OF CUSTODY

Sampled by: Francisco Barata Date/Time: 12-3-14  
 Relinquished/Received By: Francisco Barata Date/Time: 12-3-14  
 Relinquished/Received By: RECEIVED Date/Time: 12/4/14 2030

ABBREVIATIONS:

TYPES OF MATERIALS:	CONDITION:	OTHER:
S = Surface Material	G = Good	S.F. = Square Feet
TSI = Thermal Systems Insulation	D = Damaged	L.F. = Linear Feet
M = Miscellaneous Material	SD = Significantly Damaged	

ENCORP Laboratory Services, 16700 Valley View Avenue, Suite 100 La Mirada, California 90638  
 Office (714) 523-9411 Fax (714) 523-9810

CLIENT: Department of Veterans Affairs DATE: 12-2-14 PAGE: 2 OF 3  
JOB NO: PV220-VI-1 INSPECTORS: Francisco Barrera CSST 07-4192  
LOCATION: Veterans Administration SA 1st Floor Interstitial

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407648	1st Floor Interstitial		0		SFP
2.	407649					SFP
3.	407650		Pipe wrap insulation			Yellow 70% Cellulose Fiberglass ND
4.	407651					ND
5.	407652					ND
6.	407653		Brown duct seam caulking			Brown S/Cryst
7.	407654					SFP
8.	407655					SFP
9.	407656		Plaster			Brick ND
10.	407657					ND

ABBREVIATIONS:		CHAIN OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	Sampled by:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	Francisco Barrera	12-3-14
	OTHER:	Relinquished/Received By:	Relinquished/Received Date/Time:
	S.F. = Square Feet L.F. = Linear Feet	Francisco Barrera	12-3-14
		Received: <u>[Signature]</u>	12/4/14 0930



CLIENT: Department of Veterans AffairsDATE: 12-2-14PAGE: 3OF 3JOB NO: P14320.VIIINSPECTORS: Francisco BarreraLOCATION: Veterans Administration SA1st floor interstitial

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	407658	1st floor interstitial		G		pink ND
2.	407659		cloth/DIPS wrap			white Fiberglass 80% Chrys 20% Cell
3.	407660					SFP
4.	407661					SFP
5.						
6.						
7.						
8.						
9.						
30.						

## ABBREVIATIONS:

## TYPES OF MATERIALS:

S = Surface Material  
TSI = Thermal Systems Insulation  
M = Miscellaneous Material

## CONDITION:

G = Good  
D = Damaged  
SD = Significantly Damaged

## OTHER:

S.F. = Square Feet  
L.F. = Linear Feet

## Sampled by:

Francisco Barrera

## Date/Time:

12-2-14

## Relinquished/Received By:

Francisco Barrera

## Date/Time:

12-2-14

## Relinquished/Received By:

Revised: ON

## Date/Time:

12/4/14 900  
12/2/14 0930

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052780 Project Number: P14320 . V11  
Sampled Date: 12/2/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407689	1	2ND FLOOR INTERSTITIAL		WHITE	FIREPROOFING OVERSPRAY	FR	8% CHRYSOTILE	92% MATRIX
407690	2	2ND FLOOR INTERSTITIAL			FIREPROOFING OVERSPRAY		SFP	
407691	3	2ND FLOOR INTERSTITIAL			FIREPROOFING OVERSPRAY		SFP	
407692	4	2ND FLOOR INTERSTITIAL		BEIGE	FIREPROOFING (BEAMS)	FR	8% CHRYSOTILE	92% MATRIX
407693	5	2ND FLOOR INTERSTITIAL			FIREPROOFING (BEAMS)		SFP	
407694	6	2ND FLOOR INTERSTITIAL			FIREPROOFING (BEAMS)		SFP	
407695	7	2ND FLOOR INTERSTITIAL		BEIGE	FIREPROOFING (COLUMNS)	FR	8% CHRYSOTILE	92% MATRIX
407696	8	2ND FLOOR INTERSTITIAL			FIREPROOFING (COLUMNS)		SFP	
407697	9	2ND FLOOR INTERSTITIAL			FIREPROOFING (COLUMNS)		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052780

Sampled Date: 12/2/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

### LABORATORY TEST REPORT

#### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407698	10	2ND FLOOR INTERSTITIAL		PINK / GRAY	TSI ELBOWS	FR	4% CHRYSOTILE	5% FIBROUS GLASS 91% MATRIX
407699	11	2ND FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407700	12	2ND FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407701	13	2ND FLOOR INTERSTITIAL		BEIGE	PIPE WRAP (CLOTH)	FR	NONE DETECTED	10% CELLULOSE 90% MATRIX
407702	14	2ND FLOOR INTERSTITIAL		BEIGE	PIPE WRAP (CLOTH)	FR	NONE DETECTED	10% CELLULOSE 90% MATRIX
407703	15	2ND FLOOR INTERSTITIAL		BEIGE	PIPE WRAP (CLOTH)	FR	NONE DETECTED	10% CELLULOSE 90% MATRIX
407704	16	2ND FLOOR INTERSTITIAL		BROWN	CAULKING DUCT SEAMS	NF	5% CHRYSOTILE	95% MATRIX
407705	17	2ND FLOOR INTERSTITIAL			CAULKING DUCT SEAMS		SFP	
407706	18	2ND FLOOR INTERSTITIAL			CAULKING DUCT SEAMS		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052780

Sampled Date: 12/2/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407707	19	2ND FLOOR INTERSTITIAL		GREEN	CAULKING DUCT SEAMS	NF	NONE DETECTED	100% MATRIX
407708	20	2ND FLOOR INTERSTITIAL		GREEN	CAULKING DUCT SEAMS	NF	NONE DETECTED	100% MATRIX
407709	21	2ND FLOOR INTERSTITIAL		GREEN	CAULKING DUCT SEAMS	NF	NONE DETECTED	100% MATRIX
407710	22	2ND FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407711	23	2ND FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407712	24	2ND FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX

APPROVED SIGNATURE:

  
Elaine Espique, Lab Manager

-NOTES: ND=Non Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite



CLIENT: Department of Veterans AffairsDATE: 12-2-14PAGE: 4OF 3JOB NO: P14320.VI-1INSPECTORS: Francisco Barrera est 01-4192LOCATION: Veterans Administration

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407689	2nd Floor Interstitial	Fire proofing overspray	g		white 87 clay
2.	407690					SFP
3.	407691					SFP
4.	407692		Fire proofing (Beams)			Blue 87 clay
5.	407693					SFP
6.	407694					SFP
7.	407695		Fire proofing (columns)			Blue 87 clay
8.	407696					SFP
9.	407697					SFP
10.	407698		TSI elbows			Blue 87 clay S.F. Fiberglass

## ABBREVIATIONS:

## TYPES OF MATERIALS:

S = Surface Material

TSI = Thermal Systems Insulation

M = Miscellaneous Material

K = unknown or special instructions

## CONDITION:

G = Good

D = Damaged

SD = Significantly Damaged

## OTHER:

S.F. = Square Feet

L.F. = Linear Feet

Sampled by:

Francisco Barrera

Relinquished/Received By:

Francisco Barrera

Relinquished/Received By:

Rad: a-2

Date/Time:

12-3-14

Date/Time:

12-3-14

Date/Time:

12/4/14 0936

## CHAIN OF CUSTODY

# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052789

CLIENT: Department of Veterans Affairs

DATE: 12-2-14

PAGE: 2 OF 2

JOB NO: P14320-VII

INSPECTORS: Francisco Barata

LOCATION: Veterans Administration

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407699	2nd Floor Interstitial	→	0		SFP
2.	407700					SFP
3.	407701		Pipe wrap (cloth)			Brick to floor/loss ND
4.	407702		↓			ND
5.	407703					ND
6.	407704		Brown caulking Duct seams			Brown S.F. City
7.	407705		↓			SFP
8.	407706					SFP
9.	407707		Green caulking Duct seams			Green NG
20.	407708		↓			ND

### ABBREVIATIONS:

TYPES OF MATERIALS:	CONDITION:	OTHER:
S = Surface Material	G = Good	S.F. = Square Feet
TSI = Thermal Systems Insulation	D = Damaged	L.F. = Linear Feet
MA = Miscellaneous Material	SD = Significantly Damaged	

Sampled by:

Francisco Barata

Date/Time: 12-3-14

Relinquished/Received By:

Francisco Barata

Date/Time: 12-3-14

Relinquished/Received By:

Adriana

Date/Time: 12/4/14 925

12/4/14 930

### CHAIN OF CUSTODY

CLIENT: Department of Veterans Affairs

DATE: 12-2-14

PAGE: 3 OF 3

JOB NO: P4320.V11

INSPECTORS:

LOCATION: Veterans Administration SA

7000 Interstitial (2nd Floor)

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
2 1.	407709	2nd Floor interstitial	↓	g		1 NO
2.	407710		Plaster			Big NO
3.	407711		↓			1 NO
4.	407712		↓			1 NO
5.						
6.						
7.						
8.						
9.						
30.						

### ABBREVIATIONS:

TYPES OF MATERIALS:	CONDITION:	OTHER:
S = Surface Material	G = Good	SF = Square Feet
TSI = Thermal Systems Insulation	D = Damaged	LF = Linear Feet
MA = Miscellaneous Material	SD = Significantly Damaged	

### CHAIN OF CUSTODY

Sampled by:	Date/Time:
Francisco Barrera	12-3-14
Relinquished/Received by:	Date/Time:
Francisco Barrera	12-3-14
Relinquished/Received by:	Date/Time:
Revised: <u>[Signature]</u>	12/9/14 1:05
	12/4/14 0930



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052779 Project Number: P14320 V11  
Sampled Date: 12/1/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407662	1	3RD FLOOR INTERSTITIAL		WHITE	FIREPROOFING OVERSPRAY	FR	8% CHRYSOTILE	92% MATRIX
407663	2	3RD FLOOR INTERSTITIAL			FIREPROOFING OVERSPRAY		SFP	
407664	3	3RD FLOOR INTERSTITIAL			FIREPROOFING OVERSPRAY		SFP	
407665	4	3RD FLOOR INTERSTITIAL		BEIGE	FIREPROOFING BEAM	FR	8% CHRYSOTILE	92% MATRIX
407666	5	3RD FLOOR INTERSTITIAL			FIREPROOFING BEAM		SFP	
407667	6	3RD FLOOR INTERSTITIAL			FIREPROOFING BEAM		SFP	
407668	7	3RD FLOOR INTERSTITIAL		BEIGE	FIREPROOFING COLUMN	FR	8% CHRYSOTILE	92% MATRIX
407669	8	3RD FLOOR INTERSTITIAL			FIREPROOFING COLUMN		SFP	
407670	9	3RD FLOOR INTERSTITIAL			FIREPROOFING COLUMN		SFP	

~NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052779 Project Number: P14320 • V11  
Sampled Date: 12/1/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407671	10	3RD FLOOR INTERSTITIAL		GRAY	TSI ELBOWS	FR	4% CHRYSOTILE	96% MATRIX
407672	11	3RD FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407673	12	3RD FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407674	13	3RD FLOOR INTERSTITIAL		BROWN	DUCT CAULKING	NF	5% CHRYSOTILE	95% MATRIX
407675	14	3RD FLOOR INTERSTITIAL			DUCT CAULKING		SFP	
407676	15	3RD FLOOR INTERSTITIAL			DUCT CAULKING		SFP	
407677	16	3RD FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	90% CELLULOSE 10% MATRIX
407678	17	3RD FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	90% CELLULOSE 10% MATRIX
407679	18	3RD FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	90% CELLULOSE 10% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052779  
Sampled Date: 12/1/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	
		Sample Location/Activity					Asbestos Type(%)	Non Asbestos (%)
407680	19	3RD FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407681	20	3RD FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407682	21	3RD FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407683	22	3RD FLOOR INTERSTITIAL		WHITE	CLOTH PIPE WRAP	FR	6% CHRYSOTILE	65% CELLULOSE 29% FIBROUS GLASS
407684	23	3RD FLOOR INTERSTITIAL			CLOTH PIPE WRAP		SFP	
407685	24	3RD FLOOR INTERSTITIAL			CLOTH PIPE WRAP		SFP	
407686	25	3RD FLOOR INTERSTITIAL		GREEN	DUCT SEAM CAULKING	NF	NONE DETECTED	100% MATRIX
407687	26	3RD FLOOR INTERSTITIAL		GREEN	DUCT SEAM CAULKING	NF	NONE DETECTED	100% MATRIX
407688	27	3RD FLOOR INTERSTITIAL		GREEN	DUCT SEAM CAULKING	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052779

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11

Date Received: 12/4/2014

Date Analyzed:

### LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

#### SAMPLE DESCRIPTION

Sample Number	Field/ Client Number	Sample Location/Activity	Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
---------------	----------------------	--------------------------	-------	----------	------------------------	------------------	------------------

APPROVED SIGNATURE:

*Elaine Espique*

Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052779

CLIENT: Department of Veterans Affairs DATE: 12-1-14 PAGE: 1 OF 3  
JOB NO: 3350 La Bolla Village Dr. San Diego INSPECTORS: Francisco Borraza  
LOCATION: P14320-V41

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407662	3RD Floor Interstitial	Fire proofing over spray	9		White 81/CHP
2.	407663					SFP
3.	407664					SFP
4.	407665		Fire proofing Beam			Beige 81/CHP
5.	407666					SFP
6.	407667					SFP
7.	407668		Fire proofing column			Beige 81/CHP
8.	407669					SFP
9.	407670					SFP
10.	407671		Tst elbows			Grey 41/CHP

ABBREVIATIONS				CHAIN OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled by:	Date/Time:	
G = Good D = Damaged M = Miscellaneous Material SD = Significantly Damaged Comments/Special Instructions:			Francisco Borraza	12-1-14	
		S.F. = Square Feet L.F. = Linear Feet	Relinquished/Received By:	Date/Time:	
			Francisco Borraza	12-1-14	
			Relinquished/Received By:	Date/Time:	
			ReelVad: O	12/4/14 910	
				12/4/14 0930	
ENCORP Laboratory Services 16700 Valley View Avenue, Suite 100 La Mirada, California 90638					
Office (714) 523-9811 Fax (714) 523-9810					



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052779

CLIENT: Department of Veterans Affairs

JOB NO: P14320.VII

LOCATION: P14320.VII

DATE: 12-1-14  
INSPECTORS: Francisco Barrero

PAGE: 2 OF 3

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407672	3rd Floor Interstitial		g		SFP
2.	407673					SFP
3.	407674		Duct Caulking			Brown SYPH
4.	407675					SFP
5.	407676					SFP
6.	407677		Fiberglass Pipe wrap			White G/L Cell NO
7.	407678					NO
8.	407679		↑			NO
9.	407680		Plaster			Bright NO
20.	407681					NO

ABBREVIATIONS		CHAIN OF CUSTODY	
OTHER:	CONDITION:	Sampled By:	Date/Time:
SF = Square Feet LF = Linear Feet	G = Good D = Damaged SD = Significantly Damaged	Francisco Barrero	12-1-14
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material		Relinquished/Received By:	Date/Time:
Consent/Special Instructions:		Francisco Barrero	12-1-14
		Relinquished/Received By:	Date/Time:
		Receiver: a	12/13/14 210 12/4/14 0930



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052773

CLIENT: Department of Veterans Affairs DATE: 12-1-14 PAGE: 3 OF 3  
JOB NO: P14370.VF1 INSPECTORS: Francisco Barrera  
LOCATION: 3250 La Jolla Village Dr San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	407682	3rd Floor Interstitial	↓	9		↓ NO
2.	407683		cloth pipe wrap			Waste 61.64% 61.64% SF
3.	407684		↓			SF
4.	407685		↓			SF
5.	407686		Green Dust			Green NO
6.	407687		Scum ceiling			↓ NO
7.	407688		↓			↓ NO
8.						
9.						
20.						

APPROVALS		CHART OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	Sampled by:	Date/Time:
G = Good D = Damaged M = Miscellaneous Material SD = Significantly Damaged Comments/Special Instructions:	OTHER:	Francisco Barrera	12-1-14
G = Surface Material TSI = Thermal Systems Insulation MI = Miscellaneous Material	SF = Square Feet LF = Linear Feet	Re-inspected/Retest of By:	Date/Time:
		Francisco Barrera	12-1-14
		Re-inspected/Retest of By:	Date/Time:
		Received: [Signature]	12/1/14 9:10 12/1/14 8:30

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052776

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407584	1	4TH FLOOR INTERSTITIAL		WHITE	OVERSPRAY FIREPROOFING	FR	8% CHRYSOTILE	92% MATRIX
407585	2	4TH FLOOR INTERSTITIAL			OVERSPRAY FIREPROOFING		SFP	
407586	3	4TH FLOOR INTERSTITIAL			OVERSPRAY FIREPROOFING		SFP	
407587	4	4TH FLOOR INTERSTITIAL		WHITE	BEAM FIREPROOFING	FR	8% CHRYSOTILE	92% MATRIX
407588	5	4TH FLOOR INTERSTITIAL			BEAM FIREPROOFING		SFP	
407589	6	4TH FLOOR INTERSTITIAL			BEAM FIREPROOFING		SFP	
407590	7	4TH FLOOR INTERSTITIAL		WHITE	COLUMN FIREPROOFING	FR	8% CHRYSOTILE	92% MATRIX
407591	8	4TH FLOOR INTERSTITIAL			COLUMN FIREPROOFING		SFP	
407592	9	4TH FLOOR INTERSTITIAL			COLUMN FIREPROOFING		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite



Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052776  
Sampled Date: 12/1/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 · V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

### LABORATORY TEST REPORT

#### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407593	10	4TH FLOOR INTERSTITIAL		WHITE	TSI ELBOWS	FR	NONE DETECTED	5% FIBROUS GLASS 95% MATRIX
407594	11	4TH FLOOR INTERSTITIAL		WHITE	TSI ELBOWS	FR	NONE DETECTED	5% FIBROUS GLASS 95% MATRIX
407595	12	4TH FLOOR INTERSTITIAL		WHITE	TSI ELBOWS	FR	NONE DETECTED	5% FIBROUS GLASS 95% MATRIX
407596	13	4TH FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	15% CELLULOSE 2% FIBROUS GLASS 83% MATRIX
407597	14	4TH FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	15% CELLULOSE 2% FIBROUS GLASS 83% MATRIX
407598	15	4TH FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	15% CELLULOSE 2% FIBROUS GLASS 83% MATRIX
407599	16	4TH FLOOR INTERSTITIAL		BROWN	DUCT SEAM CAULKING / MASTIC	NF	5% CHRYSOTILE	95% MATRIX
407600	17	4TH FLOOR INTERSTITIAL			DUCT SEAM CAULKING / MASTIC		SFP	
407601	18	4TH FLOOR INTERSTITIAL			DUCT SEAM CAULKING / MASTIC		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052776

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407602	19	4TH FLOOR INTERSTITIAL		GREEN	DUCT SEAM CAULKING / MASTIC	NF	NONE DETECTED	100% MATRIX
407603	20	4TH FLOOR INTERSTITIAL		GREEN	DUCT SEAM CAULKING / MASTIC	NF	NONE DETECTED	100% MATRIX
407604	21	4TH FLOOR INTERSTITIAL		GREEN	DUCT SEAM CAULKING / MASTIC	NF	NONE DETECTED	100% MATRIX
407605	22	4TH FLOOR INTERSTITIAL		WHITE	CLOTH PIPE (WRAP)	FR	95% CHRYSOTILE	5% FIBROUS GLASS
407606	23	4TH FLOOR INTERSTITIAL			CLOTH PIPE (WRAP)		SFP	
407607	24	4TH FLOOR INTERSTITIAL			CLOTH PIPE (WRAP)		SFP	
407608	25	4TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407609A	26	4TH FLOOR INTERSTITIAL		WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
407609B	26	4TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052776

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			

407610	27	4TH FLOOR INTERSTITIAL	BEIGE	PLASTER	NF	NONE DETECTED 100% MATRIX
--------	----	------------------------	-------	---------	----	---------------------------

APPROVED SIGNATURE:



Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP

PAGE: 7 OF 33

DATE: 12/1/15

CLIENT: Veterans Administration SA

JOB NO: PI4320.VI-I

LOCATION: 3250 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407584	4th floor interstitial	over spray Fire proofing	g		White 8% CHH
2.	407585					SFP
3.	407586					SFP
4.	407587		Beam Fire proofing	g		White 8% CHH
5.	407588					SFP
6.	407589					SFP
7.	407590		column Fire proofing	g		White 8% CHH
8.	407591					SFP
9.	407592					SFP
10.	407593		T&E elbow	g		White 8% Fiberglass ND

ABBREVIATIONS:		CHART OF CUSTODY	
TYPES OF MATERIALS:	CONDITION	OTHER:	Sampled By: _____ Date/Time: _____
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet	Relinquished/Received By: _____ Date/Time: _____
		Relinquished/Received By: _____ Date/Time: _____	
Comments/Special Instructions:		<div>12/4/14 12d</div> <div>12/4/14 0930</div> <div>revel: a</div>	



# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052776

CLIENT: Veterans Administration SA DATE: 12/1/14 PAGE: 2 OF 3  
 JOB NO: P14320.VII INSPECTORS: Francisco Barcena cost 07-412  
 LOCATION: 3350 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407594	4th Floor interstitial	↑	↑	↑	NG
2.	407595			↑	↑	ND
3.	407596		Fiberglass Pipe wrap	g	↑	NG 15% cell 2% Fiberglass
4.	407597		↑	↑	↑	ND
5.	407598		↑	↑	↑	ND
6.	407599		Brown duct seam caulking mastic	g	↑	Brown S/GH24
7.	407600		↑	↑	↑	SFP
8.	407601 407602		↑	↑	↑	SFP
9.			Green duct seam caulking mastic	g	↑	Green ND
20.			↑	↑	↑	ND

ABBREVIATIONS:

TYPES OF MATERIALS:	CONDITION:	OTHER:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet

Comments/special instructions:

Sampled by: Francisco Barcena Date/Time: 12/1/14  
 Relinquished/Retained By: Francisco Barcena Date/Time: 12/1/14  
12/1/14 12:00 12/1/14 0930  
 fid



# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052778

CLIENT: Veterans Administration SA DATE: 12/11/14 PAGE: 3 OF 3  
 JOB NO: P14320.VII INSPECTORS: Francisco Barrera CSF 07-4102  
 LOCATION: 3350 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	407604	4th Floor Interstitial	↓	↓	↓	ND
2.	407605		cloth pipe wrap	g		Asbestos tool 5/Fibers tool 95% Chm
3.	407606		↓	↓	↓	SFP
4.	407607		↓	↓	↓	SFP
5.	407608		Plaster	g		Perigle ND
6.	407609		↓	↓	↓	Asbestos tool 5/Fibers tool 95% Chm ND
7.	407610		↓	↓	↓	Perigle ND
8.						
9.						
30.						

ABBREVIATIONS: \_\_\_\_\_

CHART OF CUSTODY

Types of Materials:

S = Surface Material  
 ISI = Thermal Systems Insulation  
 M = Miscellaneous Material

Comments/Special Instructions:

Sampled By: Francisco Barrera Date/Time: 12/11/14  
 Relinquished/Received By: Francisco Barrera Date/Time: 12/11/14  
 Relinquished/Received By: Revel: [Signature] Date/Time: 12/11/14

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052777

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407611	1	5TH FLOOR INTERSTITIAL		BEIGE	FIREPROOFING COLUMNS	FR	8% CHRYSOTILE	92% MATRIX
407612	2	5TH FLOOR INTERSTITIAL			FIREPROOFING COLUMNS		SFP	
407613	3	5TH FLOOR INTERSTITIAL			FIREPROOFING COLUMNS		SFP	
407614	4	5TH FLOOR INTERSTITIAL		GRAY	TSI ELBOWS	FR	3% CHRYSOTILE	5% FIBROUS GLASS 92% MATRIX
407615	5	5TH FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407616	6	5TH FLOOR INTERSTITIAL			TSI ELBOWS		SFP	
407617	7	5TH FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	90% CELLULOSE 10% MATRIX
407618	8	5TH FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	80% CELLULOSE 10% FIBROUS GLASS 10% MATRIX
407619	9	5TH FLOOR INTERSTITIAL		WHITE	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	80% CELLULOSE 10% FIBROUS GLASS 10% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052777 Project Number: P14320 V11  
Sampled Date: 12/1/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407620	10	5TH FLOOR INTERSTITIAL		BROWN	DUCT SEAM CAULKING	NF	5% CHRYSOTILE	95% MATRIX
407621	11	5TH FLOOR INTERSTITIAL			DUCT SEAM CAULKING		SFP	
407622	12	5TH FLOOR INTERSTITIAL			DUCT SEAM CAULKING		SFP	
407623	13	5TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407624	14	5TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407625	15	5TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407626	16	5TH FLOOR INTERSTITIAL		WHITE	CEILING OVERSPRAY FIREPROOFING	FR	3% CHRYSOTILE	97% MATRIX
407627	17	5TH FLOOR INTERSTITIAL			CEILING OVERSPRAY FIREPROOFING		SFP	
407628	18	5TH FLOOR INTERSTITIAL			CEILING OVERSPRAY FIREPROOFING		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052777 Project Number: P14320 . V11  
Sampled Date: 12/1/2014 Date Received: 12/4/2014  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 12/4/2014  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407629	19	5TH FLOOR INTERSTITIAL		BEIGE	FIREPROOFING BEAMS	FR	3% CHRYSOTILE	97% MATRIX
407630	20	5TH FLOOR INTERSTITIAL			FIREPROOFING BEAMS		SFP	
407631	21	5TH FLOOR INTERSTITIAL			FIREPROOFING BEAMS		SFP	
407632	22	5TH FLOOR INTERSTITIAL		WHITE	CLOTH PIPE WRAP	FR	80% CHRYSOTILE	15% FIBROUS GLASS 5% MATRIX
407633	23	5TH FLOOR INTERSTITIAL			CLOTH PIPE WRAP		SFP	
407634	24	5TH FLOOR INTERSTITIAL			CLOTH PIPE WRAP		SFP	
407635	25	5TH FLOOR INTERSTITIAL		GREEN	CAULKING DUCT SEAMS	NF	NONE DETECTED	100% MATRIX
407636	26	5TH FLOOR INTERSTITIAL		GREEN	CAULKING DUCT SEAMS	NF	NONE DETECTED	100% MATRIX
407637	27	5TH FLOOR INTERSTITIAL		GREEN	CAULKING DUCT SEAMS	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR)= Friable, (NF)= Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052777

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/Client Number	SAMPLE DESCRIPTION		Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			
		Material				

APPROVED SIGNATURE:



Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite





16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052777

CLIENT: Department of Veterans Affairs DATE: 12-1-14 PAGE: 1 OF 3  
JOB NO: P14320-V-11 INSPECTORS: Francisco Barraza  
LOCATION: 3350 La Jolla Dr San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407611	5th Floor interstitial	Fire proofing columns	g		Buge 87 (Hem)
2.	407612				1	SFP
3.	407613				1	SFP
4.	407614		TSI elbows	g		Gray 87 (Hem) SFP
5.	407615				1	SFP
6.	407616				1	SFP
7.	407617		Fiberglass pipe wrap	g		White 80/Cellulose ND
8.	407618				1	White 80/Cellulose ND
9.	407619				1	White 80/Cellulose ND
10.	407620		Duct/Brown seam awlkey	g		Brown 87 (Hem)

APPROVALS:		DATE OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	OTHER:	OTHER:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material Comments/special instructions.	G = Good D = Damaged SD = Significantly Damaged	SF = Square Feet LF = Linear Feet	OTHER:
Sampled by: <u>Francisco Barraza</u> Date: <u>12-3-14</u>		Date: <u>12-3-14</u>	
Material tested by: <u>Francisco Barraza</u> Date: <u>12-3-14</u>		Date: <u>12-3-14</u>	
Reviewed by: <u>Revised</u>		Date: <u>12/4/14 0930</u>	



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052777

CLIENT: Department of Veterans Affairs DATE: 12-1-14 PAGE: 2 OF 3  
JOB NO: PV320.VII INSPECTORS: Francisco Barrera  
LOCATION: 3350 La Jolla Dr San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407621	5th Floor Interstitial	↓	↓	↓	SFP
2.	407622					SFP
3.	407623		Plaster	g	↓	Buge ND
4.	407624		↓	↓	↓	ND
5.	407625			↓	↓	ND
6.	407626		Ceiling over spray Fire proofing			Unbe S/C 424
7.	407627		↓	↓	↓	SFP
8.	407628			↓	↓	SFP
9.	407629		Fire proofing Beams	g	↓	Buge S/C 424
20.	407637		↓	↓	↓	SFP

ABBREVIATIONS		CHART OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	Sampled by:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material C = Commercial/Industrial	G = Good D = Damaged SD = Significantly Damaged	Francisco Barrera	12-3-14
	SF = Square Feet LF = Linear Feet	Francisco Barrera	12-3-14
		Red	12/4/14 900
			12/4/14 0930



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.enrcorp.net

052777

CLIENT: Department of Veterans Affairs DATE: 12-1-14 PAGE: 3 OF 3  
JOB NO: P14320-VJ1 INSPECTORS: Francisco Barrata  
LOCATION: 350 La Brea Dr San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	407631	5th Floor Interstitial	↓	↓	↓	SFP
2.	407632		cloth pipe wrap	g		made 80% glass SF Fiberglass
3.	407633		↓	↓	↓	SFP
4.	407634		↓	↓	↓	SFP
5.	407635		green caulking Dust Seams	g		Green ND
6.	407636		↓	↓		ND
7.	407637		↓	↓		AD
8.						
9.						
30.						

ABBREVIATIONS		CHAIN OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	Sampled by:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material Comments/Special Instructions:	G = Good D = Damaged SD = Significantly Damaged	Francisco Barrata	12-1-14
	OTHER:	Relinquished/Received by:	Date/Time:
	S.F. = Square Feet L.F. = Linear Feet	Francisco Barrata	12-1-14
		Relinquished/Received by:	Date/Time:
		Revised: A. G.	12/4/14 9:00 12/4/14 0930

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052775

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407557	1	6TH FLOOR INTERSTITIAL		WHITE	FIREPROOFING OVERSPRAY	FR	8% CHRYSOTILE	92% MATRIX
407558	2	6TH FLOOR INTERSTITIAL			FIREPROOFING OVERSPRAY		SFP	
407559	3	6TH FLOOR INTERSTITIAL			FIREPROOFING OVERSPRAY		SFP	
407560	4	6TH FLOOR INTERSTITIAL		WHITE	FIREPROOFING (BEAMS)	FR	8% CHRYSOTILE	92% MATRIX
407561	5	6TH FLOOR INTERSTITIAL			FIREPROOFING (BEAMS)		SFP	
407562	6	6TH FLOOR INTERSTITIAL			FIREPROOFING (BEAMS)		SFP	
407563	7	6TH FLOOR INTERSTITIAL		WHITE	FIREPROOFING COLUMNS	FR	8% CHRYSOTILE	92% MATRIX
407564	8	6TH FLOOR INTERSTITIAL			FIREPROOFING COLUMNS		SFP	
407565	9	6TH FLOOR INTERSTITIAL			FIREPROOFING COLUMNS		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to samples as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Reference Batch Number: 052775  
 Sampled Date: 12/1/2014  
 Sampled By: FRANCISCO BARRAZA  
 Analyzed By: ELAINE ESPIQUE

Reference Batch Number: 052775  
 Sampled Date: 12/1/20  
 Sampled By: FRANC  
 Analyzed By: ELAINE

# BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

POLAR ASBESTOS FIBER ANALYSIS (P-LAB) L1 A-000/R-55/110: Interim Method for the Determination of Asbestos in Bulk Insulation Samples							
Sample Number	Field/ Client Number	SAMPLE DESCRIPTION			Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color	Material			
407566	10	6TH FLOOR INTERSTITIAL	BROWN	TSI ELBOWS	NF	5% CHRYSOTILE	95% MATRIX
407567	11	6TH FLOOR INTERSTITIAL		TSI ELBOWS		SFP	
407568	12	6TH FLOOR INTERSTITIAL		TSI ELBOWS		SFP	
407569	13	6TH FLOOR INTERSTITIAL	BROWN	DUCT SEAM CAULKING MASTIC / (SEAMS)	NF	5% CHRYSOTILE	95% MATRIX
407570	14	6TH FLOOR INTERSTITIAL		DUCT SEAM CAULKING MASTIC / (SEAMS)		SFP	
407571	15	6TH FLOOR INTERSTITIAL		DUCT SEAM CAULKING MASTIC / (SEAMS)		SFP	
407572	16	6TH FLOOR INTERSTITIAL	WHITE / PINK	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	20% FIBROUS GLASS 5% CELLULOSE 75% MATRIX
407573	17	6TH FLOOR INTERSTITIAL	WHITE / PINK	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	20% FIBROUS GLASS 5% CELLULOSE 75% MATRIX
407574	18	6TH FLOOR INTERSTITIAL	WHITE / YELLOW	FIBERGLASS PIPE WRAP	FR	NONE DETECTED	20% FIBROUS GLASS 5% CELLULOSE 75% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all samples.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052775  
Sampled Date: 12/1/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 12/4/2014  
Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
407575	19	6TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407576	20	6TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407577	21	6TH FLOOR INTERSTITIAL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
407578	22	6TH FLOOR INTERSTITIAL		WHITE	CLOTH PIPE WRAP	NF	10% CHRYSOTILE	90% SYNTHETIC FIBERS
407579	23	6TH FLOOR INTERSTITIAL			CLOTH PIPE WRAP		SFP	
407580	24	6TH FLOOR INTERSTITIAL			CLOTH PIPE WRAP		SFP	
407581	25	6TH FLOOR INTERSTITIAL		GRAY	DUCT SEAM CAULKING / MASTIC	NF	NONE DETECTED	100% MATRIX
407582	26	6TH FLOOR INTERSTITIAL		GRAY	DUCT SEAM CAULKING / MASTIC	NF	NONE DETECTED	100% MATRIX
407583	27	6TH FLOOR INTERSTITIAL		GRAY	DUCT SEAM CAULKING / MASTIC	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052775

Sampled Date: 12/1/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 12/4/2014

Date Analyzed: 12/4/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			

APPROVED SIGNATURE:



Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052775

CLIENT: Veterans Administration SA

DATE: 12/14/14

PAGE: 1

OF 3

JOB NO: P14320.VI1

INSPECTORS: Francisco Barrera

LOCATION: 3350 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407557	6th floor interstitial	Fire proofing overspray	9		white 8% chrys
2.	407558				1	SFP
3.	407559				1	SFP
4.	407560		Fire proofing (Beams)			white 8% chrys
5.	407561				1	SFP
6.	407562					SFP
7.	407563		Fire proofing columns			white 8% chrys
8.	407564				1	SFP
9.	407565				1	SFP
10.	407566	V	TSI elbows			Green Brown 5% chrys

### ABBREVIATIONS

### CHART OF CUSTODY

TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled by:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet	Francisco Barrera	12/14/14
Comments/Special Instructions:			Francisco Barrera	12/14/14
			Received: <u>[Signature]</u>	12/14/14 0900
				12/14/14 0900



# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052775

CLIENT: Veterans Administration SA

DATE: 12/14/14

PAGE: 2 OF 3

JOB NO: P14320.VI1

INSPECTORS: Francisco Barona

LOCATION: 3350 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	407567	6th Floor interstitial			1	SFP
2.	407568				1	SFP
3.	407569		Duct seam caulking mastic/seams	9		Brown S/Glass
4.	407570				1	SFP
5.	407571				1	SFP
6.	407572		Fiberglass Pipe wrap	9		White Pink S/Glass 20% Fiberglass
7.	407573				1	NO
8.	407574				1	White Yellow S/Glass 20% Fiberglass
9.	407575		Plaster	9		Beige NO
20.	407576				1	NO

### ABBREVIATIONS:

### CHAIN OF CUSTODY

TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled By:	Date/Time:
S = Surface Material TS = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet	Francisco Barona	12/14/14
Common/Special Instructions:			Francisco Barona	12/14/14
			Deane: [Signature]	12/14/14 100
				12/14/14 0900

# ENCORP

## FIELD DATA SUMMARY INSPECTION & PHYSICAL ASSESSMENT

052775

CLIENT: Veterans Administration SA

DATE: 12/11/14

PAGE: 3 OF 3

JOB NO: P14320.VII

INSPECTORS: Francisco Barroza

LOCATION: 3850 La Jolla Village Drive San Diego CA

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	407577	cloth floor interstitial	cloth pipe wrap	g	1	NO
2.	407578					White op/Syn Fib 10/11/14
3.	407579				1	SD
4.	407580				1	SD
5.	407581		green dust seam caulking/mastic	g		NO
6.	407582				1	NO
7.	407583				1	NO
8.						
9.						
30.						

### ABBREVIATIONS:

### CHAIN OF CUSTODY

TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled By:	Date/Time:
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	SF = Square Feet LF = Linear Feet	Francisco Barroza	12/14/14
Comments/special instructions:			Francisco Barroza	12/14/14
			Received: <i>ami</i>	12/14/14 2900



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052670  
Sampled Date: 10/27/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11  
Date Received: 10/30/2014  
Date Analyzed: 10/30/2014

Bldg 2

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406258	1	ROOF		BLACK	ROOFING MATERIAL	NF	NONE DETECTED	2% FIBROUS GLASS 98% MATRIX
406259	2	ROOF		BLACK	ROOFING MATERIAL	NF	NONE DETECTED	2% FIBROUS GLASS 98% MATRIX
406260	3	ROOF		BLACK	ROOFING MATERIAL	NF	NONE DETECTED	2% FIBROUS GLASS 98% MATRIX
406261	4	ROOF		WHITE / BLACK	PENETRATION MASTIC	NF	4% CHRYSOTILE	96% MATRIX
406262	5	ROOF			PENETRATION MASTIC		SFP	
406263	6	ROOF			PENETRATION MASTIC		SFP	
406264	7	ROOF		WHITE / GRAY	DUCT SEAM CAULKING	NF	NONE DETECTED	100% MATRIX
406265	8	ROOF		WHITE / GRAY	DUCT SEAM CAULKING	NF	NONE DETECTED	100% MATRIX
406266	9	ROOF		WHITE / GRAY	DUCT SEAM CAULKING	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052670  
Sampled Date: 10/27/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11  
Date Received: 10/30/2014  
Date Analyzed: 10/30/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406267	10	ROOF		BLACK	MOISTURE BARRIER	NF	NONE DETECTED	2% SYNTHETIC FIBERS 98% MATRIX
406268	11	ROOF		BLACK	MOISTURE BARRIER	NF	NONE DETECTED	2% SYNTHETIC FIBERS 98% MATRIX
406269	12	ROOF		BLACK	MOISTURE BARRIER	NF	NONE DETECTED	2% SYNTHETIC FIBERS 98% MATRIX
406270	13	ROOF		GRAY	CAULKING FLASHING	NF	NONE DETECTED	100% MATRIX
406271	14	ROOF		GRAY	CAULKING FLASHING	NF	NONE DETECTED	100% MATRIX
406272	15	ROOF		GRAY	CAULKING FLASHING	NF	NONE DETECTED	100% MATRIX
406273	16	ROOF		WHITE / BLACK	ROOF EDGE CAP CAULKING	NF	4% CHRYSOTILE	96% MATRIX
406274	17	ROOF			ROOF EDGE CAP CAULKING		SFP	
406275	18	ROOF			ROOF EDGE CAP CAULKING		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Client Name: Department of Veterans AffairClient Address: 4811 Airport Plaza DriveLong Beach, CA 90815Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICALFacility Address: 3350 LA JOLLA VILLAGE DRIVESAN DIEGO, CALIFORNIA 92161Reference Batch Number: 052670Sampled Date: 10/27/2014Sampled By: FRANCISCO BARRAZAAnalyzed By: ELAINE ESPIQUEProject Number: P14320 . V11Date Received: 10/30/2014Date Analyzed: 10/30/2014

## LABORATORY TEST REPORT

## BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406276A	19	ROOF		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX
406276B	19	ROOF		GREEN	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
406277A	20	ROOF		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX
406277B	20	ROOF		GREEN	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
406278A	21	ROOF		WHITE	DRYWALL	NF	NONE DETECTED	6% CELLULOSE 2% FIBROUS GLASS 92% MATRIX
406278B	21	ROOF		GREEN	MUD / TAPE	NF	NONE DETECTED	100% MATRIX
406279A	22	INTERIOR WALL		WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX
406279B	22	INTERIOR WALL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
406280A	23	INTERIOR WALL		WHITE	TOP COAT	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Client Name: Department of Veterans AffairsClient Address: 4811 Airport Plaza DriveLong Beach, CA 90815Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICALFacility Address: 3350 LA JOLLA VILLAGE DRIVESAN DIEGO, CALIFORNIA 92161Reference Batch Number: 052670Sampled Date: 10/27/2014Sampled By: FRANCISCO BARRAZAAnalyzed By: ELAINE ESPIQUEProject Number: P14320 . V11Date Received: 10/30/2014Date Analyzed: 10/30/2014

## LABORATORY TEST REPORT

## BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	
		Sample Location/Activity						Non Asbestos (%)
406280B	23	INTERIOR WALL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
406281	24	INTERIOR WALL		BEIGE	PLASTER	NF	NONE DETECTED	100% MATRIX
406282	25	GENERATOR / MECH ROOM		WHITE / BEIGE	TSI PIPE INSULATION	FR	<1% CHRYSOTILE	3% FIBROUS GLASS 3% CELLULOSE 94% MATRIX
406283	26	GENERATOR / MECH ROOM		WHITE / BEIGE	TSI PIPE INSULATION	FR	<1% CHRYSOTILE	3% FIBROUS GLASS 3% CELLULOSE 94% MATRIX
406284	27	GENERATOR / MECH ROOM		WHITE / BEIGE	TSI PIPE INSULATION	FR	<1% CHRYSOTILE	3% FIBROUS GLASS 3% CELLULOSE 94% MATRIX
406285	28	GENERATOR / MECH ROOM		BLACK	VIBRATION DAMPENER	NF	NONE DETECTED	2% SYNTHETIC FIBERS 98% MATRIX
406286	29	GENERATOR / MECH ROOM		BLACK	VIBRATION DAMPENER	NF	NONE DETECTED	2% SYNTHETIC FIBERS 98% MATRIX
406287	30	GENERATOR / MECH ROOM		BLACK	VIBRATION DAMPENER	NF	NONE DETECTED	2% SYNTHETIC FIBERS 98% MATRIX
406288	31	CHILLER ROOM		BLACK / WHITE	TRANSITE COUNTER TOP	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Client Name: Department of Veterans AffairsClient Address: 4811 Airport Plaza DriveLong Beach, CA 90815Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICALFacility Address: 3350 LA JOLLA VILLAGE DRIVESAN DIEGO, CALIFORNIA 92161Reference Batch Number: 052670Sampled Date: 10/27/2014Sampled By: FRANCISCO BARRAZAAnalyzed By: ELAINE ESPIQUEProject Number: P14320 . V11Date Received: 10/30/2014Date Analyzed: 10/30/2014

## LABORATORY TEST REPORT

## BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406289	32	CHILLER ROOM		BLACK / WHITE	TRANSITE COUNTER TOP	NF	NONE DETECTED	100% MATRIX
406290	33	CHILLER ROOM		BLACK / WHITE	TRANSITE COUNTER TOP	NF	NONE DETECTED	100% MATRIX
406291A	34	LOCKERS		GRAY	VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
406291B	34	LOCKERS		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
406292A	35	LOCKERS		GRAY	VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
406292B	35	LOCKERS		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
406293A	36	LOCKERS		GRAY	VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
406293B	36	LOCKERS		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
406294A	37	LOCKERS		TAN	4" BASECOVE	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affair

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052670

Sampled Date: 10/27/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 10/30/2014

Date Analyzed: 10/30/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406294B	37	LOCKERS		WHITE	GLUE	NF	NONE DETECTED	100% MATRIX
406295A	38	LOCKERS		TAN	4" BASECOVE	NF	NONE DETECTED	100% MATRIX
406295B	38	LOCKERS		WHITE	GLUE	NF	NONE DETECTED	100% MATRIX
406296A	39	LOCKERS		TAN	4" BASECOVE	NF	NONE DETECTED	100% MATRIX
406296B	39	LOCKERS		WHITE	GLUE	NF	NONE DETECTED	100% MATRIX
406297	40	LOCKERS ROOM		WHITE / YELLOW	2' x 4' CEILING TILES	FR	NONE DETECTED	90% FIBROUS GLASS 10% MATRIX
406298	41	LOCKERS ROOM		WHITE / YELLOW	2' x 4' CEILING TILES	FR	NONE DETECTED	90% FIBROUS GLASS 10% MATRIX
406299	42	LOCKERS ROOM		WHITE / YELLOW	2' x 4' CEILING TILES	FR	NONE DETECTED	90% FIBROUS GLASS 10% MATRIX
406300	43	CEILING SPACE		BROWN	DUCT SEAM MASTIC	FR	3% CHRYSOTILE	97% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Client Name: Department of Veterans Affair  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052670  
Sampled Date: 10/27/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 10/30/2014  
Date Analyzed: 10/30/2014

### LABORATORY TEST REPORT

#### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406301	44	CEILING SPACE			DUCT SEAM MASTIC	SFP		
406302	45	CEILING SPACE			DUCT SEAM MASTIC	SFP		
406303	46	2ND LEVEL		WHITE	PIPE WRAP	FR	NONE DETECTED	10% FIBROUS GLASS 90% MATRIX
406304	47	2ND LEVEL		WHITE	PIPE WRAP	FR	NONE DETECTED	10% FIBROUS GLASS 90% MATRIX
406305	48	2ND LEVEL		WHITE	PIPE WRAP	FR	NONE DETECTED	10% FIBROUS GLASS 90% MATRIX
406306	49	2ND LEVEL		WHITE	DUCT WRAP	FR	NONE DETECTED	8% FIBROUS GLASS 92% MATRIX
406307	50	2ND LEVEL		WHITE	DUCT WRAP	FR	NONE DETECTED	8% FIBROUS GLASS 92% MATRIX
406308	51	2ND LEVEL		WHITE	DUCT WRAP	FR	NONE DETECTED	8% FIBROUS GLASS 92% MATRIX
406309	52	VENTS PERIMETER		BLACK / GRAY	CAULKING	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052670

Sampled Date: 10/27/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 10/30/2014

Date Analyzed: 10/30/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406310	53	VENTS PERIMETER		BLACK / GRAY	CAULKING	NF	NONE DETECTED	100% MATRIX
406311	54	VENTS PERIMETER		BLACK / GRAY	CAULKING	NF	NONE DETECTED	100% MATRIX
406312	55	BALER		WHITE / GREEN	BOILER LINING	FR	NONE DETECTED	2% FIBROUS GLASS 98% MATRIX
406313	56	BALER		WHITE / GREEN	BOILER LINING	FR	NONE DETECTED	2% FIBROUS GLASS 98% MATRIX
406314	57	BALER		WHITE / GREEN	BOILER LINING	FR	NONE DETECTED	2% FIBROUS GLASS 98% MATRIX
406317	58	2ND LEVEL STORAGE ROOM		BEIGE	12" x 12" FLOOR TILES	NF	NONE DETECTED	100% MATRIX
406318A	59	2ND LEVEL STORAGE ROOM		BEIGE	12" x 12" FLOOR TILES	NF	NONE DETECTED	100% MATRIX
406318B	59	2ND LEVEL STORAGE ROOM		TAN	FLOORING MATERIAL	NF	NONE DETECTED	100% MATRIX
406319	60	2ND LEVEL STORAGE ROOM		BEIGE	12" x 12" FLOOR TILES	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052670  
Sampled Date: 10/27/2014  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11  
Date Received: 10/30/2014  
Date Analyzed: 10/31/2014

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
406320A	61	2ND LEVEL		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
406320B	61	2ND LEVEL		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
406321A	62	2ND LEVEL		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
406321B	62	2ND LEVEL		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
406322A	63	2ND LEVEL		TAN	BASECOVE	NF	NONE DETECTED	100% MATRIX
406322B	63	2ND LEVEL		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
406323	64	TUNNEL PIPE		WHITE	TSI	FR	4% AMOSITE	96% MATRIX
406324	65	TUNNEL PIPE			TSI		SFP	
406325	66	TUNNEL PIPE			TSI		SFP	

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite

Client Name: Department of Veterans Affair

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052670

Sampled Date: 10/27/2014

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 10/30/2014

Date Analyzed: 10/31/2014

### LABORATORY TEST REPORT

**BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples**

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			
		Material				

APPROVED SIGNATURE:



Elaine Espique, Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite





16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052670

CLIENT: Department of Veterans Affairs DATE: 0-27-14 PAGE: 7 OF 6  
JOB NO: P14320.V.II  
INSPECTORS: Francisco Barrera  
LOCATION: 3350 La Jolla Village Dr San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	406258	Roof	Roofing material	g	12000	Black 21 Fiberglass ND
2.	406259			g		ND
3.	406260			g		ND
4.	406261		Penetration	g	200	White Black 41 (14)
5.	406262			g		SFP
6.	406263			g		SFP
7.	406264		Duct system	g	200	White Gray ND
8.	406265			g		ND
9.	406266			g		ND
10.	406267		Block structure	g	2000	Black 21 Syn Fib ND

APPROVALS		Date/Time	
Sampled By:	Francisco Barrera	02/14	
As Inspected/Received By:	Francisco Barrera	02/14	
Rechecked/Resampled By:		10-30-14	0430
OTHER:			
CONDITION:			
G = Good			
D = Damaged			
SD = Significantly Damaged			
OTHER:			
SF = Square Feet			
LF = Linear Feet			
ENCORP Laboratory Services 16700 Valley View Avenue, Suite 100 La Mirada, California 90638			

Red 10/30 920



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052670

CLIENT: Department of Veterans Affairs DATE: 10-27-14 PAGE: 2 OF 6  
JOB NO: P14320.V.II  
INSPECTORS: Francisco Barrera  
LOCATION: 3350 La Jolla Village Dr San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	466268	↓	↓	↓	↓	ND
2.	466269	↓	↓	↓	↓	ND
3.	466270	↓	caulking	o	200A	Gray ND
4.	466271	↓	↓	↓	↓	ND
5.	466272	↓	↓	↓	↓	ND
6.	466273	↓	Roof Edge Caulking	o	100A	White Black 474444
7.	466274	↓	↓	↓	↓	SFP
8.	466275	↓	↓	↓	↓	SFP
9.	466276	↓	Drainage Pipe Rubber	o	4500A	White Black 474444 ND
20.	466277	↓	↓	↓	↓	ND

TYPES OF MATERIALS:		CONDITION:	OTHER:	SAMPLED BY:	DATE/TIME:
S = Surface Material	G = Good			Francisco Barrera	10-27-14
TS = Thermal Systems Insulation	D = Damaged	SF = Square Feet		Francisco Barrera	10-27-14
M = Miscellaneous Material	SD = Significantly Damaged	LF = Linear Feet		Francisco Barrera	10-27-14
Comments/Notes:					

Red 05 10/30 920





16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

CLIENT: Department of Veterans Affairs DATE: 10-27-14 PAGE: 3 OF 6  
JOB NO: P14320.V.II  
INSPECTORS: Francisco Barrera  
LOCATION: 3350 La Jolla Village Dr San Diego CA 92161

052670

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
2 <sup>1</sup>	4-278	↓	↓	I	2500	NO A) ↓ B) ↓
2	4-279	interior wall	Plaster	D	2500	A) Top Coat - white NO B) Plaster - Beige NO
3	4-280	↓	↓	I	↓	A) ↓ NO B) ↓ NO
4	4-281	↓	↓	I	↓	Plaster-Beige NO
5	4-282	ceiling/beam	T&E PIPS	G	2000	White Beige 21-Fiberglass 21-Fiberglass
6	4-283	↓	↓	I	↓	nael clive
7	4-284	↓	↓	I	↓	nael clive
8	4-285	ceiling/beam	vibration dampener	G	2000	Black 21-Fiberglass NO
9	4-286	↓	↓	I	↓	NO
3	4-287	↓	↓	I	↓	NO

ABBREVIATIONS		DATE OF CUSTODY	
TYPE OF MATERIALS:	CONDITION:	OTHER:	DATE:
G = Surface Material ITG = Thermal Systems Insulation M = Miscellaneous Material SD = Significantly Damaged	G = Good D = Damaged SD = Significantly Damaged	SF = Square Feet LF = Linear Feet	10-27-14
Sampled By: <u>Francisco Barrera</u>		Date: <u>10-27-14</u>	
Reviewed By: <u>Francisco Barrera</u>		Date: <u>10-30-14</u>	
Retransported/Received By:		Date:	

Red ASD 10/30/2014



052670

052670

052670052670

Z:\Public\FORM\Fold Form\Current Field Form\Balk, Sandra Form





16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052670

CLIENT: Department of Veterans Affairs DATE: 10-27-14 PAGE: 5 OF 6  
JOB NO: P14320.V.1  
INSPECTOR: Francisco Barata  
LOCATION: 3350 La Jolla Village Dr San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
4 1.	445298	↓	↓	↓	↓	ND
2.	445299	↓	↓	↓	↓	ND
3.	445300	ceiling space	Brown Dust	g	200A	3/64/10
4.	445301	↓	↓	↓	↓	SFP
5.	445302	↓	↓	↓	↓	SFP
6.	445303	2ND level	Pipe wrap	g	1000L	White 101 Fiberglass ND
7.	445304	↓	↓	↓	↓	ND
8.	445305	↓	↓	↓	↓	ND
9.	445316	2ND level	Duct wrap	g	500A	White 81 Fiberglass ND
50.	445307	↓	↓	↓	↓	ND

TYPES OF MATERIALS:		OTHER:		SIGNED BY:		DATE/TIME:	
S = Surface Material	CONDITION:			Francisco Barata	10-27-14		
TS = Thermal Systems Insulation	G = Good	SF = Square Feet		Francisco Barata	10-27-14		
M = Miscellaneous Material	D = Damaged	LF = Linear Feet					
Comments/Special Instructions:				10-30-14		0930	

Red 10/30/14 920





16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052673

CLIENT: Department of Veterans Affairs DATE: 10-27-14 PAGE: 6 OF 6  
JOB NO: P14320.V.II  
INSPECTORS: Francisco Barrera  
LOCATION: 3350 La Jolla Village Dr San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	4-308	vents perimeter	seam caulking	g	1	ND
2.	4-309				200	
3.	4-310					
4.	4-311					
5.	4-312	vent seams	caulking	g	500	
6.	4-313					
7.	4-314					
8.						
9.						
10.						

ABBREVIATIONS		CHART OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled by: <u>Francisco Barrera</u> <u>10-27-14</u>
S = Surface Material TS = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	SF = Square Feet LF = Linear Feet	Reviewed by: <u>Francisco Barrera</u> <u>10-27-14</u> Reinspected/Retested By: <u>10-30-14</u> <u>0930</u>
Comments/Special Instructions:			
ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 - La Mirada, California 90638			
Office (714) 523-9811 • Fax (714) 523-9810			

Red AD 10/30/20



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052670

CLIENT: Department of Veterans Affairs DATE: 10-27-14 PAGE: 5 OF 5  
JOB NO: P14320.V1  
INSPECTORS: Francisco Barrera  
LOCATION: 3350 La Jolla Village Dr San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
5 1.	1			1		
2.	406309 411310 <sup>a</sup> 411311	Vents Perimeter	caulking	g	500	Black Gray NG
3.	411310					NG
4.	411311					AP
5.	411312	Boiler	Boiler Lining	g	1000	White Green 2:1 (bc-105) NO
6.	411313					NG
7.	411314					NG
8.	411317	2nd wheel storage room	2x12 floor joists	g	6000	Flour like gray NO
9.	411318					A) Floor tile peeling NO B) Floor tile missing NO C) Floor tile broken NO
10.	411319					Flour like gray NO

APPROPRIATE		DATE OF CONTACT	
TYPES OF MATERIALS:	CONDITION:	OTHER:	DATE/TIME:
S = Surface Material TSI = Thermal Systems Insulation MI = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	Sampled By: <u>Francisco Barrera</u> Inspected By: <u>Francisco Barrera</u> Field Supervisor: <u>Francisco Barrera</u>	<u>10-27-14</u> <u>10-31-14 0900</u>
ENCORP Laboratory Services, 16700 Valley View Avenue, Suite 100 La Mirada, California 90638 Office (714) 523-9811 Fax (714) 523-9810 2. Vendor FORAM Field Form Current Field Form/Blank Sample Form			

Red 052670 10/31/14 850





16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.encorp.net

052670

CLIENT: Department of Veterans Affairs DATE: 10-27-14 PAGE: 1 OF 1  
JOB NO: P14320.1.1 INSPECTORS: Francisco Barreto  
LOCATION: 3350 La Jolla Village Dr San Diego CA 92161

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
61.	450320	2nd level	tap base	g	804	Asbestos - Tan ND
2.	450321	↓	↓	↓	↓	Asbestos - Yellow ND
3.	450322	↓	↓	↓	↓	ND
4.	450323	tunnel pipe	ISI	g	↓	ND
5.	450324	↓	↓	↓	↓	White 47 AMCS
6.	450325	↓	↓	↓	↓	SFP
7.						SFP
8.						
9.						
10.						

TYPES OF MATERIALS:		DATE OF TEST:	
S = Surface Material	CONDITION:	Francisco Barreto 10-27-14	
ISI = Thermal Systems Insulation	G = Good	Francisco Barreto 10-27-14	
M = Miscellaneous Material	D = Damaged	10-27-14	
SD = Significantly Damaged	SF = Square Feet	0900	
LF = Linear Feet	OTHER:		
Comments/Special Instructions:			

Red Oak 10/31/950

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICE

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICA  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052867 Project Number: P14320 . V11  
Sampled Date: 1/14/2015 Date Received: 1/19/2015  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 1/19/2015  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408557	1	3RD FLOOR ROOM 3365 LINO		BEIGE	LINOLEUM FLOORING	NF	NONE DETECTED	100% MATRIX
408558	2	3RD FLOOR ROOM 3365 LINO		BEIGE	LINOLEUM FLOORING	NF	NONE DETECTED	100% MATRIX
408559A	3	3RD FLOOR ROOM 3365 LINO		BEIGE	LINOLEUM FLOORING	NF	NONE DETECTED	100% MATRIX
408559B	3	3RD FLOOR ROOM 3365 LINO		YELLOW	GLUE	NF	NONE DETECTED	100% MATRIX
408560A	4	5TH FLOOR OR		BLACK / WHITE	12" x 12" VCT	NF	NONE DETECTED	100% MATRIX
408560B	4	5TH FLOOR OR		BLACK	MASTIC	NF	NONE DETECTED	100% MATRIX
408561A	5	5TH FLOOR OR		BLACK / WHITE	12" x 12" VCT	NF	NONE DETECTED	100% MATRIX
408561B	5	5TH FLOOR OR		BLACK	MASTIC	NF	NONE DETECTED	100% MATRIX
408562A	6	5TH FLOOR OR		BLACK / WHITE	12" x 12" VCT	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICA  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052867  
Sampled Date: 1/14/2015  
Sampled By: FRANCISCO BARRAZA  
Analyzed By: ELAINE ESPIQUE

Project Number: P14320 • V11  
Date Received: 1/19/2015  
Date Analyzed: 1/19/2015

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos in Bulk Insulation Samples

Sample Number	Field/Client Number	SAMPLE DESCRIPTION		Friable or Non-	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			
408562B	6	5TH FLOOR OR	BLACK	NF	NONE DETECTED	100% MATRIX
408563A	7	4TH FLOOR	ORANGE	NF	NONE DETECTED	100% MATRIX
408563B	7	4TH FLOOR	YELLOW	NF	NONE DETECTED	100% MATRIX
408563C	7	4TH FLOOR	TAN	NF	NONE DETECTED	100% MATRIX
408563D	7	4TH FLOOR	YELLOW	NF	NONE DETECTED	100% MATRIX
408564A	8	4TH FLOOR	ORANGE	NF	NONE DETECTED	100% MATRIX
408564B	8	4TH FLOOR	YELLOW	NF	NONE DETECTED	100% MATRIX
408565A	9	4TH FLOOR	ORANGE	NF	NONE DETECTED	100% MATRIX
408565B	9	4TH FLOOR	YELLOW BLACK	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs  
Client Address: 4811 Airport Plaza Drive  
Long Beach, CA 90815  
Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL  
Facility Address: 3350 LA JOLLA VILLAGE DRIVE  
SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052867 Project Number: P14320 V11  
Sampled Date: 1/14/2015 Date Received: 1/19/2015  
Sampled By: FRANCISCO BARRAZA Date Analyzed: 1/19/2015  
Analyzed By: ELAINE ESPIQUE

## LABORATORY TEST REPORT

### BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408566A	10	4TH FLOOR		WHITE	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
408566B	10	4TH FLOOR		YELLOW	MASTIC	NF	NONE DETECTED	100% MATRIX
408567A	11	4TH FLOOR		WHITE	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
408567B	11	4TH FLOOR		YELLOW	MASTIC	NF	NONE DETECTED	100% MATRIX
408568A	12	4TH FLOOR		WHITE	12" x 12" VCT SPECKLES	NF	NONE DETECTED	100% MATRIX
408568B	12	4TH FLOOR		YELLOW / BLACK	MASTIC	NF	2% CHRYSOTILE	98% MATRIX
408569	13	3RD FLOOR EXTERIOR - STAIRWELL WALL		LIGHT GRAY	STUCCO	NF	NONE DETECTED	100% MATRIX
408570A	14	3RD FLOOR EXTERIOR - OVERHANG		BEIGE / DARK GRAY	TOP COAT	NF	<1% CHRYSOTILE	100% MATRIX
408570B	14	3RD FLOOR EXTERIOR - OVERHANG		LIGHT GRAY	STUCCO	NF	<1% CHRYSOTILE	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

Client Name: Department of Veterans AffairsClient Address: 4811 Airport Plaza DriveLong Beach, CA 90815Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICALFacility Address: 3350 LA JOLLA VILLAGE DRIVESAN DIEGO, CALIFORNIA 92161Reference Batch Number: 052867Sampled Date: 1/14/2015Sampled By: FRANCISCO BARRAZAAnalyzed By: ELAINE ESPIQUEProject Number: P14320 . V11Date Received: 1/19/2015Date Analyzed: 1/19/2015

## LABORATORY TEST REPORT

## BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Color	Material	Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity						
408571	15	3RD FLOOR EXTERIOR - OVERHANG 2ND FLOOR		GREEN / LIGHT GRAY	STUCCO	NF	NONE DETECTED	100% MATRIX
408572	16	2ND FLOOR STAIRWELL EXTERIOR		LIGHT GRAY	STUCCO	NF	NONE DETECTED	100% MATRIX
408573	17	2ND FLOOR STAIRWELL EXTERIOR		LIGHT GRAY	STUCCO	NF	NONE DETECTED	100% MATRIX
408574	18	EXTERIOR WINDOWS		BLACK	WINDOW CAULKING	NF	NONE DETECTED	100% MATRIX
408575	19	EXTERIOR WINDOWS		BLACK	WINDOW CAULKING	NF	NONE DETECTED	100% MATRIX
408576	20	EXTERIOR WINDOWS		BLACK	WINDOW CAULKING	NF	NONE DETECTED	100% MATRIX
408577	21	2ND FLOOR PATIO LINO		BLUE / PINK	PATIO LINO	NF	NONE DETECTED	100% MATRIX
408578	22	2ND FLOOR PATIO LINO		BLUE / PINK	PATIO LINO	NF	NONE DETECTED	100% MATRIX
408579	23	2ND FLOOR PATIO LINO		BLUE / PINK	PATIO LINO	NF	NONE DETECTED	100% MATRIX

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.

# ENCORP ENVIRONMENTAL MANAGEMENT AND SERVICES

16700 VALLEY VIEW AVE. STE. 100 LA MIRADA, CALIFORNIA 90638  
(714) 523-9811 • FAX (714) 523-9810 • MAIN@ENCORP.NET • WWW.ENCORP.NET

Client Name: Department of Veterans Affairs

Client Address: 4811 Airport Plaza Drive

Long Beach, CA 90815

Facility Name: VETERANS ADMINISTRATION SAN DIEGO MEDICAL

Facility Address: 3350 LA JOLLA VILLAGE DRIVE

SAN DIEGO, CALIFORNIA 92161

Reference Batch Number: 052867

Sampled Date: 1/14/2015

Sampled By: FRANCISCO BARRAZA

Analyzed By: ELAINE ESPIQUE

Project Number: P14320 . V11

Date Received: 1/19/2015

Date Analyzed: 1/19/2015

## LABORATORY TEST REPORT

BULK ASBESTOS FIBER ANALYSIS (PLM) EPA-600/R-93/116: Interim Method for the Determination of Asbestos In Bulk Insulation Samples

Sample Number	Field/ Client Number	SAMPLE DESCRIPTION		Friable or Non-Friable	Asbestos Type(%)	Non Asbestos (%)
		Sample Location/Activity	Color			

APPROVED SIGNATURE:

*Elaine Espique* 1/19/15

Elaine Espique , Lab Manager

-NOTES: ND=None Detected Asbestos is not quantifiable below the method detection limit of one (1) percent. Amphibole asbestos includes amosite, crocidolite, anthophyllite, tremolite and actinolite. (FR) = Friable, (NF) = Non-Friable. Condition of sample is as received by the laboratory. Our policy is to retain all samples for a period of thirty days. Accredited by the National Voluntary Laboratory Accreditation Program and Environmental Laboratory Certification for the specific scope of accreditation under NVLAP Lab Code 200878-0 and ELAP certificate no. 2379. Results reported pertain to sample(s) as submitted and does not necessarily apply to other apparently identical or similar materials. This report is submitted for the exclusive use of the client to whom it is addressed. Any reproduction of this report or use of this Laboratory's name for advertising or publicity purposes without prior written authorization is prohibited. In addition, this report is not to be used to claim product endorsement by NVLAP, ELAP, or any agency of the U.S. Government. Where applicable, layers or "sub-samples" are reported and the Total Asbestos % represents the composite percentage of all sample layers.



16700 Valley View Avenue, Suite 100  
La Mirada, California 90638  
Tel: (714) 523-9811  
Fax: (714) 523-9810  
www.enrcorp.net

Engineering our Environment

052867

CLIENT: Veterans Administration DATE: 1-14-15 PAGE: 1 OF 3  
JOB NO: DUS20-Vet INSPECTORS: Francisco Benitez  
LOCATION: 3350 La Brea Village Drive San Diego CA 92104

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	4085597	3rd Floor Room 3355 LNO	Linoleum flooring	g	—	Beige ND
2.	4085598				1	Beige ND
3.	4085559				1	Fluorine-Beige ND
4.	408560	5th Floor OR	Black/white 12x12 VCT/mastic g		1	Blue-Yellow-ND A) VCT Acet/White ND B) Mastic Black-ND
5.	408561				1	A) ND B) ND
6.	408562				1	A) ND B) ND
7.	408563	4th Floor	tan/orange VCT/mastic	o	1	see below
8.	408564				1	A) VCT-orange-ND B) Mastic-Yellow-ND
9.	408565				1	A) VCT-orange-ND ND B) Mastic-Yellow/Black 3/4" ND
10.	408566	4th Floor	12x12 white vct blue speckles mastic g		1	A) VCT-white ND B) Mastic-Yellow-ND

ABBREVIATIONS		CHAIN OF CUSTODY	
TYPES OF MATERIALS:	CONDITION:	OTHER:	Sampled by: <u>Francisco Benitez</u> Date/Time: <u>1-14-15</u>
S = Surface Material TSI = Thermal Systems Insulation M = Miscellaneous Material	G = Good D = Damaged SD = Significantly Damaged	S.F. = Square Feet L.F. = Linear Feet	Relinquished/Received By: <u>Francisco Benitez</u> Date/Time: <u>1-14-15</u>
Company Special Instructions: A) VCT-orange-ND B) VCT-white-ND C) VCT-black-ND D) Mastic-yellow-ND			Relinquished/Received By: <u>Francisco Benitez</u> Date/Time: <u>1-19-15 0730</u>
ENCORP Laboratory Services - 16700 Valley View Avenue, Suite 100 La Mirada, California 90638			
Office (714) 523-9811 Fax (714) 523-9810			

052867

CLIENT: Veterans Administration SA DATE: 1-14-15 PAGE: 2 OF 3  
JOB NO: PL320-VIL INSPECTORS: Francisco Barrera  
LOCATION: 3550 La Jolla Village Drive San Diego CA 92116

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
1.	408567	↓	↓	↓	↓	ND
2.	408568	↓	↓	↓	↓	ND
3.	408569	3RD floor exterior	stucco structural wall overhang	○	↓	ND
4.	408570	↓	↓	↓	↓	ND
5.	408571	↓	↓	↓	↓	ND
6.	408572	2ND stairwell exterior	overhang 2nd floor stucco	↓	↓	ND
7.	408573	↓	↓	↓	↓	ND
8.	408574	exterior windows	↓	↓	↓	ND
9.	408575	↓	↓	↓	↓	ND
20.	408576	↓	↓	↓	↓	ND

CHART OF CUSTODY

Abbreviations:

Types of Materials:

S = Surface Material  
TSI = Thermal Systems Insulation  
M = Miscellaneous Material

Condition:

G = Good  
D = Damaged  
SD = Significantly Damaged

Other:

S.F. = Square Feet  
L.F. = Linear Feet

Sampled by: Francisco Barrera Date/Time: 1-14-15  
Re-inspected/Received by: Francisco Barrera Date/Time: 1-14-15  
Re-inspected/Received by: Francisco Barrera Date/Time: 1-19-15 0710

ENCORP Laboratory Services, 16700 Valley View Avenue, Suite 100 La Mirada, California 90638  
Office (714) 523-9811 Fax (714) 523-9810



05867

CLIENT: Veterans Admin Station SA DATE: 1-14-15 PAGE: 3 OF 3  
JOB NO: PIU320.01 INSPECTORS: Francisco Barrera  
LOCATION: 3350 La Jolla Village Drive San Diego CA 92160

SAMPLE NO.	LAB ID #	SAMPLE LOCATION	MATERIAL DESCRIPTION	CONDITION	QUANTITY	% ASBESTOS
21.	408577	2nd Floor Patio Lino	Patio Lino	G		Blue Pmk NO
2	408578					NO
3	408579					NO
4.						
5.						
6.						
7.						
8.						
9.						
30.						

ABBREVIATIONS: \_\_\_\_\_ CHART OF CUSTODY

Types of Materials: \_\_\_\_\_

S = Surface Material  
TSI = Thermal Systems Insulation  
M = Miscellaneous Material  
Continental Special Instructions: \_\_\_\_\_

Condition: \_\_\_\_\_ OTHER: \_\_\_\_\_

G = Good  
D = Damaged  
SD = Significantly Damaged

S.F. = Square Feet  
L.F. = Linear Feet

Sampled By: Francisco Barrera Date/Time: 1-14-15  
Re-inspected/Received By: Francisco Barrera Date/Time: 1-14-15  
Re-inspected/Received By: Francisco Barrera Date/Time: 1-14-15

ENCORP Laboratory Services 16700 Valley View Avenue, Suite 100 La Mirada, California 90638 Office (714) 523-9811 Fax (714) 523-9810

**SECTION VI. SAMPLED ANALYSIS – LEAD**

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Department of Veterans Affairs</u>	ADDRESS: <u>3350 La Jolla Village San Diego</u>
SCOPE OF PROJECT: <u>VA Hospital</u>	DATE: <u>10-28-14</u>
INSPECTOR: <u>Francisco Barrera</u>	XRF SERIAL #: <u>14370.17</u>

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITIO N	LOCATION	QUANTITY	COMMENTS
1.	1.43	Red	wood	block	g	confirmation		
2.	.39							
3.	.51							
4.	0.48	tan	concrete	wall	g	Block #2 exterior		N
5.	0.39							W
6.	0.20							E
7.	0.11							S
8.	0.43	black	M	Roll Down door				
9.	0.45	brown	M	Vents				
10.	0.50	Red	M	conduit	g			
X 1.	1.70	Yellow	M	Post	g	Hydrant FIRE protection	each	
2.	Data Error					(2 each)	NE	exterior
X 3.	1.56					Fire Hydrant		
4.	2 test							
✓ 5.	1.17	tan	M	Drumspout	(g)	North	each	
6.	0.39	brown	M	conduits	(g)	North		
X 7.	2.10	Gray	M	Hard Rails	(N/E/W)		2 each	
8.	0.33	brown	M	door	g	N		
9.	0.70			frame	g	L		
20.	0.15	tan	M	Railing / Gate	N	(g).		
1.	0.44	Red	concrete	cur				
2.	0.22	Brown	M	Double door	(g).			
3.	0.65	Yellow	M	water main	(E)	(g)		
4.	0.98	tan	M	conduits	(E)			
X 5.	1.46	brown	M	vent frame	(g) (E)		each 6 each	
6.	0.18	Yellow	M	Post	(g) (E)			
7.	0.54	tan	M	oxygen pipe	g			
8.	0.13	blue	M	Pipe	(g)			
9.	0.28	tan	block	wall	(g)			
30.	0.40	w	M	water	Pipe (g) . (s)			

By: Francisco Barrera

Title: Sampling tech

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Department of Veterans Affairs</u>	ADDRESS: <u>3350 La Jolla Village San Diego</u>
SCOPE OF PROJECT: <u>VA Hospital</u>	DATE: <u>6-29-14</u>
INSPECTOR: <u>Francisco Barraza</u>	XRF SERIAL #: <u>        </u> PROJECT NUMBER: <u>P14320.V17</u>

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDIT N	LOCATION	QUANTITY	COMMENTS
31.	.	unc						
2.	.	↓						
3.	0.27	tan	concrete	wall	g	sath w BUB#2 interior		
4.	0.16	tan	metal	door	g	RR		
5.	0.92	l	l	l frame	(g)			
6.	0.02	tan	block	wall	(g)			
7.	0.07	green	light	concrete	wall	(S)		
8.	0.73			metal	pipe	(g)		
9.	0.88	Red	u	water	line	(g) (S).		
40.	0.81	brown	u	Boiler	tank	(g)		
1.	0.24	blue	u	pump	g			
2.	0.34	Light green	concrete	wall	(g)	East.		
3.	0.09	l	metal	brt	frame	(g)	5 each.	
4.	2.34	black	l	drain	pipe	E	400 LF.	
5.	0.69	brown	l	door	(g)			
6.	0.81	l	l	l frame	(g)			
7.	0.18	green	black	wall	(g)	(u).		
8.	0.24	Red	u	concrete	(g)			
9.	0.32	yellow	u	water	line	E.		
50.	0.65	yellow	concrete	Markings	on concrete			
1.	0.00	Light green	concrete	column	(g)			
2.	0.30	tan	concrete	door	(g)			
3.	0.19	Light green	concrete	wall	(u).			
4.	0.67	u	u	beam	g	break/storage Room		
5.	1.85	yellow	u	hand	rails	(g) break Room/storage	Each	
6.	0.58	black	u	falling	g			
7.	0.79	Red	u	l	l			
8.	0.41	Light green	concrete	ceiling	(g)			
9.	0.98	Red	u	sprinkler	(g) pipe.			
60.	0.90	l	l	l	l			

By: Francisco Barraza

Title: sampling tech.

Page 2 of 7

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: Department of Veteran Affairs ADDRESS: 3350 La Jolla Village San Diego  
 SCOPE OF PROJECT: VA- Hospital. DATE: 10-29-14  
 INSPECTOR: Francisco Barrera XRF SERIAL #: \_\_\_\_\_ PROJECT NUMBER: PV320.V41

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITION	LOCATION	QUANTITY	COMMENTS
6.	0.56	Yellow	Metal	Man Hole cover	R.	Storage Room.		
2.	0.07	blue	w	Wall tool rack	g!			
3.	unk.							
4.	0.38	light green	M	Ducts	g)			
5.	0.39	blue	M	cabinets	g)			
6.	0.88	1	1	tank	g)			
7.	0.39	1	M	Pipe	g) / valves			
8.	0.09	w	M	conduits	g)	elec Room		
9.	0.39	w	black	wall	g w			
7.	0.23							
1.	2.23							
2.	0.36							
3.	0.37	brown	M	double door	g)			
4.	0.15	1	1	1 frame	g)			
5.	0.88	tan	M	Heun breakeer panels	g)			
6.	unk							
X 7.	3.62	w	M	conduits	g)	10' wide 6-each From main elec.		
8.	0.76	Yellow	M	Natural gas line	g).			
9.	0.65	green	M	boiler	g).			
8.	unk							
1.	0.67	blue/green	M	Boiler	g)			
2.	0.01	w	M	water line	g).			
3.	2 test							
X 4.	1.46	orange	M	water line	g)	2 pipe each		Approx 80' each
5.	0.39	Red		Fire sprinkler	Metal g).			
6.	0.76	w	M	water tank	g).	Adjacent to generator Room		
7.	0.55	Gray	M	wall panels		generator/mechanical Room		
8.	unk							
9.	1.							
9.	0.31	Yellow	M	generators				

By: Francisco Barrera

Title: Sampling tech



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: Department of Veterans Affairs	ADDRESS: 3350 La Jolla Village San Diego CA
SCOPE OF PROJECT: VA Hospital	DATE: 10-29-14
INSPECTOR: Francisco Barrera	XRF SERIAL #: PROJECT NUMBER: P14370.V1

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITION	LOCATION	QUANTITY	COMMENTS
9 1.	0.09	w	concrete wall	g		NORTH		
2.	0.43	w	Ducts	Mechanical Room	metal (g)			
3.	0.51	w	M	conduits	g			
4.	0.43	orange	M	conduits (g)		File File Line.		
5.	0.66	orange	M	File tanks				
6.	1.61	yellow	concrete barrier	(g)		Mechanical Room. Co LF.		
7.	0.56	w	M	column	(g)			
8.	0.63	black	M	handrails	(g)	Leading 2nd level.		
9.	0.81	grey	M	steps	(g)			
10 0.	0.54	black	concrete	glaz	markings			
1.	0.91	green	plaster wall	(g)		2nd level.		
2.	UNK							
3.	0.52	light green	M	computer room	g	Window frame		
4.	0.35	black	M	hand rail	g	Room 203		
5.	0.54	yellow	concrete	paint	g			
6.	1.16	black	M	hand rail	g	2nd level - north.		1 each
7.	0.38	1/2 w	M	conduits	g			
8.	0.68	tan	M	shelves frame	g	2nd level.		
9.	1.06	black	M	rollings		2nd level - above boilers, stair well.		
11 0.	ERROR							
1.	↓							
2.	0.27	w	concrete wall	g		Bldg #1 Basement interior (N)		
3.	0.64	w	M	water line (g)	sprinkler	loading docks area		
4.	0.95	yellow	concrete	stripping	(g)			
5.	0.37	tan	wood	door	g			
6.	0.48		metal	frame				
7.	0.43	w	M	window	g	frame		
8.	0.24	w	M	double doors		Bldg		
9.	0.71	l	l	frames	(g)			
12 0.	0.47	w	M	beam	g			

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: Department of Veterans Affairs	ADDRESS: 3350 La Jolla Village San Diego CA
SCOPE OF PROJECT: VA - Hospital	DATE: 10-29-14
INSPECTOR: Francisco Barrera	XRF SERIAL #: PROJECT NUMBER: P14320.14

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITION	LOCATION	QUANTITY	COMMENTS
9 1.	0.09	w	concrete	wall	g	North		
2.	0.43	w	Ducts	Mechanical Room	metal (g)			
3.	0.51	w	M	conduits	g			
4.	0.43	orange	M	conduits (g)		File File Line.		
5.	0.66	orange	M	File tanks				
6.	1.61	Yellow	concrete	barriers (g)		Mechanical Room. Co LF.		
7.	0.56	w	M	column (g)				
8.	0.63	black	M	Hand Rails (g)		Leading 2nd level.		
9.	0.81	grey	M	steps (g)				
10 0.	0.54	Black	M	concrete	g	graze markings		
1.	0.91	Green	Plaster	wall (g)		2nd level.		
2.	UNK							
3.	0.52	Light Green	M	computer	g	Window frame		
4.	0.35	black	M	Hand Rail	g	Room 203.		
5.	0.54	Yellow	concrete	paint	g			
6.	1.16	black	M	Hand Rail	g	2nd level - North.		Leach
7.	0.38	1/2 w	M	conduits	g			
8.	0.68	tan	M	shelves frame	g	2nd level.		
9.	1.06	black	M	Rollings		2nd level - above boiler, stair well.		Leach
11 0.	ERR							
1.	↓							
2.	0.27	w	concrete	wall	g	Bldg #1 Basement interior (N)		
3.	0.64	w	M	water line (g)		sprinkler. Loading dock's area		
4.	0.95	Yellow	concrete	stripping (g)				
5.	0.37	tan	wood	door	g			
6.	0.48		Metal	frame				
7.	0.43	w	M	window	g	frame		
8.	0.24	w	M	double doors.		Bldg		
9.	0.71	l	l	frames (g)				
12 0.	0.47	w	M	beam	g			

By: Francisco Barrera

Title: Sampling tech

Page 4 of 4

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Department of Veterans Affairs</u>	ADDRESS: <u>3350 La Jolla Village San Diego CA</u>
SCOPE OF PROJECT: <u>VA-Hospital</u>	DATE: <u>10-29-14</u>
INSPECTOR: <u>Francisco Barrera</u>	XRF SERIAL #: <u></u> PROJECT NUMBER: <u>PH320-VH</u>

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITION	LOCATION	QUANTITY	COMMENTS
12.1.	0.15	ble	concrete wall	w		interior Bldg 7	basement	
2.	0.04	w	drywall wall	g				
3.	0.11	w	fiberglass ceiling tiles	g.				
4.	0.18	blue	drywall wall	(g)				
5.	0.37	l	u	column	l			
x 6.	1.14	yellow	u	hand rail (g)			7 each.	
7.	0.62	w	u	beam	g			
8.	0.40	w	u	Hand Rail (g)		storage 2nd level		
9.	0.15	w	u	Ducts (g)				
x 13.0.	1.46	tan	u	sprinklers (g)		throughout.		
x 1.	1.31	l	l	l		B254		
2.	1.70	tan	plaster wall	(g)				
3.	0.08	l	drywall wall	l				
4.	0.20	l	l	l				
5.	0.46	l	concrete	l				
6.	unk							
7.	0.44	tan	u	door frame (g)		B255		
8.	0.37	l	l	door	l			
9.	0.22	blue	drywall wall	(g)				
14.0.	0.59	w	u	door (g)				
1.	0.64	l	l	frame	l			
2.	2.46	w	concrete w	(g)				
3.	0.28	tan	drywall wall	east.				
4.	0.18	w	porcelain	sink g.				
5.	0.55	w	l	urinal g				
6.	0.18	w	l	toilet.				
7.	0.48	tan	u	partitions (g)				
x 8.	9.90	l	ceramic	cartridge		NEWS Rest Room - by warehouse		
9.	1.06	l	plaster wall	(g)				
15.0.	0.35	tan/multi color	"ixi" floor tile	RR NEWS.				

By: Francisco Barrera

Title: sampling tech

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: Department of veterans affairs	ADDRESS: 3350 La Jolla Village San Diego CA
SCOPE OF PROJECT: VA-Hospital	DATE: 6-29-14
INSPECTOR: Francisco Barrera	XRF SERIAL #: PROJECT NUMBER: P4320VJ

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITION	LOCATION	QUANTITY	COMMENTS
15.1	6.03	Yellow	concrete	floor striping		Warehouse Area		
2.	0.24	Black	drywall	wall paint	gl			
3.	0.24	tan	l	wall	(gl)			
x 4.	16.29	Yellow	M	column	(gl)	protection storage	8 each	
5.	0.01	tan	fiberglass	wall paneling	(gl)			
6.	0.21	tan	M	door	(gl)	S75		
7.	0.44	l	l	l	frame			
8.	0.14	tan	wood	wall paneling	(gl)			
9.	0.63	Yellow	metal	columns	(gl)	Adjacent to Room B223C		
16.0	0.36	w	fiberglass	2x2 fisher	ceiling tiles			
1.	0.17	tan	drywall	ceiling	(gl)			
2.	0.30	w	M	Fire extinguisher	can			
3.	0.04	tan	M	door	g	B223A		
4.	0.42	l	l	l	frame			
5.	0.07	Green	drywall	wall	(gl)	Textile CARE UNIT.		
6.	0.29	tan	l	l				
7.	0.08	green	l	wall	g			
8.	0.74	tan	metal	window frame	(gl)			
9.	0.99	tan	plaster	column	(gl)			
17.0	0.12	blue	ceramic	wall tile				
1.	0.31	tan	concrete	wall				
2.	0.73	w	concrete	wall		w exterior		
3.	0.03	black	M	drain pipe	(gl)			
4.	0.27	w	w	wall panel	(gl)			
5.	0.34	black	M	ladder	(gl)			
6.	0.66	gray	ceramic	tile wall	(gl)			
7.	0.57	w	M	EAD Box				
x 8.	11.01	w	ceramic	wall tile	(gl)	B122	soiled dish room	
x 9.	10.65	l	l	l		Confirmation		
18.0	2.57	Red	l	floor tile	(gl)			

By: Francisco Barrera

Title: sampling tech

Page 6 of 7

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Department of Veterans Affairs</u>		ADDRESS:	
SCOPE OF PROJECT: <u>VA Hospital</u>			DATE: <u>10-29-14</u>
INSPECTOR: <u>Francisco Barraza</u>	XRF SERIAL #:		PROJECT NUMBER: <u>P14320.011</u>

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COMPONENT	CONDITION	LOCATION	QUANTITY	COMMENTS
18	1.	0.16	tan	drywall	walls (g)	E wall.		
	2.	0.05	brown	1 wall	(g)			
	3.	0.02	blue	concrete floor	(g)			
	4.	0.13						
	5.	.						
	6.	.						
	7.	.						
	8.	.						
	9.	.						
19	0.	.						
	1.	.						
	2.	.						
	3.	.						
	4.	.						
	5.	.						
	6.	.						
	7.	.						
	8.	.						
	9.	.						
20	0.	.						
	1.	.						
	2.	.						
	3.	.						
	4.	.						
	5.	.						
	6.	.						
	7.	.						
	8.	.						
	9.	.						
21	0.	.						

By: Francisco Barraza

Title: Sampling tech



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-12-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
1.	1.01	R	Wood	G	conformation	Test Block		
2.	1.04	↓	↓	↓	↓	↓		
3.	.92	↓	↓	↓	↓	↓		
4.	-.27	Blue	Plaster		8th Floor Penthouse Elevator En Tit N	Wall		
5.	-.04	↓	↓	↓	↓	E		
6.	-.10	↓	↓	↓	↓	S		
7.	.01	↓	↓	↓	↓	W		
8.	-.25	W	↓	↓	↓	E Ceiling		
9.	.07	↓	Orange	↓	↓	W Beam		
10.	-.02	↓	↓	↓	↓	F		
1.	-.34	↓	↓	↓	↓	S		
2.	-.12	↓	↓	↓	↓	N		
3.	.10	Gray	Metal	↓	↓	N Electric Box		
4.	.01	↓	↓	↓	↓	W		
5.	.02	Gray	↓	↓	↓	S Door		
6.	.37	↓	↓	↓	↓	S Frame		
7.	.04	Blue	↓	↓	↓	S Conduit		
8.	.12	R	↓	↓	↓	E		
* 9.	25.14	Blk	↓	↓	↓	S Ladder	15 LF	
20.	.45	Blm	↓	↓	↓	S Vent		
1.	.57	Gray	Concrete	↓	↓	W Floor		
2.	.43	↓	↓	↓	↓	E		
3.	.47	Tan	Metal	↓	↓	S Motor		
4.	-.12	W	↓	↓	↓	N Light		
5.	.25	Blue	↓	↓	↓	N Motor		
6.	.34	Gray	↓	↓	↓	N		
* 7.	1.54	↓	↓	↓	↓	S Electric Tray	220 LF	
* 8.	1.05	Tan	↓	↓	↓	W	↓	30 LF
9.	.39	Blk	↓	↓	↓	S Pipe		
30.	.40	R	↓	↓	↓	S Hatch		

Louis Ponder

CDHP6409 1046

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-12-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
3 1.	-1.10	Blue	Plaster	G	Penthouse 7th Fl. <sup>Rm 7005</sup> Mech Rm Int'l	Wall		
2.	-.25					E		
3.	-.32					S		
4.	-.47					W		
5.	-.10	W				E	Ceiling	
6.	.17	Blue	Metal			S	Air Duct	
7.	.12					W		
8.	.58	Tan				E	Door	
9.	.77					E	Frame	
4 0.	.63	Blk				S	Door	
1.	.74					S	Frame	
* 2.	11.07	Grn				N	Stairs	200 $\phi$
* 3.	12.04					N	Hand Rail	100 LF
4.	.12	W				W	Lights	
5.	-.21	Gray				W	Electric Box	
6.	-.27	Tan				W		
7.	.14					W	Conduit	
8.	.20	R				W		
9.	.54	Grn				W	Window Frame	
5 0.	.11	Blue				N	Pipe	
* 1.	22.25					W	Ladder	40 <del>LF</del> LF
2.	.63	Tan				W	Cage	
3.	.51	Blm				N	Air Duct	
4.	.38					N	Motor	
5.	-.04	W				N	Tank	
6.	-.10					N	Pipe	
7.	.12	Brn				E	Electric Box	
8.	.25	Grn				E	Door	
9.	.31					E	Frame	
6 0.	.40					W	Tank	

Larry Ponder

CDHP6409 2016

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-12-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
61.	-.12	Blue	Plaster	G	Penthouse 7TH Fl. Rm7001	W	Wall	
2.	-.21	↓	↓	↓		E	↓	
3.	.01	↓	↓	↓		S	↓	
4.	-.04	↓	↓	↓		W	↓	
5.	.38	Gray	Concrete			E	Floor	
6.	-.25	W	Plaster			W	Ceiling	
7.	.34	Gray	Metal			W	Tank	
8.	.42	Brn	↓	↓		W	↓	
9.	-.22	W	↓	↓		N	↓	
70.	.15	BLK			Rm 7000	E	Door	
1.	.25	↓	↓	↓		E	Frame	
2.	.30	Blw	↓	↓		E	Vert	
3.	.58	↓	↓	↓		N	Elevator Door	
4.	.12	R	↓	↓		N	Conduit	
5.	.04	Blue	↓	↓		S	↓	
6.	.00	BLK	↓	↓		S	Bracket	
7.	.01	↓	↓	↓		S	Pipe	
8.	-.04	Blue	Drum			S	Support	
9.	.12	Tan	Metal			W	Door	
80.	.18	↓	↓	↓		W	Frame	
1.	.28	Gray	↓	↓		N	Door	
2.	.34	↓	↓	↓		N	Frame	
3.	.15	Gray	Concrete			W	Floor	
4.	.49	R	↓	↓		W	↓	
5.	-.20	Blue	Plaster		Rm 7005	E	Wall	
6.	-.31	↓	↓	↓		E	↓	
7.	-.10	↓	↓	↓		S	↓	
8.	-.15	↓	↓	↓		W	↓	
9.	.02	W	↓	↓		E	Ceiling	
90.	.10	Tan	Metal	↓	↓	E	Vert	

Louis Ponder

CDHP6409 3046

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-12-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
91.	-.23	Blue	Plaster	G	Penthouse Electric Rm 7003	N Wall		
2.	-.38	↓	↓	↓	↓	S Ceiling		
3.	-.07	W	↓	↓	↓	W Floor		
4.	.10	Gray	Metal	↓	↓	E Electric Box		
5.	.05	↓	↓	↓	↓	S ↓		
6.	.01	↓	↓	↓	↓	W ↓		
7.	.29	yellow	Concrete	↓	↓	W Floor		
8.	.18	Tan	Drywall	↓	5th Floor Corridor	N Wall		
9.	.10	↓	↓	↓	↓	E ↓		
100.	.11	↓	↓	↓	↓	S ↓		
1.	.15	↓	↓	↓	↓	W ↓		
2.	.50	↓	Metal	↓	↓	S Door		
3.	.36	↓	↓	↓	↓	S Frame		
4.	.02	Brn	Wood	↓	↓	N Floor		
5.	-.25	W	Drywall	↓	↓	S Ceiling		
6.	-.16	↓	Ceramic	↓	Restroom 5371	N Wall		
7.	.21	Grn	↓	↓	↓	S ↓		
8.	.12	Tan	↓	↓	↓	W ↓		
9.	.02	↓	↓	↓	↓	E Floor		
110.	.17	↓	Metal	↓	↓	E Door		
1.	.21	↓	↓	↓	↓	E Frame		
2.	.01	W	↓	↓	↓	W Light		
3.	-.08	↓	↓	↓	↓	S Vent		
4.	-.02	↓	Porcelain	↓	↓	S Sink		
5.	-.15	↓	↓	↓	↓	S Toilet		
6.	.10	Tan	Metal	↓	Room 5321A	E Door		
7.	.20	↓	↓	↓	↓	E Frame		
8.	.02	W	Drywall	↓	↓	N Wall		
9.	-.15	↓	↓	↓	↓	E ↓		
120.	-.21	↓	↓	↓	↓	S ↓		

Low Ponder

CDHP6409 4 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-12-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
121.	-.10	W	Metal	G	5TH Floor Rm 5321A	S Light		
2.	-.15	↓	↓	↓		E Vent		
3.	-.27	↓	↓	↓		W Grid		
4.	-.09	↓	↓	↓		E T-Grid		
5.	-.23	Tan	Drywall		Rm 5314	N Wall		
6.	-.27	↓	↓	↓		E ↓		
7.	-.03	↓	Metal			W Door		
8.	.07	↓	↓	↓		W Frame		
9.	.02	Brn	↓	↓		E window Frame		
130.	.22	Tan	Ceramic		Rm 5280	E Wall		
1.	.02	W	Porcelain			E Sink		
2.	.01	Tan	Drywall			N Wall		
3.	.10	↓	Metal			W Door		
4.	.07	↓	↓	↓		W Frame		
* 5.	1.02	Yellow	↓	↓	S. Corridor	S Bumper Guards	10 LF	
6.	-.04	Tan	Drywall			N Wall		
7.	.02	Brn	Wood			N Floor		
8.	.12	Tan	Metal			N Door		
9.	.15	↓	↓	↓		N Frame		
140.	.02	Grn	Ceramic		Rm 5106	W Wall		
1.	-.01	W	Porcelain			E Sink		
2.	.17	Grn	Metal			S Door		
3.	.21	↓	↓	↓		S Frame		
4.	.04	↓	↓	↓		S window Frame		
5.	-.07	↓	Drywall		Rm 5090A	N Wall		
6.	.02	Tan	Metal			E Door		
7.	.01	↓	↓	↓		E Frame		
8.	.01	W	↓	↓		W Light		
9.	.00	↓	↓	↓		N Vent		
150.	.04	Brn	↓	↓		N window Frame		

Louis Ponder

CDHP6409 5 of 6



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-12-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM.
* 151.	10.46	Grn	Ceramic	G	5TH Floor Rm 5003 MRN	Wall	5004	Also Rm 5009 WRA
2.	.27	↓	↓	↓		N Floor		
3.	.02	W	Porcelain			W Sink		
4.	-.04	↓	↓			W Toilet		
5.	.03	↓	↓			N Urinal		
6.	.10	Blue	metal			S Daverden Stall		
7.	.22	Tan	↓			N Door		
8.	.55	↓	↓			N Frame		
✓ 9.	.01	Grn	Drywall		Rm 5235	N Wall		
160.	.10	Tan	Metal			W Door		
1.	.17	↓	↓			W Frame		
2.	.02	W	Porcelain		Rm 5249	N Sink		
3.	.01	↓	↓			S Toilet		
4.	.03	W	Ceramic			N Wall		
5.	.02	Tan	↓		Rm 5252 SRR	N Wall		
6.	.04	↓	↓			N Floor		
7.	-.27	↓	Drywall			N Wall		
8.	-.21	↓	↓			N Ceiling		
✓ 9.	.07	Grn	↓		Rm 5021	N Wall		
170.	.01	Brn	Wood			N Floor		
1.	.12	Tan	metal			E Door		
2.	.14	↓	↓			S Frame		
3.	.10	BRK	↓			S Window Frame		
4.	.04	Tan	↓		W Corridor	S Window Panel		
5.	.10	BRK	↓			S Door Panel		
6.	.12	↓	↓			S Door		
7.	.08	↓	↓			S Frame		
8.	.02	Grn	Wood			S Wall		
✓ 9.	1.00	R	↓		confirmation	TEST Block		
180.	1.02	↓	↓	↓	↓	↓		

Lead Powder

CNHPC6409 6 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <i>Veterans Admin SA</i>	ADDRESS: <i>3350 La Jolla Village Dr.</i>
SCOPE OF PROJECT: <i>Hospital</i>	DATE: <i>11-13-14</i>
CONTACT: <i>Tammy Brent</i>	PHONE: <i>858-642-3920</i>
PROJECT NUMBER: <i>P14320.U11</i>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
1.	.90	R	wood	G	Confirmation	Test Block		
2.	1.04	↓	↓	↓	↓	↓		
3.	1.02	↓	↓	↓	↓	↓		
4.	-.22	Tau	Ceramic		4th Floor Area Rm 4300 RR N	Wall		
5.	.01	↓	↓			N Floor		
6.	.02	W	Porcelain			W Sink		
7.	.01	↓	↓			W Toilet		
8.	-.07	↓	Drywall			E Ceiling		
9.	.10	Tau	Metal			W Door		
10.	.15	↓	↓			W Frame		
1.	.01	W	↓			E Vent		
2.	.02	↓	↓			S Light		
3.	.03	Tau	Ceramic		Rm 4296 RR N	Wall		
4.	.21	↓	↓			N Floor		
5.	-.04	W	Drywall			W Ceiling		
6.	.02	↓	Porcelain			N Sink		
7.	.01	↓	↓			N Toilet		
8.	.08	Tau	Metal			W Door		
9.	.12	↓	↓			W Frame		
20.	-.10	W	Drywall		Rm 4294	N Wall		
1.	-.21	↓	↓			W ↓		
2.	.07	↓	Metal			E Vent		
3.	.02	Brn	Wood			S Cabinet		
4.	.11	Tau	Metal			W Door		
5.	.17	↓	↓			W Frame		
6.	.01		Drywall		Corridor 4390	N Wall		
7.	.10		Plaster			W ↓		
8.	.11		Metal			S Door		
9.	.15	↓	↓			S Frame		
30.	.01	W	↓	↓	↓	W Fire Box		

*Lead Powder*

*CDHP 6409 1 of 7*

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-13-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
31.	.03	W	Ceramic	G	4th Floor Area 1 <sup>Shower</sup> Rm 4320	N Wall		
2.	.07	↓	↓			N Floor		
3.	.10	Tan	Metal			W Door		
4.	.17	↓	↓			W Frame		
5.	.01	W	Drywall			E Ceiling		
6.	.07	Tan	Plaster		Area 2 <sup>Corridor</sup> 4000	N Wall		
7.	.01	↓	↓			S ↓		
8.	-.20	W	Metal			E T-Grid		
9.	.10	↓	↓			W Vent		
40.	.32	Tan	<del>Light</del>			N Elevator Door		
1.	.02	W	Metal			N Light		
2.	.10	Brn	↓			E Window Frame		
3.	.11	Tan	↓			S Door		
4.	.21	↓	↓			S Frame		
5.	.04	↓	Ceramic		Rm 4002 MR	N Wall		
6.	.02	Brn	↓			N ↓		
7.	-.07	Blue	↓			N ↓		
8.	.12	Tan	↓			N Floor		
9.	.01	W	Porcelain			S Sink		
50.	.02	↓	↓			N Toilet		
1.	.00	↓	↓			N Urinal		
2.	.14	Tan	Metal			N Door		
3.	.12	↓	↓			N Frame		
4.	-.21	W	Ceramic		<sup>Shower</sup> Rm 4011	N Wall		
5.	-.04	Tan	↓			N Floor		
6.	.66	↓	Tamato			N Catch Basin		
7.	-.67	W	Drywall			N Wall		
8.	.61	↓	Metal			N Locker		
9.	.56	↓	↓			E Cabinet		
60.	.10	BRK	↓			N Vent		

Lead Powder

CDHP6409 2 of 7

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-13-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
61.	.02	Tan	Plaster	G	4th Floor Area 3 Corridor 4110	W Wall		
2.	.07	↓	Drywall			W ↓		
3.	.25	BRN	Metal			W Window Frame		
4.	.77	W	↓			W Window Panel		
5.	-.34	Tan	Plastic			E Bumper Guard		
6.	.02	↓	Drywall		Rm 4157	N Wall		
7.	-.05	↓	↓			S ↓		
8.	.01	↓	↓			E Ceiling		
9.	-.21	BRN	Wood			W Floor		
70.	.02	↓	Metal			S Door		
1.	.01	↓	↓			S Frame		
2.	-.12	GRN	Drywall			W Wall		
3.	.21	BLK	Metal			N Window Frame		
4.	-.02	Tan	Ceramic		Rm 4157A RR	N Wall		
5.	-.04	↓	↓			N Floor		
6.	.01	↓	Drywall			W Ceiling		
7.	-.01	↓	Ceramic			S Shower Wall		
8.	-.05	↓	↓			W Floor		
9.	.02	W	Porcelain			N Sink		
80.	.01	↓	↓			N Toilet		
1.	.05	↓	Metal			S Vent		
2.	-.02	BRN	↓			E Door		
3.	-.05	↓	↓			E Frame		
4.	-.03	Tan	Ceramic		Rm 4136A	N Wall		
5.	.01	↓	↓			N Floor		
6.	.00	↓	↓			N Shower Wall		
7.	.02	↓	↓			N Floor		
8.	.01	W	Porcelain			W Sink		
9.	.02	↓	↓			W Toilet		
90.	.07	↓	Metal			S Vent		

Lead Powder

CDHP6409 3 of 7

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-13-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM.
* 91.	1.63	Tan	Ceramic	G	4th Floor Area 4 - Rm 4067 U	Wall	300#	* Ray Area
2.	.04	Bru	↓			N Floor		
3.	-.22	Tan	Drywall			N Ceiling		
4.	.02	W	Porcelain			E Sink		
5.	.01	↓	↓			E Toilet		
6.	.03	Tan	Metal			N Door		
7.	.02	↓	↓			N Frame		
8.	-.01		↓			S Light		
9.	.07	↓	↓			S Vent		
* 100.	10.10	↓	Drywall		Rm 4066	N Wall	600#	All by way of rooms
1.	.02	Bru	Wood			N Floor		
2.	.01	↓	↓			W Cabinet		
3.	.01	W	↓			W Counter top		
4.	.02	↓	Porcelain			W Sink		
5.	-.02	Gray	Wood			W Cabinet		
6.	.21	Blk	Metal			S Window Frame		
7.	-.02	Tan	Ceramic		Rm 4054 SRR	N Wall		
8.	.01	Bru	↓			N Floor		
9.	.01	W	↓ Drywall			W Ceiling		
110.	.02	↓	Porcelain			W Sink		
1.	-.01	↓	↓			W Toilet		
2.	-.21	Tan	Plaster		Rm 4039	N Wall		
3.	-.02	↓	↓			N ↓		
4.	.05		Metal			S Door		
5.	.07	↓	↓			S Frame		
6.	.15	Blk	↓			W Window Frame		
7.	.25	Tan	Ceramic		Area 5 Rm 4260 RRM	N Wall		
8.	.12	↓	↓			N Floor		
9.	.02	W	Porcelain			N Sink		
120.	.01	↓	↓			E Toilet		

Lead Powder

CDHP6409 4 of 7



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-13-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
124	-.03	Gray	Ceramic	G	4 <sup>th</sup> Floor-Area 5- Corridor 4263	N Wall		
2.	-.42	R	↓			W		
3.	.01	Tan	Drywall			E		
4.	.12	Blk	Metal			W Window Frame		
5.	-.27	Tan	Drywall		Rm 4270	N Wall		
6.	-.21	Brown	Wood			N Floor		
7.	.10	Tan	Metal			S Door		
8.	.12	↓	↓			S Frame		
9.	.02	Gray	Ceramic		Rm 4275	N Wall		
130.	-.04	R	↓		Kit	N		
1.	-.01	Gray	Wood			S Cabinet		
2.	-.08	Pink	↓			S Counter Top		
3.	.10	Tan	Metal			E Door		
4.	.15	↓	↓			E Frame		
5.	.07	↓	↓			E Vent		
6.	.02		Drywall		3 <sup>rd</sup> Floor-Area 1 Corridor 3011	N Wall		
7.	-.21	↓	↓			S		
8.	.10		Metal			N Door		
9.	.14	↓	↓			N Frame		
140.	-.24		Drywall		Rm 3399	N Wall		
1.	-.25		↓			E		
2.	.08		Metal			A Door		
3.	.12	↓	↓			N Frame		
4.	.18	Blk	↓			S Window Frame		
5.	.21	Tan	Ceramic		Rm 3399 ARR	N Wall		
6.	.09	↓	Ceramic			N Floor		
7.	-.08	W	Plastic			N Shower		
8.	.02		Porcelain			W Sink		
9.	.01	↓	↓			S Toilet		
150.	.07	Tan	Drywall			E Ceiling		

Louis Ponder

CDHP6409 5 of 7

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-13-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
151.	.02	Tan	Ceramic	G	3 <sup>rd</sup> Floor Area 1 - Rm 3382	RR NW Wall		
2.	.01	↓	↓			S Floor		
3.	-.02	W	Porcelain			E Sink		
4.	.03	↓	↓			W Toilet		
5.	.02	Tan	Drywall			↓ S Ceiling		
6.	-.21	W	↓		Rm 3357	N Wall		
7.	-.27	Blue	↓			E ↓		
8.	.10	Tan	Metal			W Door		
9.	.12	↓	↓			↓ W Frame		
160.	-.15	W	Drywall		Rm 3374	N Wall		
1.	-.25	↓	↓			S ↓		
2.	.15	Blk	Metal			S Window Frame		
3.	.10	Tan	↓			N Door		
4.	.11	↓	↓			↓ N Frame		
5.	.02	Gray	Ceramic		Rm 3374A	RR NW Wall		
6.	-.01	Tan	↓			N Floor		
7.	.01	W	Porcelain			S Toilet		
8.	.01	↓	↓			N Sink		
9.	-.47	↓	Plastic			↓ N Shower		
170.	-1.07	Tan	Ceramic		Area 2 Rm 3003	RR NW Wall		
1.	-.20	Bru	↓			N ↓		
2.	.12	Blue	↓			N ↓		
3.	.01	Tan	↓			N Floor		
4.	.02	W	Porcelain			N Sink		
5.	.03	↓	↓			E Urinal		
6.	.01	↓	↓			E Toilet		
7.	.05	↓	Metal			W Light		
8.	.07	↓	↓			S Vent		
9.	.12	Tan	↓			N Door		
180.	.08	↓	↓			N Frame		

Louis Ponder

CDHP6409 6 of 7

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-13-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
181.	.02	Brn	Ceramic	G	3 <sup>rd</sup> Floor Area 2 Rm 3090N	Wall		
2.	-.25	Tan	Metal			S Vent		
3.	.07	W				E Light		
4.	.12	Blk				E Window Frame		
5.	.25	Tan	Ceramic			N Floor		
6.	-.10	Brn	Wood			N		
7.	.20	Blk	Metal			N Door		
8.	.17					N Frame		
9.	.02	W	Ceramic		Rm 3005	N Wall		
190.	-.04	Tan	Tan			N Wash Basin		
1.	.25	Tan	Ceramic			N Floor		
2.	.01	W	Drumell			E Ceiling		
3.	.02	Tan			Corridor Rm 3015	N Wall		
4.	.04					S		
5.	.15	Blk	Metal			W Window Frame		
6.	.12	W				E Panel		
7.	1.04	R	Wood		CONFIRMATION	Test		
8.	1.00							
9.	.							
200.	.							
1.	.							
2.	.							
3.	.							
4.	.							
5.	.							
6.	.							
7.	.							
8.	.							
9.	.							
210.	.							

Larry Ponder

CDHP6409 7 of 7

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-14-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
1.	1.01	R	Wood	G	Confirmation	Test Stick		
2.	1.04	↓	↓	↓	↓	↓		
3.	1.00	↓	↓	↓	↓	↓		
4.	.02	Tan	Drywall		3 <sup>rd</sup> Floor Area 4 Rm 3038 A	Wall		
5.	-.20	↓	↓	↓	↓	E		
6.	-.12	↓	↓	↓	↓	S		
7.	.01	R	↓	↓	↓	W		
8.	.10	Tan	Metal			E Door		
9.	.17	↓	↓	↓	↓	E Frame		
10.	.01	W	↓	↓	↓	W Light		
1.	.02	↓	↓	↓	↓	E Vent		
2.	-.36	↓	Porcelain		↓	S Sink		
3.	-.27	Brn	Drywall		Rm 3029	W Wall		
4.	-.04	Tan	↓	↓	↓	E		
5.	-.10	↓	↓	↓	↓	S		
6.	-.12	↓	↓	↓	↓	W		
7.	.02	W	Metal			E T-Grid		
8.	.01	↓	↓	↓	↓	S Light		
9.	.01	↓	↓	↓	↓	W Vent		
20.	.07	Tan				S Door		
1.	.12	↓	↓	↓	↓	S Frame		
2.	.07	Blk	↓	↓	↓	N window frame		
3.	-.21	W	Porcelain		↓	W Sink		
4.	.01	Gray	Ceramic		Rm 3012	S Wall		
5.	-.23	Tan	Drywall			N		
6.	.01	↓	↓	↓	↓	E		
7.	-.11	↓	↓	↓	↓	S		
8.	-.10	↓	↓	↓	↓	W		
9.	.10	Tan	Metal			E Door		
30.	.18	↓	↓	↓	↓	E Frame		

Larry Ponder

CDHP6409 1 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-14-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
31.	-.31	Tan	Ceramic	G	3rd Floor Area 4-Rm 3089	RR NW Wall		
2.	-.11	Grn				N		
3.	-.07	Brn				N		
4.	-.12	Tan				N	Floor	
5.	.02	W	Pordaw			S	Sink	
6.	-.17	↓	↓			S	Toilet	
7.	.10	Tan	Drywall			S	Ceiling	
8.	.01	W	Metal			E	Light	
9.	.02	↓	↓			W	Unit	
40.	.12	Tan				N	Door	
1.	.10	↓	↓			N	Frame	
2.	-.22		Drywall		Corridor 3069	E	Wall	
3.	-.24		↓			W	↓	
4.	.12	↓	Metal			W	Window Frame	
5.	.10	W	↓			W	File Box	
6.	.02					N	Light	
7.	.04					W	Speaker	
8.	.01	↓	↓			S	Unit	
9.	.12	Blk				W	Door	
50.	.19					W	Frame	
1.	.34	↓	↓			W	Window Frame	
2.	.15	Tan	↓			W	Panel	
3.	.18	↓	↓			W	Door Panel	
4.	-.11		Drywall		Rm 3074	N	Wall	
5.	-.18					E		
6.	-.37					S		
7.	.01	↓	↓			W	↓	
8.	.15		Metal			S	Door	
9.	.21	↓	↓			S	Frame	
60.	.01	W	↓			W	Light	

Louis Ponder

CDHP6409 7 of 6



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-14-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
61.	.01	Tan	Drywall	G	3 <sup>rd</sup> Floor Area 3 Rm 3117 N	Wall		
2.	-.07					F		
3.	.00					S		
4.	.02					W		
5.	.03	Bra	Wood			E	Floor	
6.	.11	Tan	Metal			E	Door	
7.	.14					E	Frame	
8.	.20					E	Window Frame	
9.	.10	BLK				N		
70.	.02	Tan	Drywall		Corridor 3132	E	Wall	
1.	-.02					W		
2.	-.27		Plastic			W	Isopropyl Alcohol	
3.	.04	W	Metal			W	Fire Box	
4.	.01					S	Vent	
5.	.01					E	Light	
6.	.17	Tan				N	Door	
7.	.16					N	Frame	
8.	-.21		Drywall		Rm 3192 RR	N	Wall	
9.	.01					E		
80.	.00					S		
1.	-.04					W		
2.	-.08					E	Ceiling	
3.	.02	W	Porcelain			S	Sink	
4.	.01					S	Toilet	
5.	.10	Tan	Metal			N	Door	
6.	.11					N	Frame	
7.	.04					S	Vent	
8.	.01					N	Light	
9.	.02					E	Grill	
90.	.01					W	Light	

Lead Powder

CDHP6409 3 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-14-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
91.	-.07	Tan	Prghall	G	3 <sup>rd</sup> Floor Area 3-Rm 3185 N	Wall		
2.	-.02					E		
3.	.01					S		
4.	-.01					W		
5.	.08		Metal			W	Door	
6.	.11					W	Frame	
7.	.10					E	Door	
8.	.05					E	Frame	
9.	.02					N	Cabinet	
100.	-.08	W				E	Light	
1.	.10					S	Vent	
2.	.07					W	Grill	
3.	.02	Grn	Ceramic		Rm 3141 RR N	Wall		
4.	.01	Blk				N		
5.	.04	Tan				N		
6.	.21					N	Floor	
7.	.02	W	Porcln			N	Sink	
8.	-.01					N	Toilet	
9.	.20	Tan	Metal			S	Door	
100.	.18					S	Frame	
1.	.07					W	Light	
2.	-.28					E	Vent	
3.	.01		Prghall		Rm 3143 N	Wall		
4.	.00					E		
5.	-.07					S		
6.	.01		Wood				Cabinet	
7.	-.04	Gray					Counter Top	
8.	-.15	Bra					Floor	
9.	.12	Tan	Metal				Door	
120.	.18						Frame	

Lead Powder

CDHP6409 4 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-14-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
121.	.01	Tan	Drywall	G	3rd Floor-Area 5 - Rm 3286A	Wall		
2.	-.04					E		
3.	.00					S		
4.	-.12					W		
5.	.10		Metal			W	Door	
6.	.11					W	Frame	
7.	.02		Ceramic		Rm 3271	N	Wall	
8.	.25	Pink	Terrazo			N	Floor	
9.	-.27	Tan	Drywall			N	Wall	
130.	.01					S	Ceiling	
1.	.15		Metal			W	Door	
2.	.08					W	Frame	
3.	.21	W				E	Cabinet	
4.	.24					N		
5.	.02	Gray	Ceramic		Rm 3276	RR N	Wall	
6.	.08	Tan			3274	N	Floor	
7.	.01		Drywall			N	Wall	
8.	.00					E		
9.	-.07					S		
140.	.02					W		
1.	.07					W	Ceiling	
2.	.01	W	Porcelain			E	Sink	
3.	.02					E	Toilet	
4.	.19	Tan	Metal			N	Door	
5.	.12					N	Frame	
6.	.07					W	Vent	
7.	-.01					S	Light	
8.	.10	Tan				N	T-Grid	
9.	.21					N	Bracket	
150.	.07					S	Grill	

Lead Powder

CDHP6409 5 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>11-14-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
151.	-.20	Tan	Drywall	G	3rd Floor Area S Rm 3282	N Wall		
1.	-.01		↓			S ↓		
3.	.02		↓			W ↓		
4.	-.07		Metal			S Door		
5.	.02	↓				S Frame		
6.	.10	BLK	↓			N Window Frame		
7.	.00	Gray	↓			E Cabinet		
8.	-.25	Tan	Drywall		Rm 3273C	N Wall		
9.	.02	↓	↓			S ↓		
160.	.10	Rvn	Wood			E Cabinet		
1.	.07	↓	↓			E counter top		
2.	.12	BLK	Metal			N Door		
3.	.15	↓	↓			N Frame		
4.	.10	↓	↓			N Window Frame		
5.	.01	Gray	Ceramic		Rm 3252	N Wall		
6.	.06	Tan	↓			N Floor		
7.	-.27	W	Plastic Shower			N Wall		
8.	.10	Tan	Metal			S Door		
9.	.15	↓	↓			S Frame		
170.	.01	W	Porcelain			E Sink		
1.	.02	↓	↓			W Toilet		
2.	.02	Gray	Ceramic		Rm 3301 RR	N Wall		
3.	.07	↓	↓			N Floor		
4.	.01	W	Porcelain			W Sink		
5.	.02	↓	↓			E Toilet		
6.	.01	Tan	Drywall			N Wall		
7.	.00	↓	↓			W ceiling		
8.	.05	W	metal			E Cigarette		
9.	1.10	R	wood		Confirmation	Test Block		
180.	1.01	↓	↓		↓	↓		

Larry Ponder

CDHP6409 6046

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-1-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
1.	1.00	R	Wood	G	Confirmation	Test Block		
2.	1.04	↓	↓		↓	↓		
3.	1.01	↓	↓		↓	↓		
* 4.	15.33	Orange	Metal		5th Floor Intertitial	N Catwalk	9200LF	
5.	.09	Gray	↓			N Floor		
6.	.21	W	Concrete			N Ceiling		
7.	.37	Gray	Metal			N Door		
8.	.61	↓	↓			N Frame		
9.	.24	Gray	↓			E Door		
10.	.52	↓	↓			E Frame		
1.	.43	↓	↓			W Door		
2.	.60	↓	↓			W Frame		
3.	.19	↓	↓			S Door		
4.	.89	↓	↓			S Frame		
5.	.01	W	↓			N Light		
6.	.02	↓	↓			E ↓		
7.	.00	↓	↓			S ↓		
8.	.01	↓	↓			W ↓		
9.	.12	Gray	↓			N Electric Box		
10.	.10	↓	↓			E ↓		
1.	.08	↓	↓			S ↓		
2.	.04	↓	↓			W ↓		
3.	.21	Yellow	↓			S Floor		
4.	.10	Gray	↓			N Air Duct		
5.	.15	↓	↓			S ↓		
6.	.08	↓	↓			E ↓		
7.	.12	↓	↓			W ↓		
8.	.24	BLK	↓			N Pipe		
9.	.27	R	↓			N Conduit		
10.	.12	BLK	↓			N Pipe		

Lead Powder

CDHP6409 1 of 5



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-1-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
31.	.07	Gray	Metal	G	5th Floor Intertitial	N Brace		
2.	.29	Grn	↓			N Box		
3.	.11	W	↓			S Cordint		
* 4.	4.61	yellow	Wood			S Signs	40 Ea	
5.	—					40 Ea		Void
6.	—					Plaster		Void
7.	.14	W	Plaster			N Wall		
8.	.12					E ↓		
9.	.05					S ↓		
40.	.10					W ↓		
1.	.24	Gold	Metal			N Door		
2.	.47	↓	↓			N Frame		
3.	.52	↓	↓			S Elevator Door		
* 4.	14.77	Orange	↓		6th Floor	S cat walk	9200 LF	
* 5.	4.12	yellow	Wood			W Signs	40 Ea	
6.	.07	Gray	Metal			E Floor		
7.	.21	yellow	↓			S ↓		
8.	.17	Grn				N Door		
9.	.41	↓	↓			N Frame		
50.	.15	Gray				E Door		
1.	.52	↓	↓			E Frame		
2.	.12	Grn				S Door		
3.	.38	↓	↓			S Frame		
4.	.15	Orange				N Door		
5.	.47	↓	↓			N Frame		
6.	.00	W				N Light		
7.	.01					E ↓		
8.	.01					S ↓		
9.	.02	↓	↓			W ↓		
60.	.17	BLK	↓			E Pipe		

Low Powder

CDHP6409 2045

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-1-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
61.	.12	Gray	Metal	B	6 <sup>th</sup> Floor Intertitil	N Electrics		
2.	.07					E		
3.	.10					S		
4.	.05					W		
5.	.18	R				E	Conduit	
6.	.21	W				W		
7.	.32	R				E	Pipe	
8.	.15	Orange				S	Bracker	
9.	.07	Gray				N	HV Duct	
70.	.05					E		
1.	.09					S		
2.	.02					W		
3.	.15	W	Plaster			N	Wall	
4.	.12					E		
5.	.07					S		
6.	.10					W		
7.	.08		Concrete			N	Ceiling	
8.	07.12	orange	Metal		3 <sup>rd</sup> Floor	W	Cat Walk	9,200 LF
9.	4.21	yellow	wood			E	Signs	40 Ea
80.	.18	Gray	Metal			N	Floor	
1.	.41	yellow				S		
2.	.12	Grn				N	Door	
3.	.37					N	Frame	
4.	.15					S	Door	
5.	.47					S	Frame	
6.	.08	Gray				E	Poor	
7.	.27					E	Frame	
8.	.17	Orange				N	Door	
9.	.49					N	Frame	
90.	.21	Grn				N	Rack	

Lead Powder

CDHP6409 3 of 5

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-1-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
91.	.01	W	Metal	G	3rd Floor Intertial	N Light		
2.	.00					S		
3.	.02					E		
4.	.04					W		
5.	.05	Gray				N	↓	
6.	.01					E		
7.	.03					S		
8.	.02					W		
9.	.12					N	Electrical Box	
10.	.10					E		
1.	.07					S		
2.	.11					W		
3.	.15	W	Concrete			S	Ceiling	
4.	.12		Plaster			N	Wall	
5.	.07					E		
6.	.09					S		
7.	.07					W		
8.	.20	R	Metal			N	conduit	
9.	.14	W				S		
10.	.07	B/K				E	Pipe	
1.	.12	R				W		
* 2.	16.17	Orange			4th Floor	N	cat walk	9,200 LF
* 3.	5.02	Yellow	Wood			S	Signs	40 Ea
4.	.17	Gray	Metal			E	Floor	
5.	.40	Yellow				W		
6.	.12	Gray				E	Door	
7.	.45					E	Frame	
8.	.18	Grn				N	Door	
9.	.49					N	Frame	
120.	.21					S	Cage	

Larry Ponder

CDHP6409 4 of 5

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <i>Veterans Admin SA</i>	ADDRESS: <i>3350 La Jolla Village Dr.</i>
SCOPE OF PROJECT: <i>Hospital</i>	DATE: <i>12-1-14</i>
CONTACT: <i>Tammy Brent</i>	PHONE: <i>858-642-3920</i>
PROJECT NUMBER: <i>P14320.U11</i>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
121.	.12	Grn	metal	G	4th Floor Intertial	S Door		
2.	.38	✓				S Frame		
3.	.15	Orange				N Door		
4.	.42	✓	✓			N Frame		
5.	.40	✓	✓			S Elevator		
6.	.00	W				N Light		
7.	-.02					E		
8.	-.04					S		
✓ 9.	.01	✓				W		
130.	.02	Gray				N A/Duct		
1.	.04					E		
2.	.07					S		
3.	.02					W		
4.	.12					N Electric Box		
5.	.10					E		
6.	.18					S		
7.	.15	✓	✓			W		
8.	.10	W				N Conduit		
✓ 9.	.17	R				E		
140.	.09	Blk				S Pipe		
1.	.17	R				W		
2.	.08	W	Plaster			N Wall		
3.	.10					E		
4.	.07					S		
5.	.17					W		
6.	.10	✓	Concrete			N Ceiling		
7.	.39	Orange	metal			S Bracket		
8.	.43	✓	✓			S Cage		
✓ 9.	1.01	R	wood		confirmation	Testicle		
150.	1.07	✓	✓	✓	✓	✓		

*Lead Powder*

*CDHP6409 5 of 5*

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-2-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
1.	1.06	R	Wood	G	Confirmation	Test Block		
2.	1.00	↓	↓	↓	↓	↓		
3.	.92	↓	↓	↓	↓	↓		
4.	15.34	Orange	Metal		1st Floor Intertitil	N Cat walk	9800 LF	
5.	5.20	Yellow	Wood			N Signs	40 EA	
6.	.12	Gray	Metal			S Floor		
7.	.21	Yellow	↓			S ↓		
8.	.07	W	concrete			W Ceiling		
9.	25.91	Orange	Metal			S Cage	12 LF	
10.	.07	Blk	↓			S Bracket		
11.	.04	Blk	↓			S Cage		
12.	.17	Grn	↓			S ↓		
13.	.15	Gold	↓			N Door		
14.	.43	↓	↓			N Frame		
15.	.12	Gray	↓			E Door		
16.	.34	↓	↓			E Frame		
17.	.19	↓	↓			W Door		
18.	.49	↓	↓			W Frame		
19.	.21	Grn	↓			S Door		
20.	.47	↓	↓			S Frame		
21.	.51	Orange	↓			S Elevator		
22.	.02	W	Plaster			N Wall		
23.	.04	↓	↓			E ↓		
24.	.07	↓	↓			S ↓		
25.	.01	↓	↓			W ↓		
26.	.10	Blk	metal			N Pipe		
27.	.17	R	↓			E ↓		
28.	.12	↓	↓			S conduit		
29.	.21	W	↓			W ↓		
30.	.07	↓	↓			N ↓		

Low Ponder

CDHP6409 1 of 6



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-2-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
31.	.07	Gray	Metal	G	1st Floor Intertitil	N Air Duct		
2.	.04					E		
3.	.08					S		
4.	.02					W		
5.	.11					N Electric Box		
6.	.15					E		
7.	.10					S		
8.	.12					W		
9.	16.27	Orange			2nd Floor	S cat walk	9200LF	
40.	5.07	yellow wood				S Signs	40 Ea	
1.	21.43	orange	Metal			S Cage	15 LF	
2.	.20	BK				N		
3.	.10	Grn				S		
4.	.15	Gold				N Door		
5.	.41					N Frame		
6.	.17	Gray				W Door		
7.	.49					W Frame		
8.	.12	Grn				E Door		
9.	.34					E Frame		
50.	.17					S Door		
1.	.51					S Frame		
2.	.48	Orange				S Elevator Door		
3.	.04	Gray				N Air Duct		
4.	.01					E		
5.	.05					S		
6.	.04					W		
7.	.10					N Electric Box		
8.	.14					E		
9.	.08					S		
60.	.12					W		

Lead Powder

CDHP6409 2 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-2-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
61.	.07	W	Plaster	G	2 <sup>nd</sup> Floor Intertitial	N Wall		
2.	.04					E		
3.	.10					S		
4.	.03					W		
5.	.21		Concrete			S Ceiling		
6.	.07	BLK	Metal			N Pipe		
7.	.12	R				E		
8.	.10					S Conduit		
9.	.17	W				W		
70.	.03	R	Wood			N Cost		
1.	.02					S Rack		
2.	.51	Gray	Metal		Basement	N Cat Walk		
3.	.43					N Bracket		
4.	.52					N Hand Rail		
5.	.49					N Floor		
6.	.10	W	Concrete			N Ceiling		
7.	.02		Metal			N Light		
8.	.01					E		
9.	-.04					S		
80.	.02					W		
1.	.40	BLK				E Ladder		
2.	.10	W	Wood			E Hatch		
3.	.15		Metal			E Beam		
4.	.10					E Column		
5.	.21	Tan				N Door		
6.	.34					N Frame		
7.	.02	W	Drywall			N Wall		
8.	.01					E		
9.	.01					W		
90.	.02		Wood			S Ceiling		

Lead Powder

CDHP6409 3 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-2-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
91.	.12	BLK	Metal	G	Basement Intertitil	N Pipe		
2.	.21	R	↓			W Conduit		
3.	.09	W	↓			S ↓		
4.	.07	Grny	↓			N A/Duct		
5.	.04		↓			E ↓		
6.	.02		↓			S ↓		
7.	.09	↓	↓			W ↓		
8.	.12	W	↓			E Bracket		
9.	.10	Brn	↓			W ↓		
100.	-.08	Tan	Drywall		2nd Floor North Restroom Area 1	W Wall		
1.	-.02		↓			E ↓		
2.	.01		↓			S ↓		
3.	-.04		↓			W ↓		
4.	-.27	↓	Metal			N T-Grid		
5.	.12		↓			W Door		
6.	.18	↓	↓			W Frame		
7.	.10	↓	↓			E Vent		
8.	.02	W	↓			S Light		
9.	.01		Porcelain			S Sink		
110.	.03	↓	↓			S Toilet		
1.	.02		Drywall		Rm 2416	N Wall		
2.	.02		↓			E ↓		
3.	.01		↓			S ↓		
4.	.01	↓	↓			W ↓		
5.	.01	↓	Metal			E T-Grid		
6.	.12		↓			S Vent		
7.	.04	↓	↓			E Light		
8.	.15	Tan	↓			N Door		
9.	.19	↓	↓			W Frame		
120.	.01	W	↓	↓	↓	N Grill		

Laws Ponder

CNHPC.409 U of L

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-2-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
121.	-.07	Tan	Drywall	G	2 <sup>nd</sup> Floor Area 1 North Rm 2393 N	Wall		
2.	-.02					W		
3.	.01		Metal			S	Door	
4.	.02					N	Frame	
* 5.	2.86	W	Porcelain			N	Sink	1 Ea
6.	.10	Brown	Wood			N	Floor	
7.	.21	Tan	Drywall		Corridor 2190 W	Wall		
8.	.07					E		
9.	.12	Blk	Metal			N	Door	
130.	.19					N	Frame	
1.	.04					N	Window Frame	
2.	.25	Tan	Plaster		Area 2 2000 N	Wall		
3.	.12					E		
4.	.14					S		
5.	.19					W		
6.	.07		Metal			W	Door	
7.	.09					W	Frame	
8.	.51					N	Elevator Door	
9.	-.07	R				E	Fire Box	
140.	-.02	Blk				W	Window Frame	
1.	.10	Tan				N	Display Case	
2.	-.25	W				E	Citipak Case	
3.	.25		Plaster		2009 N	Wall		
4.	.18					E		
5.	.47					S	Ceiling	
6.	.21	Pink	Tarnish			N	Basin	
7.	.02	W	Wood			E	Cabinet	
8.	.07		Metal			S	Vent	
9.	.04					W	Light	
150.	.08					N	Grill	

Low Ponder

CNH P6409 5 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-2-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
151.	-1.15	Tan	Ceramic	G	2 <sup>nd</sup> Floor Area 3 Rm 2218	W	Wall	
2.	-.21		↓			E	Floor	
3.	.16		↓ Drywall			S	Wall	
4.	.20		↓			W	↓	
5.	.11		↓			E	Ceiling	
6.	.15		↓ Metal			W	Door	
7.	.19		↓			W	Frame	
8.	.02	W	↓			E	Light	
9.	.01		↓			S	Vent	
160.	.02	Grn	Drywall		Rm 2240	N	Wall	
1.	-.04		↓			W	↓	
2.	.12	Tan	Metal			E	Door	
3.	.17		↓			E	Frame	
4.	.02	W	↓			N	Vent	
5.	.08		↓			E	Light	
6.	.01		↓			W	T-Grid	
7.	.02	Blue	Drywall		Rm 2242	N	Wall	
8.	-.07		↓			S	↓	
9.	.10	Tan	<del>Wood</del> Metal			E	Door	
170.	.18		↓ Metal			E	Frame	
1.	-.02	Brn	Wood			S	Cabinet	
2.	.01	Tan	Drywall		Rm 2230	N	Wall	
3.	-.04		↓			W	↓	
4.	.10		↓ Metal			N	Door	
5.	.17		↓			N	Frame	
6.	.02	W	Porcelain			E	Sink	
7.	.01		↓			W	Toilet	
8.	.11	Tan	Metal			E	Vent	
9.	1.00	R	Wood		Confirmation		Test Block	
180.	1.04		↓				↓	

Lead Powder

CDHP6409 6046



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-3-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM.
1.	1.06	R	wood	G	Confirmation	Test		
2.	1.11	↓	↓	↓	↓	↓		
3.	1.01	↓	↓	↓	↓	↓		
4.	.07	Tan	Drywall		2 <sup>nd</sup> Floor Area 4 Rm 2042	Wall		
5.	.12	↓	↓	↓	↓	E		
6.	.14	↓	↓	↓	↓	S		
7.	.10	↓	↓	↓	↓	W		
8.	.12	Tan	Metal			S Door		
9.	.32	↓	↓	↓	↓	S Frame		
10.	.10	↓	↓	↓	↓	W T-Grid		
1.	.02	↓	↓	↓	↓	S Vent		
2.	.04	W	Porcelain			E Sink		
3.	.02	↓	↓	↓	↓	E Toilet		
4.	.07	Tan	Drywall		Rm 2069	Wall		
5.	.04	↓	↓	↓	↓	E		
6.	.10	↓	↓	↓	↓	S		
7.	-.02	↓	↓	↓	↓	W		
8.	-.07	Brn	wood			E Floor		
9.	-.12	Grn	↓	↓	↓	E Cabinet		
20.	-.10	Gray	↓	↓	↓	E Counter Top		
1.	.02	W	Metal			S Light		
2.	.10	↓	↓	↓	↓	E Vent		
3.	.07	↓	↓	↓	↓	W Grill		
4.	.01	Tan	Drywall		Rm 2108	Wall		
5.	.12	↓	↓	↓	↓	E		
6.	.02	↓	↓	↓	↓	S		
7.	.10	↓	↓	↓	↓	W		
8.	-.02	↓	wood			E Trim		
9.	.07	Brn	↓	↓	↓	S Floor		
30.	.10	Tan	Metal	↓	↓	N Door		

Law Ponder

CNHPC6409 1 of 4

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-3-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
31.	.12	Tan	Ceramic	G	2nd Floor Area 5 Rm 2245 N	Wall		
2.	.21	Blau	↓			N ↓		
3.	.07	Brn	↓			N ↓		
4.	.02	Tan	↓			S Floor		
5.	.11	W	Drywall			E Ceiling		
6.	.02	↓	Metal			W Light		
7.	.04	↓	↓			N Vent		
8.	.10	↓	↓			S Grill		
9.	.02	↓	Porcelain			N Sink		
40.	.04	↓	↓			N Toilet		
1.	-.01	↓	↓			N Urinal		
2.	.10	Tan	Metal			E Door		
3.	.21	↓	↓			E Frame		
4.	.12	↓	Drywall		Rm 2263 N	Wall		
5.	.07	↓	↓			E ↓		
6.	.08	↓	↓			S ↓		
7.	.10	↓	↓			W ↓		
8.	.02	W	Porcelain			N Sink		
9.	.01	↓	↓			S Toilet		
50.	.10	Tan	Metal			E Door		
1.	.34	↓	↓			E Frame		
2.	.12	↓	Drywall		Corridor 2246 N	Wall		
3.	.07	↓	↓			S ↓		
4.	.10	W	Metal			W Light		
5.	.12	↓	↓			E Vent		
6.	.11	↓	↓			S Grill		
7.	.17	Tan	↓			N Door		
8.	.31	↓	↓			N Frame		
9.	.12	↓	↓			S Door		
60.	.27	↓	↓	+		S Frame		

Lead Powder

CDHP6409 ZOF4

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-3-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
61.	.02	Blue	Ceramic	G	6TH Floor Area 2 Rm 6011W	Wall		
1 2.	.04	BRN				N		
3.	.02	Tau				N		
4.	-.02	↓	↓			N		Floor
5.	.10	W	Drywall			W		Ceiling
6.	.08		Metal			N		Light
7.	.07					S		Vent
8.	.01	↓	↓			W		Grill
9.	.02	W	Porcelain			W		Sink
70.	-.02	↓	↓			W		Toilet
1.	.10	Tau	Metal			E		Door
2.	.31	↓	↓			E		Frame
3.	.21		Plaster		corridor 6000	NW		Wall
4.	.07					E		
5.	.20					S		
6.	.12	↓	↓			W		↓
7.	.17		Metal			E		Door
8.	.34					E		Frame
9.	.10					W		Door
80.	.32					W		Frame
1.	.51	↓	↓			N		Elevator Door
2.	.07	W				E		Vent
3.	.01					W		Grill
4.	.00					S		T-Grid
5.	-.02	↓	↓			N		Light
6.	-.01	Tau	Wood			E		Cabinet
7.	.01	↓	↓			E		Counter
8.	.04	BLK	Metal			S		Window Frame
9.	.10	Tau	↓			S		Panel
90.	.08	R	↓			E		Fire Panel

Low Ponder

CNHP6409 3 of 4

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-3-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
91.	.10	Tan	Drywall	G	6 <sup>th</sup> Floor Area 2 <sup>Pm</sup> 6014 N	Wall		
2.	.08	↓	↓			E		
3.	.04	↓	↓			S		
4.	.02	↓	↓			W		
5.	.02	W	Metal			S	Light	
6.	-.01	↓	↓			E	Vent	
7.	.01	↓	↓			W	Grill	
8.	.12	Tan	↓			S	Door	
↓ 9.	.31	↓	↓			S	Frame	
100.	.02	W	Ceramic		Pm 6010 N	Wall		
1.	-.02	Pink	Tamiro			N	Basin	
2.	.01	W	Plaster			N	Wall	
3.	.02	↓	↓			E		
4.	.02	↓	↓			S		
5.	-.02	↓	↓			W		
6.	.02	↓	↓			E	Ceiling	
7.	-.01	↓	Wood			E	Cabinet	
8.	.10	Tan	Metal			W	Door	
↓ 9.	.34	↓	↓			W	Frame	
110.	.10	W	↓			E	Light	
1.	.08	↓	↓			S	Vent	
2.	.11	↓	↓			N	Grill	
3.	.10	Tan	Drywall		Pm 6008 N	Wall		
4.	.07	↓	↓			E		
5.	.04	↓	↓			S		
6.	.07	↓	↓			W		
7.	.11		Metal			W	Door	
8.	.30	↓	↓			W	Frame	
↓ 9.	1.00	R	Wood		confirmation	Test block		
120.	.92	↓	↓		↓	↓		

Lany Ponder

CDHP 6409 4 of 4

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-17-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
1.	1.01	R	Wood	G	confirmation	Test Block		
2.	.92	↓	↓	↓	↓	↓		
3.	1.07	↓	↓	↓	↓	↓		
4.	.02	W	↓	↓	1 <sup>ST</sup> Floor-Area 1-Rm 1396	N Wall		
5.	-.04	Grn	↓	↓	↓	E		
6.	-.01	↓	Drywall	↓	↓	S		
7.	.01	Tan	↓	↓	↓	W		
8.	.02	↓	Metal	↓	↓	S	Door	
9.	.01	↓	↓	↓	↓	S	Frame	
10.	.02	W	↓	↓	↓	N	T-Grid	
1.	.10	↓	↓	↓	↓	E	Unit	
2.	.01	↓	↓	↓	↓	S	Light	
3.	.08	↓	↓	↓	↓	W	Grill	
4.	-.12	Brn	Wood	↓	↓	N	Wall	
5.	-.07	Grn	↓	↓	↓	N	↓	
6.	.02	W	Metal	↓	↓	S	Fire Box	
7.	.04	↓	Ceramic	↓	↓	N	Wall	
8.	.01	Blau	↓	↓	↓	N	↓	
9.	-.02	Gray	↓	↓	↓	N	Floor	
20.	.04	W	Wood	↓	↓	W	Cabinet	
1.	.10	↓	↓	↓	↓	N	Door	
2.	.12	↓	↓	↓	↓	N	Frame	
3.	.02	Gray	Ceramic	↓	↓	N	Counter Top	
4.	.06	Brn	↓	↓	Rm 1391	N	Wall	
5.	.01	Tan	↓	↓	↓	N	↓	
6.	.02	↓	↓	↓	↓	N	Floor	
7.	-.01	W	Porcelain	↓	↓	W	Sink	
8.	-.02	↓	↓	↓	↓	W	Toilet	
9.	-.10	↓	↓	↓	↓	E	Urinal	
30.	.04	↓	Drywall	↓	↓	S	Ceiling	

Lead Powder

CDHP6409 1 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-17-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
3 1.	-.04	W	Drywall	G	1 <sup>ST</sup> Floor - Area 1 - Rm 1414 N	Wall		
2.	-.02	↓	↓			W ↓		
3.	.01	BRN	Wood			N Trim		
4.	.02	W	Drywall			N Ceiling		
5.	-.04	BRN	Wood			N Trim		
6.	-.12	↓	↓			N Bench		
7.	.07	↓	↓			N Light		
8.	.02	BRN	Metal			E Door		
9.	.04	↓	↓			E Frame		
4 0.	-.02	BRN	Wood			W Window Frame		
1.	.01	Gray	↓		Rm 1355	U Wall		
2.	.02	↓	↓			E ↓		
3.	-.04	BRN	↓			W Floor		
4.	.02	W	Drywall			N Ceiling		
5.	-.02	Gray	Wood			W Cabinet		
6.	-.01	↓	↓			E Counter Top		
7.	.04	W	Metal			N Light		
8.	.07	↓	↓			S Vent		
9.	.10	↓	↓			W Grill		
5 0.	.07	↓	↓			S Door		
1.	.12	↓	↓			S Frame		
2.	-.08	GRN	Drywall		Rm 1377	N Wall		
3.	-.12	TAN	↓			E ↓		
4.	.02	BRN	Wood			W Floor		
5.	.01	↓	↓			W Wall		
6.	-.01	↓	↓			W Cabinet		
7.	-.02	↓	↓			W Counter Top		
8.	-.12	↓	↓			E Trim		
9.	.07	W	Metal			S Light		
6 0.	.11	↓	↓			N Vent		

Lead Powder

CDHP6409 20AB



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-17-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
6 1.	.01	W	Drywall	G	1st Floor - Area 2	N Wall		
2.	.02	↓	↓			W ↓		
3.	.04	Tan	Ceramic			S ↓		
4.	-.02	↓	↓			E ↓		
5.	.01	Gray	↓			W Base		
6.	.02	↓	↓			N Floor		
7.	.04	W	Metal			E Light		
8.	-.02	↓	Drywall			W Column		
9.	-.11	Brn	Wood			N Wall		
7 0.	.04	Tan	Metal			E Door		
1.	.08	↓	↓			E Frame		
2.	-.02	Grn	Drywall		Area 3 Rm 1403	N Wall		
3.	.01	Brn	↓			S ↓		
4.	.02	Tan	Metal			N Door		
5.	.07	↓	↓			N Frame		
6.	.02	↓	↓		Rm 1497	N Door		
7.	.08	↓	↓			N Frame		
8.	-.02	W	Drywall			N Wall		
9.	.01	↓	↓			E ↓		
8 0.	.10	Blk	Metal			W Window		
1.	.04	W	↓			S Light		
2.	.05	↓	↓			E Vent		
3.	.02	↓	↓			N Grill		
4.	-.02	↓	Ceramic		Rm 1009	N Wall		
5.	.02	Gray	↓			N ↓		
6.	.01	R	↓			N ↓		
7.	.04	Gray	↓			N Floor		
8.	.02	W	Porcelain			W Sink		
9.	-.02	↓	↓			E Toilet		
9 0.	.01	↓	↓			E Urinal		

Lead Powder

CDHP6409 3 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-17-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
91.	-.02	W	Drywall	NG	1st Floor - Area 3 - Rm 1035 N	Wall		
2.	.04					E		
3.	.52		Ceramic			W		
4.	.02		Wood			S	Door	
5.	.04		Metal			S	Frame	
6.	.67		Wood			W	Window Frame	
7.	-.01		Metal			E	Light	
8.	-.04					W	Vent	
9.	.02					S	Guilt	
100.	.01		Ceramic		Corridor	S	Floor	
1.	-.02	Blue				S		
2.	.02	Gray				S		
3.	.01	Tan	Drywall		Rm 1525 N	Wall		
4.	.04					W		
5.	-.01		Wood			E	Door	
6.	.07		Metal			E	Frame	
7.	.02	W	Drywall			N	Ceiling	
8.	-.08	Grn			Rm 1510	N	Wall	
9.	-.10					W		
110.	.01	Brn	Wood			N	Floor	
1.	-.02	W				S	Door	
2.	.07		Metal			S	Frame	
3.	-.09	Brn	Wood			N	Cabinet	
4.	-.11					N	Counter Top	
5.	.01	Tan	Drywall		Rm 1589 N	Wall		
6.	.04					E		
7.	.02	Brn	Wood			S	Floor	
8.	.07	Tan				W	Door	
9.	.10		Metal			W	Frame	
120.	.12	BLK	Metal			S	Window Frame	

Larry Ponder

CDHP6409 4 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <i>Veterans Admin SA</i>	ADDRESS: <i>3350 La Jolla Village Dr.</i>
SCOPE OF PROJECT: <i>Hospital</i>	DATE: <i>12-17-14</i>
CONTACT: <i>Tammy Brent</i>	PHONE: <i>858-642-3920</i>
PROJECT NUMBER: <i>P14320.U11</i>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM.
121.	.01	Grn	Drywall	G	1st Floor - Area 4 - Rm 1493	WALL		
2.	-.01	↓	↓			W ↓		
3.	.03	Silver	Metal			W Door		
4.	.07	↓	↓			W Frame		
5.	.02	W				N Light		
6.	.08	↓	↓			E Vent		
7.	.10	↓	↓			W Grill		
8.	-.12	Brown	Wood			E Cabinet		
9.	-.08	↓	↓			↓ E Counter Top		
130.	.01	Blue	Drywall		Rm 1449	WALL		
1.	.02	↓	↓			S ↓		
2.	-.02	Blk	Wood			S Cabinet		
3.	-.01	↓	↓			S Counter Top		
4.	.07	Tan	↓			S Door		
5.	.10	↓	Metal			S Frame		
6.	.08	R	Drywall			↓ E Wall		
7.	.01	W	↓		Rm 1459	N ↓		
8.	.02	↓	↓			E ↓		
9.	.04	Tan	Wood			S Door		
140.	.08	↓	Metal			S Frame		
1.	.01	W	↓			N Light		
2.	.03	↓	↓			E Vent		
3.	.07	↓	↓			↓ W Grill		
4.	-.01	↓	Drywall		Rm 1456	N WALL		
5.	-.02	↓	↓			S ↓		
6.	.04	Tan	Wood			S Door		
7.	.08	↓	Metal			S Frame		
8.	.27	W	Porcelain			S Sink		
9.	-.07	Gray	Wood			W Cabinet		
150.	-.01	↓	↓	↓	↓	↓ W Counter Top		

*Larry Ponder*

CDHP6409 5 OF 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>Hospital</u>	DATE: <u>12-17-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
151.	.02	W	Drywall	G	1 <sup>ST</sup> Floor - Area 5 - An 1152 N	Wall		
2.	.01	↓	↓	↓		E ↓		
3.	-.02	Brn	Wood			E Trim		
4.	.02	Tan	↓			N Door		
5.	.08	↓	Metal			↓ N Frame		
6.	-.01	W	Drywall		Rm 1279 N	Wall		
7.	-.02	↓	↓			W ↓		
8.	.07	↓	Metal			E Light		
9.	.02	↓	↓			↓ S Vent		
160.	-.01	Brn	Ceramic		Rm 1271 N	Wall		
1.	.02	Tan	↓			N ↓		
2.	.03	W	Drywall			N ↓		
3.	.01	↓	↓			N Ceiling		
4.	.07	Tan	Ceramic			N Floor		
5.	.01	W	Porcelain			W Sink		
6.	.02	↓	↓			W Toilet		
7.	-.02	↓	↓			↓ W Urinal		
8.	-.27	Pink	Wood			↓ W Counter Top		
9.	.01	Tan	Drywall		Rm 1250 N	Wall		
170.	.10	↓	↓			N Ceiling		
1.	.02	W	Porcelain			E Sink		
2.	.04	↓	↓			↓ E Toilet		
3.	.01	↓	Drywall		Rm 1160 N	Wall		
4.	-.02	↓	Wood			E Cabinet		
5.	-.04	↓	↓			E Counter Top		
6.	.08	Tan	↓			W Door		
7.	.10	↓	Metal			N Frame		
8.	.11	W	↓			E Vent		
9.	1.00	R	Wood		Confirmation	Test Block		
180.	1.04	↓	↓	↓	↓	↓		

Low Ponder

CDHP6409 6 of 6

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <i>Veterans Admin SA</i>	ADDRESS: <i>3350 La Jolla Village Dr.</i>
SCOPE OF PROJECT: <i>U.A. Hospital</i>	DATE: <i>12-18-14</i>
CONTACT: <i>Tammy Brent</i>	PHONE: <i>858-642-3920</i>
PROJECT NUMBER: <i>P14320.U11</i>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
1.	1.02	R	wood	G	confirmation	Test Block		
2.	1.10	↓	↓	↓	↓	↓		
3.	.97	↓	↓	↓	↓	↓		
4.	-.12	Orn	Drywall		6th Floor - Area 3	N Wall		
5.	-.02	Blue	↓			E		
6.	-.11	W	↓			S		
7.	.01	Tan	↓			W		
8.	.02	↓	Metal			E Door		
9.	.01	↓	↓			E Frame		
10.	.01	↓	↓			W Door		
1.	-.01	↓	↓			W Frame		
2.	-.02	↓	↓			S Door		
3.	.02	↓	↓			S Frame		
4.	.01	↓	↓			N Door		
5.	-.04	↓	↓			N Frame		
6.	.12	↓	Drywall		Rm 6101	N Wall		
7.	.07	↓	↓			E		
8.	.10	↓	↓			S		
9.	.02	↓	↓			W		
20.	.03	W	Metal			S Light		
1.	.07	↓	↓			E <del>Frame</del> Vent		
2.	.02	↓	↓			W Grill		
3.	.10	BK	↓			N Window Frame		
4.	.02	BK	↓			E Door		
5.	.01	↓	↓			E Frame		
6.	.12	↓	↓			E Window Frame		
7.	.15	↓	↓			S		
8.	-.02	Silver	↓			N Freezer		
9.	-.04	↓	↓			N Frame		
30.	.01	↓	↓			N Door		

*Lead Powder*

*CDHP6409 1045*

# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>U.S. Hospital</u>	DATE: <u>12-18-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	Radiology	COMPONENT	QUANTITY	COMM
* 31.	4.01	Tan	Drywall	G	1 <sup>ST</sup> Floor - Area 5 - Rm 1309	N Wall		20,000	12-14
* 2.	4.25	↓	↓			1294	↓	↓	
* 3.	2.20	↓	↓			1301	↓	↓	
* 4.	4.12	↓	↓			1806	↓	↓	
* 5.	4.08	↓	↓			1324	↓	↓	
* 6.	3.75	↓	↓			↓ 1841	↓	↓	
* 7.	18.04	↓	Metal			Rm 1309W	Door	6 Ea	
* 8.	.47	↓	↓			W	Frame		
↓ 9.	.07	W	Porcelain			N	Sink		
4 0.	.02	↓	↓			N	Toilet		
1.	.08	↓	Metal			E	Light		
2.	.10	↓	↓			W	Vent		
3.	.04	↓	↓			S	Grill		
4.	.09	Tan	Wood			E	Window Frame		
5.	.02	W	Metal			S	Speaker		
6.	-.04	W	Wood			↓ N	Cabinet		
* 7.	4.07	Tan	Drywall		Corridor	E	Corridor	3,000	
* 8.	4.52	↓	↓			W	↓	↓	
* 9.	3.12	↓	↓			N	↓	↓	
* 5 0.	5.02	↓	↓			S	↓	↓	
1.	.08	W	Metal			E	Fire 130x		
2.	.02	↓	↓			N	Light		
3.	.01	↓	↓			E	Vent		
4.	.10	↓	↓			S	T-Grill		
5.	-.01	Tan	Wood			W	Bumper Guard		
6.	.04	↓	↓			N	Door		
7.	.10	↓	Metal			N	Frame		
8.	.02	↓	Wood			E	Door		
↓ 9.	.12	↓	Metal			E	Frame		
6 0.	.15	Silver	Metal			W	Bumper Guard		

Lead Powder

CDHP 6409 2 of 5



# ENCORP LEAD BASED PAINT INSPECTION WORKSHEET

CLIENT: <u>Veterans Admin SA</u>	ADDRESS: <u>3350 La Jolla Village Dr.</u>
SCOPE OF PROJECT: <u>U.A. Hospital</u>	DATE: <u>12-18-14</u>
CONTACT: <u>Tammy Brent</u>	PHONE: <u>858-642-3920</u>
PROJECT NUMBER: <u>P14320.U11</u>	

SAMPLE NUMBER	K-SHELL READING	PAINT COLOR	SUBSTRATE	COND	LOCATION	COMPONENT	QUANTITY	COMM
61.	.15	BRN	Ceramic	G	1ST Floor - Area 3 - Corridor E	Drinking Fountain Wall		
2.	.07	Tan	Organic			E Wall		
3.	.02	↓	↓			W ↓		
4.	.01	W	Metal			N Light		
5.	.08	↓	↓			S Vent		
6.	.10	↓	↓			N Grill		
7.	.02	Tan	Wood			E Door		
8.	.01	↓	Metal			E Frame		
9.	.01	↓	Wood			W Door		
70.	.02	↓	Metal			W Frame		
1.	.04	W	↓			E Fire Box		
2.	.02	BRN	Wood			W Bumper Guard		
3.	.04	Silver	Metal			W ↓		
4.	.10	↓	↓			E Hand Rail		
5.	<del>.01</del>	<del>Tan</del>	<del>Organic</del>		<del>Area 4 Corridor</del>	<del>W Wall</del>		
6.	<del>.01</del>	<del>↓</del>	<del>↓</del>			<del>S ↓</del>		
7.	<del>.</del>	<del>↓</del>	<del>Wood</del>			<del>N Door</del>		
8.	<del>.</del>	<del>↓</del>	<del>Metal</del>			<del>N Frame</del>		
9.	<del>.</del>	<del>↓</del>	<del>Wood</del>			<del>S Door</del>		
80.	<del>.</del>	<del>↓</del>	<del>Metal</del>			<del>S Frame</del>		
1.	<del>.</del>	<del>Blue</del>	<del>Organic</del>			<del>N Wall</del>		
2.	<del>.</del>	<del>BRN</del>	<del>Wood</del>			<del>S ↓</del>		
3.	<del>.</del>	<del>↓</del>	<del>↓</del>			<del>N Bumper Guard</del>		
4.	<del>.</del>	<del>Silver</del>	<del>Metal</del>			<del>S ↓</del>		
5.	<del>.</del>	<del>↓</del>	<del>↓</del>			<del>N ↓</del>		
6.	<del>.</del>	<del>↓</del>	<del>↓</del>			<del>N ↓</del>		
7.	<del>.</del>	<del>↓</del>	<del>↓</del>			<del>S Fire Box</del>		
8.	<del>.</del>	<del>↓</del>	<del>↓</del>			<del>S Frame</del>		
9.	<del>.</del>	<del>Tan</del>	<del>Ceramic</del>			<del>N Wall</del>		
90.	<del>.</del>	<del>↓</del>	<del>↓</del>			<del>S Floor</del>		

Larry Ponder

CDHP6409 3 of 5