

**RIVERSIDE DINING FACILITY BLDG. # 350 FLIGHT DISHWASHER
REPLACEMENT**

Abstract

Salient Characteristics for the purchase of Flight Dishwasher Unit

15 August 2023

Building 350 Flight Dishwasher Replacement


Flight Dishwasher replacement for Riverside Dining Facility building 350.

This requirement is for a unit that rinses, and sanitizes plates, silverware, trays, and other food utensils used daily at the dining facility. The current dishwasher (Hobart Model # FT1000SER) has reached the end of its life expectancy.

SALIENT CHARACTERISTIC

Request to replace the current dishwasher (Fig 1.) with comparable one

Fig 1. Current Dishwasher Unit Data Plate



Request Unit General Information

- Flight type dish machine
- Minimum 58 gallons of final rinse consumption per hour, with dual rinse
- Hinged & insulated doors
- Sliding wash arms without caps
- Auto Clean, Auto Delime
- Energy Recovery
- Automatic Soil Removal system (ASR),
- Minimum Standard warranty - 1-Year parts, labor.
- 2.5' Load Platform
- Drain in Unload

- Standard Non-Split 5' Center Joined (Wash/Dual Rinse)
- All chemicals must be non-proprietary
- Blower Dryer
- Electric Heat 480v/60/3-ph (HV)
- Service Connections
- Electric Booster
- Standard Piping
- Right to left operation the incoming cold-water line
- Conveyor

Install

- Installation and removal of existing Dishwasher.
- Requires machine assembly during normal business hours, with appropriate notice; Include assembly of this item, final electrical or plumbing.
- Uncrate new dishwasher, set in place, connect to existing electric, water and drains per factory specifications.
- include vent connection, move clean and soiled dish tables into place, install new disposer connecting to existing utilities, place, start up the dishwasher and make any adjustments, make ready for final use, remove debris.

