

Pictures for 554-23-109 Install New Jackets on Valves and Traps



Figure 1: PRV Station 6-PRV-1



Figure 2: PRV Station 6-PRV-2





*Figure 3: Steam Header Left Side*



Figure 4: Steam Header Right Side






*Figure 5: Boiler Blowdown Valves*



*Figure 6: Boiler Flanged Port and Hand Access Port*



*Figure 7: Boiler Rear Sight Glass Port*





*Figure 8: Boiler Discharge Valves and Startup Bypass*





*Figure 9: Boiler Top Access Port*



Figure 10: 6-DHX-3 Control Valves and Trap





*Figure 11: 6-DHX-3 Steam Isolation Gate Valve and Y-Strainer*



Figure 12: 6-DHX-2 Steam Isolation Gate Valve and Y-Strainer





Figure 13: 6-DHX-2 Control Valves and Trap



Figure 14: 6-DHX-1 Steam Isolation Gate Valve and Y-Strainer





Figure 15: 6-DHX-1 Control Valves and Trap



Figure 16: 6-DHX-1 Drip Leg Trap





Figure 17: 6-DHX-2 Drip Leg Trap



*Figure 18: 6-DHX-3 Drip Leg Trap*





Figure 19: 6-DHX-3 Water Heater Trap and Y-strainer



Figure 20: 6-DHX-2 Water Heater Trap and Y-Strainer





*Figure 21: 6-DHX-1 Water Heater Trap and Y-strainer*