

Performance Work Statement

1. Description of Services

1.1 Provide assets as outlined. Here to the purchaser is known as the 341st Missile Wing (US Government) and the contractor providing service is known as the seller.

2. PROVIDE AND REPLACE A LIFT CYLINDER ON A TEREX CRANE. REGISTRATION NUMBER 18D00275.

2.1 AT A MINIMUM: THE LIFT CYLINDER MUST BE REPLACED DUE TO FAILURE TO MEET SUSTAINABLE SPECIFICATIONS. THE CYLINDER MUST BE AN EXACT REPLACEMENT OR EQUIVALENT DUE TO CRITICAL SAFETY NATURE OF OPERATION. THE CURRENT INSTALLED PART IS TEREX PART NUMBER T117684.

3. PROVIDE A TWO-YEAR WARRANTY.

4. Shipping and handling to destination and installation labor must be included in final price.

5. Prior to acceptance, the product will be inspected by a representative from 341 Missile Wing Logistics Readiness Squadron Vehicle Maintenance.