

Photographs

These photographs represent possible conditions at the culvert locations. Some culverts ends will be cleaned while some receive additional repair. List of requirements is tabled in the PWS. These photographs do not include all 11 culverts and are provided as a sample of condition.



Figure 1



Figure 2



Figure 3



Figure 4



Figure 5



Figure 6



Figure 7



Figure 8



Figure 9



Figure 10



Figure 11