

## STATEMENT OF WORK

Statement of Work: Repair 2018 Blue Bird Reg Number 18B00253

Work Order: 2023011700008

Date: 20 April 2023

Project Manager: SSgt Nevins, 552-4583

### I. Summary

Repair 2018 Blue Bird Reg Number 18B00253 in accordance with manufacturer's recommendations and specifications to return this vehicle to original operational condition. Work must include: Repair left center lower panel and inner supports between front and rear tires, repair compartment door and frame containing aux heater, repair or replace frame lower rub rail, repair right rear upper corner behind the last latch window, repair or replace right rear vent panel and panel behind it.

1. Procurement of all parts and accessories required to repair this 2018 Blue Bird.
2. Provide all labor required to inspect, diagnose and repair this vehicle.
3. Perform operational checks to ensure proper function and reliability as per manufacturer's design.

### II. Drawings, Attachments, References and Enclosures:

1. A1 Auto Body Quote
2. Alaska Industrial Paint Quote
3. Bob's Services Quote

### III. Submittals: N/A

### IV. Products:

All materials and products provided by the contractor in the performance of this contract shall be in accordance with Manufacturers Specifications.

### V. Quality Control:

The Contractor shall be responsible for all quality control and all inspection and test that are required unless otherwise specified, arrange for factory tests and inspections when they are required.

1. The contractor shall perform all work according to accepted Industry Standards, Safety Procedures and Manufacturers Specifications.
2. The contractor shall schedule work to cause the least amount of interference with station operations.
3. The contractor is responsible for any damage to the work area or adjacent areas due to negligence and will immediately repair at the contractors own expense.
4. The Contractor shall perform field tests and provide labor, equipment, and incidentals required for testing. Also, the Contractor shall be able to produce evidence, when required, that each item of work has been constructed properly in accordance with the drawings, specifications, and product manufacturers' instructions.
5. Work shall be performed by licensed personnel. Note: Required certification/license to be made available when requested. At the conclusion of the project, required certification shall be performed by Licensed Personnel to test and verify for proper operation.

### VI. Execution:

Scope of Work: Repair (2018 Blue Bird Reg Number 18B00253 in accordance with manufacturer's recommendations and specifications to return this vehicle to original operational condition. Work must include: Repair left center lower panel, repair compartment door frame, repair dog legs 2 and 3, repair lower rub rail, repair right rear corner, refinish rear panel

1. Period of Performance: Return 2018 Blue Bird Reg Number 18B00253 within 30-45 days of receipt of the vehicle.

VII. Environmental & Safety:

1. The contractor shall perform all work according to accepted Industry Standards, Safety Procedures and Manufacturers Specifications.
2. Ensure all workers are wearing the proper PPE for the assigned task.
3. The contractor will dispose of all hazardous waste per local, state, and federal regulations.
4. Known Encountered Waste Summary: none

VIII. Testing: N/A