

Address  
City, State Zip  
Phone#

## Special Hazards Inspection Report

Customer: VA - Lake Nona - Superstructure Room 4K307B  
Inspector: Warren H. Shipley

Date of Service: 3/26/21  
SR#: 48545126  
Task#: 75891089

### 12. Cylinder Inspection

| #  | Cylinder type | Cylinder Mfr. | Serial Number | Last Test Date | Stamped Wt. (A) | Total Wt. (B) | Cylinder Fill / Capacity (A-B) | Cylinder Pressure | Condition | Liquid Level Indicator | Temperature | Last 5 Yr. External Inspection Date | Rack # |
|----|---------------|---------------|---------------|----------------|-----------------|---------------|--------------------------------|-------------------|-----------|------------------------|-------------|-------------------------------------|--------|
| 1  | 4BW450        | FIKE          | 1257395       | 10/21/2019     | 783             | 373           | 410                            | 390               | GOOD      | 19"                    | 72          | 1/21/2020                           |        |
| 2  | 4BW450        | FIKE          | 1464516       | 10/21/2019     | 153             | 77            | 76                             | 377               | GOOD      | 14"                    | 72          | 1/21/2020                           |        |
| 3  |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 4  |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 5  |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 6  |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 7  |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 8  |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 9  |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 10 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 11 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 12 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 13 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 14 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 15 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 16 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 17 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 18 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 19 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |
| 20 |               |               |               |                |                 |               |                                |                   |           |                        |             |                                     |        |

#### Cylinder Inspection Comments:

### 13. List Changes in Occupancy, Hazard, or Fire Protection System in Section 2:

#### 14. Deficiencies and Recommendations:

Panel 'Trouble' bell does not have a sign, Pull station by main entrance is missing the label 'suppression release'  
see attached photos.

#### 15. Deficiencies and Recommendations were discussed with Customer / Customer Representative:

☒ Yes ☐ No ☐ N/A

If No, explain:

**IMPORTANT NOTICE TO CUSTOMER:** Customer acknowledges and agrees that, in the absence of a Service Agreement between parties, services hereunder are performed pursuant to the terms and conditions on the reverse side of this Inspection Report. Customer further agrees that the services have been completed to Customer's satisfaction and that the system is in good working order and repair, unless services performed were of a temporary nature, in which case Customer acknowledges that part of customer's system may have been bypassed or is otherwise inoperable until services can be completed. **CUSTOMER'S ATTENTION IS DIRECTED TO THE LIMITATION OF LIABILITY, WARRANTY, INDEMNITY AND OTHER CONDITIONS ON THE REVERSE SIDE.**

#### Acceptance of customer or customer's representative

| Signature:  | Date:     |
|---|-----------|
| emailed to Scott.Reed@va.gov, Dalton.Allison@va.gov | 3/26/2021 |
| Print Name:   |           |
| Scott Reed, Dalton Allison                          |           |

| Inspector Signature:     | Date:     |
|--------------------------|-----------|
| <i>Warren H. Shipley</i> | 3/26/2021 |
| Inspector Name (Print):  |           |
| Warren H. Shipley        |           |