


Date 11/03/87

Shore Facility FAST Report

Page 1

Host Unit Name	Host Unit ID	RPFN	Facility Name	Fac Type	Area	Physical Adequacy	Functional Adequacy	Adequacy Date
FORTESQUE SARDET	30001	LLL	LAND (LEASED)	L		71	60	10/09/87
		MR1	RETAINING WALL	S		80	90	10/09/87
		MU1	BOAT BASIN	S		80	80	10/09/87
		OM1	STA BLDG	B	1344	78	76	10/09/87
		SM1	WOODEN BLKHD BEHIND STEEL BLKHD	S		80	55	10/09/87
		SQ1	FINGER PIER	S		74	75	10/09/87
		SQ2	FINGER PIER	S		74	75	10/09/87
		SS1	FLOATING DOCK	S		72	70	10/09/87
		TF1	FLAGPOLE	S		90	90	10/09/87
		TS1	VHF TOWER	S		80	70	10/09/87
		TS2	HIGH LEVEL TOWER	S		90	90	10/09/87
		UP1	DIESEL TANK-AG-BOATS-500 GAL	S		80	80	10/09/87
		UP2	WASTE OIL TANK-200 GAL	S		80	90	10/09/87



ENCL (2)

24x56 1344

HAVING TROUBLES ENTERING IN CEDS