

# ATTACHMENT 1

## TASK LIST

Below is a list of asbestos lagging sites that would have to be removed from the radiological spaces. List is NOT all inclusive nor is it guaranteed to be accurate. All values are estimates only. All removed material to be disposed of according to Federal, State, or Local Laws.

SITE #	SITE TYPE	PIPE SIZE (Inches)	LAGGING THICKNESS (Inches)	AMOUNT OF LAGGING
1	Pipe	2	0.5	1 ft.
2	Pipe	1	1.5	3 ft.
3	Pipe	1	1.5	1 ft.
4	Pipe	1	1.5	6 ft.
5	Pipe	1	1.5	1.5 ft.
6	Pipe	1	1.5	1.5 ft.
7	Pipe	0.5	1.5	3 ft.
8	Pipe	1	1.5	6 ft.
9	Pipe	1	1.5	11 ft.
10	Pipe	1	1.5	7 ft.
11	Pipe	1	1.5	7 ft.
12	Pipe	1	1.5	6 ft.
13	Large Component	N/A	Various (3 - 18)	(150 EA Pads) 50 ft <sup>3</sup>
14	Pipe	3	0.5	1 ft.
15	Pipe	1	1.5	1 ft.
16	Pipe	0.5	1.5	1 ft.
17	Pipe	14	3	1 ft.
18	Pipe	2	3	0.5 ft.
19	Pipe	1	1.5	1 ft.
20	Pipe	0.5	1.5	1 ft.
21	Pipe	14	3	1 ft.
22	Pipe	2	1.5	1 ft.
23	Large Component	N/A	3	2 ft <sup>2</sup>
24	Large Component	N/A	3	2 ft <sup>2</sup>
25	Pipe	14	3	2 ft.
26	Pipe	14	3	2 ft.
27	Pipe	9.5	1.5	2 ft.
28	Pipe	14	3	1 ft.
29	Valve	1	1.5	1 ft.
30	Valve	1	1.5	1 ft.
31	Pipe	5	3	2 ft.
32	Pipe	5	3	3 ft.
33	Pipe	1	1.5	1.5 ft.
34	Pipe	5	3	4 ft.
35	Valve	1	0.5	2 ft.
36	Pipe	1	0.5	2 ft.
37	Valve	1	0.5	2 ft.
38	Pipe	1	1	28 ft

ATTACHMENT 1  
TASK LIST